
AD-A148 514	INSTALLA SEARCH W CHESTER	TION REST	ORATION VE AIR.	PROGRAI	M PHRS	E I: R	ECORDS INC I	S NEST	1/	3
UNCLASSIFIED	CHESTER	PH 01 NU	V 84 HF-	938H F	98637-	83-0-6	F/G 6	76	NL	
ŝ										
		;								
	·								d <sub>a</sub>	
	1 De									
									./s.	



MICROCOPY RESOLUTION TEST CHART
MATIONAL BUREAU OF STANDARDS - 1963 - A



INSTALLATION RESTORATION PROGRAM
PHASE I: RECORDS SEARCH
WILLOW GROVE AIR RESERVE FACILITY
WILLOW GROVE, PENNSYLVANIA

Prepared For:

UNITED STATES AIR FORCE RESERVE ROBINS AFB, GEORGIA 31098

NOVEMBER 1984

By:

Roy F. Weston, Inc. Weston Way West Chester, Pennsylvania 19380 DTIC ELECTE DEC 7 1984

D

DISTRIBUTION STATEMENT

Approved for public releases
Distribution Unlimited

84 11 28 016

DTIE FILE COPY

AD-A148 514

#### **PROPRIETARY NOTICE**

This report has been prepared for the U.S. Air Force by Roy F. Weston, Inc. for the purpose of aiding in the implementation of Air Force Installation Restoration Program. It is not an endorsement of any product. The views expressed herein are those of the contractor and do not necessarily reflect the official views of the publishing agency, the United States Air Force or the Department of Defense.

Copies of this report may be purchased from:

National Technical Information Service 5285 Port Royal Road Springfield, Virginia 22161

Federal Government agencies and their contractors registered with Defense Technical Information Center should direct requests for copies of this report to:

Defense Technical Information Center Cameron Station Alexandria, Virginia 22314



#### DEPARTMENT OF THE AIR FORCE HEADQUARTERS AIR FORCE RESERVE ROBINS AIR FORCE BASE, GEORGIA 31098

2 1 NOV 1984

REPLY TO ATTN OF:

DEPV (Mr Garrett/5755)

SUBJECT: Installation Restoration Program (IRP) Phase I Final Report for Willow Grove ARF PA

TO: See Distribution

The attached report is forwarded for your information/action. This report is the initial phase of an Air Force program to identify and fully evaluate problems associated with past hazardous material disposal and spill sites on Air Force facilities, to control the migration of hazardous contamination from such facilities, and to control hazards to the health and welfare that may have resulted from past operations.

FOR THE COMMANDER

JERROLD F. SMITH

Acting DCS/Engineering and Services

1 Atch
Phase I IRP Report, Willow Grove

ARF, PA

Distribution:	No Cys
913 TAG/CC	1
913 TAG/DE	15
HQ USAF/LEEV	wo Atch
SAF/MIQ	wo Atch
SAF/LLP	wo Atch
AFRCE-ER/ROV	5
HQ AFESC/DEV	wo Atch
HQ USAF/SGES	wo Atch
USAF OEHL/TS	2
USAF OEHL/CVT	1
14 AF/DE	1
HQ AFMSC/SGP	1
ANGSC/DEV Stop 18	1
HQ USAF/REX	1
HQ USAF/LEER	1
439 TAW/CC	1
US Dept of Commerce	1
Nat'l Technical Information Co	:T
5285 Port Royal Road	
Springfield VA 22161	

Defense Technical Information Ctr Cameron Station Alexandria VA 22314

SECURITY CLASSIF	ICATION OF TH	IS PAGE						
			REPORT DOCUM	ENTATION PAGE	E			
IN REPORT SECU		ATION		1b. RESTRICTIVE MARKINGS NONE				
20. SECURITY CLA	SSIFICATION A	UTHORITY		3. DISTRIBUTION/AVAILABILITY OF REPORT				
26. DECLASSIFICA	TION/DOWNGR	ADING SCHE	DULE	UNCLASSIFIED	/UNLIMITED	)		
4. PERFORMING C	RGANIZATION	REPORT NUM	BER(S)	5. MONITORING OR	GANIZATION R	EPORT NUMBER	(S)	
				AF-058A				
6. NAME OF PERI		NIZATION	6b. OFFICE SYMBOL (If applicable)	7a. NAME OF MONIT	-	IZATION		
6c. ADDRESS (City 1 Weston Wa West Cheste	y		<del> </del>	7b. ADDRESS (City, S Tyndall AFB		de)		
MANE OF FUN ORGANIZATION HQ A1r Ford	N	NG	8b. OFFICE SYMBOL (If applicable) DEPV	9. PROCUREMENT J		ENTIFICATION P	NUMBER	
8c. ADDRESS (City	<del></del>		I	10. SOURCE OF FUN	IDING NOS.			
Robins AFB	GA 31098-6	001		PROGRAM ELEMENT NO.	PROJECT NO.	TASK NO.	WORK UNIT	
11. TITLE (Include	Security Classifice	ition)						
12 PERSONAL AU Phase I, Re	THOR(S)	ch Willow	Grove ARF PA					
134 TYPE OF REP	ORT	136 TIME C	04/01 <sub>to</sub> 84/11/0	0 14. DATE OF REPORT (Yr., Mo., Day) 15. PAGE COUNT				
16. SUPPLEMENTA	RY NOTATION							
17. C	OSATI CODES		18. SUBJECT TERMS (C	Continue on reverse if ne	cessary and ident	ify by block numb	eri	
FIELD GRO	UP SI	B. GR.	]					
			<u> </u>					
A Phase I Willow Growere reviewere condupast waste Assessment all seven	Initial ass we ARF, Per wed, regula cted. Past and spill Rating Mer sites.	essment unsylvania itory ager waste he sites wer chodology		lation Restorations and group osal practices. Seven sites we improve the monitoring properties of the second seven	s were inte und and aer s were eval ere assesse programs we	erviewed, re rial reconna- luated, and ed using the ere recommen	ecords aissance seven e Hazard	
UNCLASSIFIED/U			TIC USERS .	UNCLASSIFIE		22c. OFFICE SY	MROL	
LARRY S.		VIDUAL		Include Area Co	de)	HO AFRE		

DD AURM 1475, 83 APR

11 28 016

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS P'

#### TABLE OF CONTENTS

Section	•	Title	Page
	EXEC	UTIVE SUMMARY	ES-1
1	INTR	ODUCTION	1-1
	1.1	Background and Authority	1-2
	1.2	Purpose and Scope of the	
		Assessment	1-2
	1.3	Methodology	1-4
2	INST	ALLATION DESCRIPTION	2-1
	2.1	Location, Size and Boundaries	2-1
	2.2	History	2-3
		2.2.1 913th Tactical Air Group	2-3
		2.2.2 111th Pa Air National Guard	2-5
	2.3	Organization and Mission	2-6
		2.3.1 913th Tactical Airlift Group	2-6
		2.3.2 111th Pa Air National Guard	2-8
3 ( 0418	ENVI	RONMENTAL SETTING	3-1
ing	3.1	Meteorology	3-1
Accession For	3.2	Geography	3-3
NTIS GRAMI		3.2.1 Topography	3-3
Unanneunced		3.2.2 Soils	3-3
Justification	3.3	Surface Water Resources	3-6
Ву		3.3.1 Surface Drainage	3-6
Distribution/		3.3.2 Surface Water Quality	3-8
Availability Codes  Avail and/or		3.3.3 Surface Water Use	3-12
Nail and/or Dist Special			



#### TABLE OF CONTENTS

(Con't)

Section		<u>Title</u>	Page
	3.4	Groundwater Resources	3-13
		3.4.1 Background Geology	3-13
		3.4.2 Hydrogeologic Units	3-14
		3.4.3 Groundwater Quality	3-20
		3.4.4 Groundwater Use	3-28
	3.5	Biotic Environment	3-34
	3.6	Sensitive Environmental Features	3-35
	3.7	Summary of Environmental Conditions	3-36
4	FIND	DINGS	4-1
	4.1	Introduction	4-1
	4.2	913th Tactical Air Group	4-1
·		4.2.1 Overview of Industrial	
		Operations	4-1
		4.2.2 Hazardous Waste Generation	
		and Management	4-5
	4.3	lllth Pa Air National Guard	4-13
	4.4	Fuels Management	4-13
		4.4.1 POL Fuel Area	4-13
		4.4.2 Fuel Spills	4-22
	4.5	Industrial Waste Control - Sanitary	
		Sewer and Storm Sewer Systems	4-25
	4.6	Site Findings	4-28
		4.6.1 POL Area - Site No. 1	4-28
		4.6.2 Open Storage Area #42 -	
		Site No. 2	4-32



## TABLE OF CONTENTS (Con't)

Section			Title	Page	
		4.6.3	Ponding Basin - Site No. 3	4-34	
		4.6.4	Washrack Area - Site No. 4	4-35	
		4.6.5	Building #330 Waste Oil		
			Storage Area - Site No. 5	4-37	
		4.6.6	Heating Plant - Site No. 6	4-38	
		4.6.7	Old Well House - Site No. 7	4-39	
5	CONC	LUSIONS	<b>3</b>	5-1	
	5.1	Introd	luction	5-1	
	5.2	POL Area - Site No. 1			
	5.3	Open Waste Storage Area #42 -			
		Site No. 2			
	5.4	Ponding Basin - Site No. 3			
	5.5	Washra	nck - Site No. 4	5-5	
	5.6	Buildi	ing #330 Waste Oil Storage		
		Area -	- Site No. 5	5-6	
	5.7	Heatin	ng Plant - Site No. 6	5-6	
	5.8	Old We	ell House - Site No. 7	5-7	
6	RECO	MMENDAT	TIONS	6-1	
	6.1	Introd	luction	6-1	
	6.2	POL Ar	rea - Site No. l	6-1	
	6.3	Open S	Storage Area #42 - Site No. 2	6-3	
	6.4	Pondir	or Ragin - Site No. 3	6-6	



## TABLE OF CONTENTS (Con't)

Section	Title				
	6.5 Washrack Area - Site No. 4	6-8			
	6.6 Building #330 Waste Oil Storage -				
	Site No. 5	6-9			
	6.7 Heating Plant - Site No. 6	6-9			
	6.8 Old Well House - Site No. 7	6-10			
	6.9 General Confirmation Recommendations	6-10			
	6.9.1 Soil Borings and Well				
	Installations	6-10			
	6.9.2 Analytical Parameters	6-11			
Appendix					
A	Resumes of the WESTON Team	A-1			
В	List of Interviewees	B <b>~1</b>			
С	List of Outside Agencies	C-1			
D	Hazard Assessment Rating Methodology	D-1			
E	Site Harm Score Calculations	E-1			
F	Photographs	F-1			
G	Glossary of Terms and Abbreviations	G-1			
Ħ	References	H-1			



### LIST OF FIGURES

Figure No.	<u>Title</u>	Page
ES-1	Location of Sites Recommended for Confirmation	ES-5
1-1	Decision Tree	1-6
2-1	Location of Willow Grove ARF	2-2
2-2	Facility Locations at Willow Grove ARF	2-4
3-1	Soils Conditions at Willow Grove ARF	3-4
3-2	Surface Drainage	3-7
3-3	Flood-Prone Area	3-9
3-4	Geological Map of Stockton Formations	3-15
3-5	Bedrock Surface Elevations	3-17
3–6	Water Table Map	3-21
3-7	Location of Water Supply Wells	3-30
4-1	Major Buildings and Facilities-913th TAG	4-3
4-2	Hazardous Waste Accumulation Points and Storage Locations at 913th TAG	4-6
4-3	Hazardous Waste Management at Willow	4~7



# LIST OF FIGURES (Con't)

Figure No.	<u>Title</u>	Page
4-4	Major Buildings and Facilities-lllth PaANG	4-14
4-5	Location of Fuel Storage and Waste Oil Tanks at Willow Grove ARF	4-20
4-6	Sanitary Sewer System	4-27
4-7	Location of Sites Recommended for Confirmation	4-29
6-1	Monitoring Well Profile	6-5



#### LIST OF TABLES

Table No.	<u>Title</u>	Page
ES-1	Summary of Waste Types and HARM Scores	
	for Confirmation Sites	ES-6
ES-2	Recommended Phase II Sampling Program	ES-8
3-1	Climatic Conditions at Willow Grove ARF	3-
3-2	Soils at Willow Grove ARF	<b>~5</b>
3-3	Chemical Analysis of Water from Little	
	Neshaminy Creek at Neshaminy	3-10
3-4	Statistical Summary of Background Ground-	
	water Quality - Stockton Formation	3-22
3-5	Maximum Reported Concentrations of	
	Volatile Organic Compounds in Groundwater	3-24
3-6	Ranges of TCE and PCE Concentrations	
	in Willow Grove Naval Air Station	
	Supply Wells	3-25
3-7	Inorganic Parameter Concentrations in	
	Willow Grove Air Station Supply Wells	3-29
3-8	Supply Well Specifications - Willow	
	Grove Newsl Bir Station	3-31



# LIST OF TABLES (Con't)

Table No.	Title	Page
3-9	Groundwater Pumpage in 1980 by Public Water Suppliers and Government Facilities	3-33
4-1	Hazardous Material/Waste Generation ~ 913th TAG	4-9
4-2	Shop-by-Shop Hazardous Materials/Wastes Generation - 913th TAG	4-10
4-3	Hazardous Material/Waste Generation - lllth PaANG	4-15
4-4	Shop-By-Shop Hazardous Materials/Wastes Generation - lllth PaANG	4-16
4-5	Fuel Storage Tanks at Willow Grove ARF	4-19
4-6	Summary of Small Quantity Fuel Spill Responses	4-23
5-1	Summary of Waste Types and HARM Scores for Confirmation Sites at Willow Grove ARF	5-2
6-1	Recommended Phase II Sampling Program	6-2
6-2	Minimum Well Construction Requirements	6-4
6-3	Recommended List of Analytical Parameters for Selected Sites at Willow Grove ARF	6-7



#### EXECUTIVE SUMMARY

The Department of Defense (DoD) has developed a program to identify and evaluate past hazardous material disposal sites on DoD property, to control the migration of hazardous contaminants, and to control hazards to health or welfare that may result from these past disposal operations. This program is called the Installation Restoration Program (IRP). The IRP has four phases consisting of Phase I, Initial Assessment/Records Search; Phase II, Confirmation and Quantification; Phase III, Technology Base Development/Evaluation of Remedial Alternatives; and Phase IV, Operations/Remedial Actions. Roy F. Weston, Inc. was retained by the United States Air Force to conduct the Phase I, Initial Assessment/Records Search for Willow Grove Air Reserve Facility under Contract No. F08637-83-G0009.

### - See #1673 (pont)

#### INSTALLATION DESCRIPTION

The Willow Grove Air Reserve Facility (ARF) is located approximately 23 miles north of Philadelphia, Pennsylvania in southeastern Montgomery County. The ARF is located adjacent to and northeast of the Willow Grove Naval Air Station.

The ARF consists of about 162 acres and is occupied by the 913th Tactical Air Group. A portion of the facility is leased to the 111th Pennsylvania Air National Guard.

At the present time, there are 964 personnel attached to the 913th TAG, most of which are part-time Air Reservists. The 111th PaANG has about 830 personnel assigned, most of which are part-time Air National Guardsmen.



#### ENVIRONMENTAL SETTING

The surrounding land use at Willow Grove ARF has been described as "urban sprawl", radiating out from Philadelphia. The land west and north of the base is relatively open agricultural land, and scattered industrial and residential development and golf courses. The areas to the north are environmentally sensitive and zoned low density residential, and are expected to remain largely vacant due to lack of utility service. The areas south and east of the Air Reserve Facility are densely developed for residential, industrial and commercial uses.

The following environmental conditions are of particular importance in the evaluation of past hazardous waste disposal practices at Willow Grove ARF:

- 1. The mean annual precipitation is 41 inches, the net precipitation is 18 inches and the one-year, 24-hour rainfall event is estimated to be 2.7 inches. These data indicate there is moderate to high potential for infiltration into the surface soils on the base, and that there is moderate to high potential for runoff and erosion.
- 2. The natural soils on the base are loams and silt loams. Soil permeabilities range from 0.2 to 6.3 inches per hour, which correspond to slow to moderately rapid permeability. Soils data indicate that recharge of infiltration through the soil will be slow to moderately rapid. The soils and other consolidated material overlying the bedrock are considerably more porous then the bedrock.



- 3. Surface water is controlled on base by open ditches, and underground storm sewers. There are no natural surface water features on the base. No 100-year flood plain has been delineated on the base, but highly localized flooding does occur.
- 4. Bedrock in the vicinity of Willow Grove is the Stockton Formation, which consists primarily of gray and red sandstone with interlayers of red shale. The Stockton formation lies approximately 10 feet below the surface at Willow Grove, and as far as 15 to 20 feet below the surface in areas where structural fill has been placed.
- 5. Groundwater is an important resource in the vicinity of Willow Grove. The Stockton formation, the bedrock aquifer, is an important source of private and public water supplies. The water table in the unconsolidated upper aquifer fluctuates seasonally. This fluctuation would have a significant influence on the direction and rate of contaminant migration in both the unconsolidated and bedrock aquifers, because primary source of recharge for the bedrock aquifer is the unconsolidated aquifer.
- 6. There are no known federal endangered or threatened species which inhabit the area.

#### METHODOLOGY

During the course of this project, interviews were conducted with base personnel (past and present) familiar with past waste disposal practices; file searches were performed for past hazardous waste activities; interviews were held with local, state and Federal agencies; and field and helicopter reconnaissance inspections were conducted at past hazardous waste activity



sites. Seven sites were identified as potentially containing hazardous contaminants resulting from past activities. These sites have been assessed using a Hazard Assessment Rating Methodology (HARM) which takes into account factors such as site characteristics, waste characteristics, potential for contaminant migration and waste management practices. The details of the rating procedure are presented in Appendix D. The rating system is designed to indicate the relative need for follow-on action in Phase II of the IRP Program.


#### FINDINGS AND CONCLUSIONS

All seven sites identified during the study were evaluated as having a high potential for environmental contamination, primarily due to the fact that the Stockton formation, which is the bedrock aquifer for the region, lies about ten feet below the surface at Willow Grove. The Stockton formation is an important source of private and public water supplies.

Figure ES-1 shows the locations of the seven sites recommended for confirmation. Table ES-1 presents the results of the HARM score rating analysis and indicates the types of contamination of concern at each site.

#### RECOMMENDATIONS

The recommendations shown in Table ES-2 are made for work to be performed in Phase II (Confirmation and Quantification). The recommended actions are generally one-time sampling and analytical programs. They are designed on a site-by-site basis to verify the presence or absence of contamination at a site, and to further assess the potential for adverse environmental impact from contamination should it be present at a site.





#### TABLE ES-1

### SUMMARY OF WASTE TYPES AND HARM SCORES FOR CONFIRMATION SITES AT WILLOW GROVE ARF

Site Number	Site Name	Waste Type	HARM Score
1	POL Area	JP-4 Fuel JP-4 Fuel Sludge 1100 Aviation Fuel	82
2	Open Waste Storage Area #42	Engine Oil Hydraulic Fluid Solvents (PD-680,1,1,1-Tri- chloroethane, Lacquer Thinner, Paint Stripper) Methanol De-Icing Fluid (Ethylene Glycol)	79
3	Ponding Basin	JP-4 Fuel Other Fuel Oils Solvents	70
4	Washrack Area	Super II Detergent Solvents (PD-680, Dexyl) Paint Strippers (Lacquer and Enamel Stripper, MEK)	69
5	Building #330 Waste Oil Storage Area		69



### TABLE ES-1 (Con't)

### SUMMARY OF WASTE TYPES AND HARM SCORES FOR CONFIRMATION SITES AT WILLOW GROVE ARF

Site Number	Site	Name	Waste Type	HARM Score
6	Heating Plant		#6 Fuel Oil #2 Fuel Oil Solvents (Petroleum Naptha) Corrosion Inhibitor (Acidine) Liquid Oxygen Scavenger Alkalinity Control Agent	66
7	Old Well	l House	Paint and Paint Wastes Paint Thinners Solvents (Toluene)	57



THELE ES-2

### RECOMMENDED PHASE II SAMPLING PROGRAM WILLOW GROVE ARP

				Recom	mended Phar	ogram	
Site	Site Name	Harm Score	No. of Soil Borings <sup>1</sup>	No. of Monitor Wells <sup>2</sup>	Maximum No. of Soil/Sed Samples <sup>3</sup>	GW	No. of Surface Water
1	POL Area	82	6	1	18	5	-
2	Open Storage Area No. 42	79	6	4	18	4	
3	Ponding Basin	70			6	3 (seeps)	6
4	Washrack Area	69	3	3	14	5 (3 wells, 2 seeps)	-
5	Bldg. 330 Waste Oil Storage Area	69 a		1	8 (5 hand auger)	1	-
6	Heating Plant	66		_	5 (all hand auger)	~~	
7	Old Well House	57	خيت	_	1	2	1
TOTALS		15	9	71	20*	7	

<sup>\* 20 = 2</sup> from AF-2, 4 from existing monitor wells, 9 from new monitor wells, 5 from seeps

#### NOTES:

Soil borings refer to hollow stem auger holes not finished as monitor wells.

<sup>&</sup>lt;sup>2</sup> All monitor wells to be drilled 20 feet into bedrock, screened above seasonal high water and sand packed.

<sup>3.</sup> Sediment samples to be preserved for analysis to be determined by use of on-site OVA.

<sup>&</sup>lt;sup>4</sup> A seep is defined as an area of ground where water or other liquid oozes from the earth; water collected from a seep is treated as groundwater.



#### SECTION 1

#### INTRODUCTION

#### 1.1 BACKGROUND AND AUTHORITY

The United States Air Force, due to the nature of its primary mission, has long been engaged in a wide variety of operations dealing with toxic and hazardous materials. This circumstance, coupled with the enactment of environmental legislation at the Federal, state, and local levels of government, has required action to be taken to identify and eliminate hazards related to past disposal sites in an environmentally responsible manner.

The primary federal legislation governing the disposal of hazardous waste is the Resource Conservation and Recover Act (RCRA), as amended. Under Section 6003 of the Act, Federal agencies are directed to assist EPA and make available information on past disposal practices. Section 3012 of RCRA requires each state to inventory disposal sites and make information available to requesting agencies. To assure compliance with these hazardous waste regulations, DoD issues Defense Environmental Quality Program Policy Memoranda (DEQPPM), which mandated a comprehensive Installation Restoration Program (IRP).

The current DoD IRP policy is contained in DEQPPM 81-5, dated 11 December 1982 and implemented by Air Force message dated 21 January 1982. DEQPPM 81-5 reissues,

### WESTERN .

consolidates, and amplifies all previous directives and memoranda on the Installation Restoration Program. DoD policy is to identify and fully evaluate suspected problems associated with past hazardous contamination from Air Force facilities, and to control hazards to health or welfare that resulted from past operations. The IRP will be the basis for U.S. Air Force response actions under the provisions of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, and directed by Executive Order 12316, and 40 CFR 300, Subpart F, National Contingency Plan. CERCLA is the primary legislation governing remedial action at past hazardous waste disposal sites.

#### 1.2 PURPOSE AND SCOPE OF THE ASSESSMENT

The Installation Restoration Program has been developed as a four-phased program:

- Phase I Initial Assessment (Records Search)
- Phase II Confirmation/Quantification
- Phase III Technology Base Development
- Phase IV Operations/Remedial Actions

WESTON was retained by the United States Air Force to conduct the Phase I Records Search at Willow Grove Air Reserve Facility under Contract No. F08637-83-G0009. Two facilities were included in this records search: the Air Force Reserve Facility (913th TAG) and the Pennsylvania Air National Guard Facility (11lth PaANG). The two facilities, encompassing 162 acres, are separate operations, housed at separate but adjacent facilities. This report contains a summary and an evaluation of the information collected during Phase I of the IRP.

### W. STEEN

The objective of the first phase of the program is to identify the potential for environmental contamination from past waste disposal practices at Willow Grove to assess the probability for contaminant migration, and to develop conclusions and recommendations for follow on actions. The Phase I program included a pre-performance meeting, an on-site base visit, a review and analysis of the information collected, and preparation of this report.

The pre-performance meeting was held at Willow Grove on 15 May 1984. The purpose of this meeting was to define responsibilities of the project participants, establish a program schedule, transfer information to the project contractor, and to tour the base facilities.

WESTON's team conducted the on-site base visit 25-29 June 1984. Activities performed during the on-site visit included a detailed search of installation records, tours of the installation, and interviews with past and present base personnel. At the conclusion of the on-site base visit, an outbriefing was held with representatives of the U.S. Air Force Reserve and the Air National Guard to discuss preliminary findings.

The following individuals comprised WESTON's record search team:

- o Raymond W. Kane, P.E., Project Manager, (M.S. Civil Engineering, 1976)
- o Allison L. Dunn, Hydrogeologist, (M.S., Geology, 1981)
- o Michael F. Coia, Chemical Engineer, (M.S., Environmental Engineering, 1981)
- o Jennifer L. Kauffman, Environmental Planner, (M.R.P., Regional Planning, 1979)



Resumes of these key team members are provided in Appendix A.

#### 1.3 METHODOLOGY

The Willow Grove records search began with a review of past and present industrial operations and was conducted at the base. Information was obtained from available records, such as shop files and real property files, and from interviews with past and present base employees from the various operating areas. A list of the 29 interviewees by position and approximate years of service is presented in Appendix B.

Prior to the base interviews, the applicable federal, state and local agencies were contacted for pertinent base related environmental data. The agencies contacted are listed in Appendix C.

The next step in the activity review process was to identify all hazardous waste generators and to determine the past management practices regarding the use, storage, treatment, and disposal of hazardous materials from the various Air Force Reserve and Air National Guard operations on the Base. Included in this part of the activities review was the identification of all known past disposal sites and other possible sources of contamination, such as spill areas.

A general ground tour of the identified sites was then made by the WESTON record search team to gather site-specific information, including general site conditions, visual evidence of environmental stress, and the presence of nearby drainage ditches or surface water

### WESTERN

bodies. A helicopter survey was also conducted. These water bodies were inspected for any obvious signs of contamination or leachate migration.

A decision was then made, based on all of the above information, whether a potential exists for hazardous material contamination at any of the identified sites using the Flow Chart shown in Figure 1-1. If no potential existed, the site was deleted from further consideration. If minor operations and maintenance deficiencies were noted during the investigation, the conditions were reported to the Base Environmental Coordinator for remedial action.

For those sites where a potential for contamination was identified, the potential for migration of the contamination across installation boundaries was evaluated by considering site-specific ground- and surface water conditions. If there is potential for on-base contamination or other environmental concerns, the site was referred to the Base Environmental Coordinator for further action. If the potential for contaminant migration is considered significant, the site is evaluated and prioritized using the Hazard Assessment Rating Methodology (HARM), described in Appendix D.

The site rating indicates the relative potential for environmental impact at each site. For those sites showing significant potential, recommendations are made to quantify the potential contaminant migration problem under Phase II of the Installation Restoration Program. No Phase II work is recommended for those sites showing a low potential.






FIGURE 1-1 PHASE I INSTALLATION RESTORATION PROGRAM



#### SECTION 2

#### INSTALLATION DESCRIPTION

#### 2.1 LOCATION, SIZE AND BOUNDARIES

The Willow Air Reserve Facility is located Grove northeast of Willow Grove Naval Air Station, and is owned by the U.S. Air Force. A portion of the facility leased to PaANG. Willow Grove approximately 23 miles of Philadelphia north southeastern Montgomery County, immediately adjacent to Figure 2-1 shows the location of the facility within the region.

The Air Reserve Facility is located in Horsham Township, just west of Warminster and Warington Townships in Bucks The surrounding land use has been described as County. "urban sprawl", radiating out from Philadelphia. land west and north of the base is relatively open agricultural land, and scattered industrial and residential development and golf courses. Sewer service is planned in the western area, and development is expected to The areas to the north are environmentally sensitive and zoned low density residential, and are expected to remain largely vacant due to lack of utility The areas south and east of the Air Reserve Facility are densely developed for residential, industrial and commercial uses. The Federal government is the process of acquiring lands in the north and south clear zones and additional easements to the north to additional development which conflicts with preclude flight patterns.






FIGURE 2-1 LOCATION OF WILLOW GROVE ARF



The Willow Grove Air Reserve Facility occupies approximately 162 acres of land. The Pennsylvania Air National Guard leases and occupies 45 acres in the southern third of the site, while the U.S. Air Force Reserve owns the remainder. The facility locations are shown in Figure 2-2.


#### 2.2 HISTORY

#### 2.2.1 History of the 913th Tactical Airlift Group

The 913th Tactical Air Group evolved from the 512th Troop Carrier Group, which has been located at the Willow Grove Air Reserve Facility since 1958.

The 512th Troop Carrier Group was originally trained and based at the municipal airport in Reading, Pennsylvania and was activated during the Korean War. In 1958, the 512th Troop Carrier Group was officially located at the new Willow Grove Air Reserve Facility. The 913th Troop Carrier Group, host group at Willow Grove, and 912th Troop Carrier Group were assigned to the 512th until 1965 when they were reassigned to the 302nd TCW in Clinton, Ohio. In 1966, the 912th and 913th TCG's were reassigned to the 514th Troop Carrier Wing at McGuire AFB, New Jersey.

The 912th and 913th were renamed Tactical Airlift Groups in July 1967. The 913th participated in the YC-119 program at Willow Grove - the forerunner of the AC-119 gunship used in Viet Nam. In August 1967, fourteen crews of the South Vietnam Air Force trained on C-119 aircraft at Willow Grove.





The 912th TAG was deactivated in 1968 and became the 912th Military Airlift Group (associate) at Dover AFB, Delaware. Plans for the deactivation of the 913th TAG were made in 1969, but instead the Group was given a new mission in 1970: "to fly 'Hercules' C-130 aircraft" - and has remained at Willow Grove Air Reserve Facility. At the present time, eight C-130E Hercules aircraft are assigned at the Willow Grove Air Reserve Facility.

#### 2.2.2 History of the 111th Tactical Air Support Group (PaANG)

The 111th PaANG evolved from the 103rd Observation Squadron, and has been located at Willow Grove since 1963.

The 103rd Observation Squadron was originally formed Philadelphia in 1924, part of the 28th Division Aviation, Pennsylvania National Guard. Through the years, the 103rd has operated from a number of locations and performed a variety of missions. In 1941, the Observation Squadron became a Reconnaissance Squadron. 1943, the 103rd was redesignated as the 40th Photo Reconnaissance Squadron. The 40th was inactivated and was reactivated 1946 as the 103rd Bomb Squadron in Philadelphia. Federal recognition was received in December 1948. The Philadelphia Air National Guard became the 111th, a fully constructed self-supported tactical flying unit which served in Korea.

The 111th was redesignated as a Fighter Interceptor Group in May 1955, with a day fighter mission. Beginning in 1955, the unit underwent major reorganization due to cutbacks. The Group's mission changed from day fighter to all weather air defense assignment.



In April 1963, the Group was officially redesignated as an Air Transport Unit. The 111th was relocated to Willow Grove in March 1963. In May 1969, the unit acquired its present designation, the 111th Tactical Air Support Group, and was equipped with the U-3 and O-2A's as interim aircraft. At the present time, nineteen A-37 'Dragonfly' aircraft and nine, C-131D are assigned to the 111th PaANG.

#### 2.3 ORGANIZATION AND MISSION

## 2.3.1 Organization and Mission of the 913th Tactical Airlift Group

The primary mission of the 913th Tactical Airlift Group is to achieve, through training, capabilities for:

- air transportation for airborne forces and their equipment and supplies;
- long-range movement of personnel, equipment and supplies, including air evacuation of patients;
- material support, including supply services and organizational and field maintenance of assigned aircraft;
- operation and maintenance of base facilities in support of assigned or attached units;
- operation and maintenance of communications facilities and equipment in support of USAFR flying activities at airport and air-base type installations;
- medical support to assigned units;
- operations of air terminals for airlift; and
- loadmaster services for aerial delivery of heavy loads.



The secondary mission is to operate and maintain an air force installation at the Willow Grove Air Reserve Facility.

The 913th Tactical Airlift Group is comprised of the following units:

- HQ 913th Tactical Airlift Group
- 913th Consolidated Aircraft Maintenance Squadron
- 327th Tactical Airlift Squadron
- 913th Civil Engineering Squadron
- 913th Combat Support Squadron
- 913th Tactical Clinic Unit
- 913th Communications Flight (Support)
- 913th Weapons System Security Flight
- 913th Aerial Port Flight
- 913th Mobility Support Flight

At the present time, there are 818 personnel attached to the 913th TAG. The personnel include the following:

#### No. of Personnel

Air Reservists (Part-time)	693
Air Reserve Technicians	116
Civilians (Host and Tenants)	151
Active Duty Air Advisors	_4
TOTAL Personnel	964

The 913th TAG is currently part of the 459th Tactical Airlift Wing at Andrews AFB, Maryland.



## 2.3.2 Organization and Mission of the 111th Pa Air National Guard

The mission of the lllth Air National Guard is to provide units organized, equipped and trained to function efficiently at existing strengths in the protection of life and property and preservation of peace, order and public safety, under competent orders of state authorities.

In addition, the lllth PaANG is to:

- provide operationally-ready combat units, combat support units, and qualified personnel for active duty in the Air Force;
- to protect life and property and preserve peace, order, and public safety; and to
- organize, train and equip assigned personnel to provide operationally-ready Direct Air Support Center (DACS) Squadrons and Tactical Air Support Squadrons (TASSq) to the Tactical Air Control System (TACS).

The 111th PaANG is composed of the following units:

- HQ 111th Tactical Air Support Group
- 103rd Tactical Air Support Group
- 111th Tactical Clinic
- 111th Civil Engineering Flight
- 111th Combat Support Squadron
- 111th Communications Flight (SPT)
- 111th Direct Air Support Center Squadron
- 140th Weather Flight (Attached)



At the present time, 829 personnel are assigned to the lllth PaANG at Willow Grove. The personnel include

### No. of Personnel

All National Guardsmen	
(Part-time)	689
Air Technicians	138
Active Duty Air Advisors	2
TOTAL Personnel	829

The 111th PaANG is currently assigned to the 105th TASW, Westchester County Airport, White Plains, NY.



#### SECTION 3

#### ENVIRONMENTAL SETTING

#### 3.1 METEOROLOGY

Willow Grove is located in the Southeastern Coastal Plain/Allegheny Plateau physiographic unit. The Atlantic Ocean to the east and Appalachian Mountains to the west have a moderating influence on local climate. January is the coldest month, with an average temperature of 32.3°F, and July is the warmest month, with an average temperature of 75.6°F, (NOAA, 1974).

On the average, 41.18 inches of precipitation falls annually. Maximum rainfall occurs in late summer in connection with local thunderstorms. The average annual snowfall is 20.3 inches (NOAA, 1974). Climatic data is summarized in Table 3-1.

Net precipitation is an indicator of the potential for leachate generation, and is equal to the difference between precipitation and evapotranspiration. Average annual evapotranspiration in Bucks County is estimated to be 27 inches per year (Sloto and Davis, 1983). Net precipitation at Willow Grove is estimated to be 18 inches, which indicates a moderate to high potential for leachate generation.

Rainfall intensity is an indicator of the potential for excessive runoff and erosion, and is of interest in determining the potential for movement of contaminants.



TABLE 3-1

## CLIMATIC CONDITIONS AT WILLOW GROVE AIR RESERVE FACILITY\* (Period of Record 1936 to 1975)

TEMPERATURE (QF)			PRECIPIT		
Month	Daily Maximum	Daily Minimum	Monthly Average	Normal Total (inches)	Mean Total Snowfall (inches)
January	40.1	24.4	32.3	3.16	5.3
February	42.2	25.5	33.9	3.11	6.2
March	51.2	32.5	41.9	3.52	3.7
April	63.5	42.3	52.9	3.29	0.2
May	74.1	52.3	63.2	3.34	Trace
June	83.0	61.6	72.3	3.65	-0-
July	86.8	66.7	76.8	4.10	-0-
August	84.8	64.7	74.8	4.50	-0-
September	78.4	57.8	68.1	3.41	-0-
October	67.9	46.9	57.4	2.79	Trace
November	55.5	36.9	46.2	3.10	0.7
December	43.2	27.2	35.2	3.21	4.2
YEAR	64.4°F	44.9°F	54.6°F	41.18 in.	20.3 in

Source: Ruffner and Bair, 1977

<sup>\*</sup> Data from station at Philadelphia International Airport.



The one-year, 24-hour rainfall event is used to gauge rainfall intensity. The one-year, 24-hour rainfall in the vicinity of Willow Grove is about 2.7 inches, (NOAA, 1962).

#### 3.2 GEOGRAPHY

### 3.2.1 Topography

The Willow Grove Air Reserve Facility is mostly level, and slopes gently to the northwest. The highest elevation of 315 feet above mean sea level (m.s.l.) occurs along Privet Road near Building \$217. The lowest elevation of 264 feet occurs in the vicinity of the basin in the northwest corner of the facility. Both the U.S. Air Force Reserve and Pennsylvania Air National Guard areas slope toward the ponding basin, (Willow Grove Air Reserve Facility, file information).

### 3.2.2 Soils

The principal soils on the base which have remained undisturbed by construction are the Doylestown Silt Loam, the Lawrenceville Silt Loam, the Lansdale Loam and the Readington Silt Loam (USDA, SCS, 1967). The distribution of soils is shown in Figure 3-1. Soil characteristics are summarized in Table 3-2.

Soil borings taken in 1956 prior to the construction of the facility indicate that soils and unconsolidated sediments overlying the bedrock at Willow Grove are approximately 10 feet thick at the present time, except to the south and below the parking apron and associated hangars






FIGURE 3-1 SOIL CONDITIONS AT WILLOW GROVE ARF



TABLE 3-2

### SOILS AT WILLOW GROVE ARF (SOIL SURVEY - MONTGOMERY COUNTY, PENNSYLVANIA)

Soil Name	Symbol	Permeability (in./hr.)	Depth to Seasonal High Water Table (ft.)	Depth to Bedrock (ft.)
Doylestown Silt Loam	Ds	0.63 - 6.3	0 - 0.5	4 - 8
Lansdale Loam	La	0.63 - 6.3	3+	3 - 12
Lawrenceville Silt Loam	Le	0.20 - 6.3	1 - 2	4 - 12
Readington Silt Loam	Re	0.20 - 6.3	1.5 - 2.5	3 - 5

Natural soils at the facility are members of the Lawrenceville-Chalfont-Doylestown Association. They are deep, moderately well-drained to poorly-drained soils, formed in windblown silt deposited on undulating uplands.



where structural fill has been placed to bring grade as far as 15 to 20 feet above the bedrock. The overburden is considerably more porous than the underlying bedrock.

The soil property of concern in assessing the potential for surface water infiltration is vertical permeability. The vertical permeability values for soils on the base range from 0.2 inches/hour to 6.3 inches/hour, (USDA, SCS, 1967). These values correspond to low to moderately high permeability.

### 3.3 SURFACE WATER RESOURCES

### 3.3.1 <u>Drainage</u>

The Willow Grove Air Reserve Facility drains generally northward into the Little Neshaminy Creek drainage basin which flows east into the Delaware River. Storm sewers and surface runoff from the U.S. Air Force and Pennsylvania Air National Guard property drain into the ponding basin, which empties into Park Creek, a tributary of Little Neshaminy Creek, at the boundary of the base. Figure 3-2 shows drainage patters at Willow Grove ARF.

There are no streams with defined flood plains on the base property. Very localized flood conditions associated with the various man-made drainage ditches and swales exist on the base property. These flood areas can only be established through on-site observation or extensive engineering analysis, (U.S. Navy, file information). As a result, no 100-year flood plain has been delineated on the Air Reserve Facility property. However, a review of flood plain information provided in FEMA flood insurance study for Horsham



Township indicates that the Air Reserve Facility, with the possible exception of the ponding basin, is located above the 100-year flood elevation, (FEMA, 1977). Figure 3-3 is a map of flood prone areas at Willow Grove ARF.

### 3.3.2 <u>Surface Water Quality</u>

Streamflow and water quality are not continuously recorded on Little Neshaminy Creek in the vicinity of the study area. However, water quality sampling was conducted during low flow periods in 1979 and 1980 for a study of the effects of urbanization on water resources (Sloto and Davis, 1983). The closest sampling station to Willow Grove was located on Little Neshaminy Creek at Neshaminy, approximately two miles downstream from Willow Grove. Results are summarized in Table 3-3.

The data summarized in Table 3-3 give a general picture of water quality from Willow Grove. Since the sampling was done during low flow conditions, concentrations of dissolved constituents are expected to be higher than during other periods of the year. Concentrations were also higher during the 1980 sampling period, when precipitation (and streamflow) were below average. concentrations in samples at Station 01464800 are generally in the low to median end of the range of concentrations in samples from other streams in Warminster Township sampled during the same period. Also, samples taken further downstream in Little Neshaminy Creek significant increases in concentrations of nutrients and other constituents. These increases are attributed to wastewater treatment plant discharges downstream from Willow Grove, and indicate that there are influences other than Willow Grove on the quality of Little Neshaminy Creek.




FIGURE 3-3 FLOOD-PRONE AREAS



### TABLE 3-3

### CHEMICAL ANALYSIS OF WATER FROM STATION NO. 01464800 LITTLE NESHAMINY CREEK AT NESHAMINY DURING LOW FLOW CONDITIONS

	Date of Sample 7/15/80	
Discharge (in cubic feet per second)	29.7 cfs	1.24 cfs
Dissolved Solids, Residue at 180°C, (mg/1)	169	237
Specific Conductance (umhos)	280	370
ΡĦ		7.2
Temperature, <sup>O</sup> C	12.0	23.0
Calcium, Dissolved (mg/l as Ca)	22	32
Magnesium, Dissolved (mg/l as Mg)	8.0	11
Sodium, Dissolved (mg/l as Na)	15	21
Sodium and Potassium, Dissolved (mg/l as Na)	17	
Potassium, Dissolved (mg/l as K)	2.1	3.1
Chloride, Dissolved (mg/l as Cl)	19	31
Sulfate, Dissolved (mg/l as SO4)	36	41
Nitrogen, Nitrate Dissolved (mg/l as N)	2.20	1.20



### TABLE 3-3 (Con't)

### CHEMICAL ANALYSIS OF WATER FROM STATION NO. 01464800 LITTLE NESHAMINY CREEK AT NESHAMINY DURING LOW FLOW CONDITIONS

	Date of Sample	
	10/17/79	7/15/80
Nitrogen, Nitrite, Dissolved		
(mg/l as N)	.000	.040
Phosphorous, Ortho, Dissolved		
(mg/l as P)	.050	.340
Phosphorous, Dissolved		
(mg/l as P)	.090	.340
Iron, Dissolved		
(ug/l as Fe)	60	20
Manganese, Dissolved		
(ug/l as Mn)	60	230
Silica, Dissolved		
(mg/l as SiO <sub>2</sub> )	14	8.4
Pluoride, Dissolved		
(mg/l as F)	.2	.6
Carbon, Organic, Dissolved		
(mg/l as C)	2.9	
Alkalinity, Field		
(mg/l as CaCO <sub>3</sub> )	41	83
Hardness		
(mg/l as CaCO <sub>3</sub> )	88	130
Hardness, Noncarbonate		
(mg/l as CaCO <sub>3</sub> )	47	42
Cadmium, Dissolved		
(ug/l as Cd)	1	. 4



### TABLE 3-3 (Con't)

### CHEMICAL ANALYSIS OF WATER FROM STATION NO. 01464800 LITTLE NESHAMINY CREEK AT NESHAMINY DURING LOW FLOW CONDITIONS

	Date of Sample		
	10/17/79	7/15/80	
Chormium, Dissolved (ug/l as Cr)	< 10	20	
Copper, Dissolved (ug/l as Cu)	2	6	
Lead, Dissolved (ug/l as Pb)	0	1	
Mercury, Dissolved (ug/l as Hg)	.2	.1	
Selenium, Dissolved (ug/l as Se)		0	
Zinc, Dissolved (ug/l as Zn)		4	

Source: Sloto and Davis, 1983



The protected use for Little Neshaminy Creek basin is warm water fishes: "maintenance and propagation of fish species and additional flora and fauna which are indigenous to a warm water habitat", (PA DER, 1980).

Water quality criteria have been developed for the warm water fish use classification. The concentrations reported in Table 3-3 are less than the maximum values for which primary and secondary drinking water standards have been established.

### 3.3.3 Surface Water Use

Surface water uses in the vicinity of Willow Grove are related primarily to water supply and wastewater treatment. The majority of water supplies in the vicinity of Willow Grove are obtained from groundwater aquifer. An exception is a surface water intake for a municipal supply near the confluence of the Little Neshaminy Creek and Delaware River, located 10 miles downstream from Willow Grove ARF. The creek is also used for disposal of treated wastewater effluents by a number of municipalities downstream of Willow Grove ARF.

#### 3.4 GROUNDWATER RESOURCES

### 3.4.1 Background Geology

Willow Grove ARF overlies a major regional bedrock water supply aquifer. This subsection describes the geologic setting of the facility, the underlying hydrogeologic units and their characteristics, regional groundwater quality, and groundwater use.



Willow Grove is situated in the southern portion of the Triassic Basin, and is underlain by the Stockton Formation, which consists primarily of gray and red sandstone with red shale interlayers and has a total thickness of 6,000 feet near the Bucks-Montgomery County line Three members are distin-(Rima and Others, 1962). quished within the Stockton: the lower arkose member, characterized by abundant coarse-grained sandstone and arkosic conglomerate (composed of unsorted quartz and feldspar grains); the middle arkose member, characterized abundant fine- and medium-grained by arkosic sandstone; and the upper shale member, characterized by abundant shale and siltstone. The middle arkose member, which underlies Willow Grove ARF and most of Warminster Township, has a maximum thickness of 4,200 feet at the Bucks-Montgomery County line, and 70% of the Stockton Formation. The middle arkose member has the best water yield of the formations.

Individual lithologic units in the Stockton vary from 10 to 120 feet in thickness, and show great lateral variability in texture, pinching out or grading laterally into beds of different grain size or color, (Rima and Others, 1962; Sloto and Davis, 1983). Vertical jointing is well developed regionally. A geologic map is presented in Figure 3-4.

### 3.4.2 <u>Hydrogeologic Conditions</u>

The Stockton Formation underlying the ARF is the major aquifer (or water-yielding subsurface hydrogeologic unit) in the region. Groundwater flow in the Stockton occurs primarily through fractures in the rock, and is, therefore, strongly influenced by the size, frequency,






FIGURE 3-4 GEOLOGIC MAP OF THE STOCKTON FORMATION IN THE VICINITY OF WILLOW GROVE ARF AND WILLOW GROVE NAS

### W. STEEN

distribution and orientation of fractures and fracture zones. Most deep wells in the region draw water from several major fracture zones, and the hydraulic head in each zone generally varies (Sloto and Davis, 1983). The static water level in a well, therefore, reflects the composite hydraulic head of the different water-yielding zones which it penetrates. Water wells in the region are seldom drilled below a depth of 500 feet because the water-bearing capacity of bedrock decreases with depth.

According to Sloto and Davis (1983), yields of drilled wells in the area range from 8 to 700 gallons-per-minute (gpm) with a median of 145 gpm. Rima and Others (1962) reported values of transmissivity ranging from 8,000 gallons-per-day-per-foot (gpd/ft.) for the 23,000 Stockton in the area of Doylestown and Langhorne based on pumping tests performed in 1957 to 1958. Based on pumping tests performed in 1979 to 1980, Sloto and Davis (1983) reported that production wells pumped at 235 to 309 gpm for 48 to 71 hours, caused drawdown to occur observation wells downdip, updip or along strike, as far away as 2500 feet, even if the wells did not penetrate the same stratigraphic intervals. Transmissivity values derived from these tests were not reported.

The Stockton is overlain throughout the area by a relatively thin (2 to 15 feet) cover of soil and unconsolidated sediment formed primarily from in situ chemical and mechanical weathering of the bedrock, and grading downward to less and less weathered bedrock. The bedrock surface elevation below Willow Grove ARF has been well-defined by a series of soil borings made in 1956 prior to facility construction and during subsequent development. Logs for these borings are available

### WESTERN .

for the Civil Engineer's office. They indicate that subsurface materials below Willow Grove ARF consist silty sandy clay, and sandy clay grading downward to weathered shale. Bedrock near the surface consists of medium hard sandstone, brown and reddish brown, overlain in many places by 3 to 20 feet of soft medium hard red shale, usually decomposed by weathering.

Data from these borings have been used to compile the bedrock surface map in Figure 3-5. According to this map, the bedrock slopes gently downward to the north, approximately downdip and paralleling the original topography from an elevation of 290 feet mean sea level (m.s.l.) along Privet Road on the southeast boundary of the ARF to 270 feet along the northern boundary. A low point on the bedrock surface (elevation 260 feet) occurs at the current site of the ponding basin.

The unconsolidated overburden is considerably than the underlying factured bedrock, porous generally acts as a storage medium for wet infiltration which is slowly transmitted as recharge to the bedrock aguifer. The overburden is generally good hydraulic communication with the upper, weathered bedrock zone, and together they form the upper, table aquifer, in which water pressure is in equilibrium with atmospheric. The water table rises during the wet season (November to April) as infiltration moves through the soil down to the saturated zone, where all void spaces are filled with water. In the spring and summer, evapotranspiration from soil and plants takes up water before it can reach the saturated zone, and even draws water from the saturated zone, causing the water table

### W. STOCK

The height of the water table determines the hydraulic head and the driving force downward into the bedrock aquifer and laterally into shallow streams and ditches incised into the overburden. When the water table is high, the recharge rate to the bedrock aquifer increases, as does the baseflow in streams and springin hillside groundwater springs, which usually occur at the overburden-bedrock interface. As the water table falls, recharge decreases and spring- and streamflow may decrease or cease. The water table aquifer dries up locally in the summer in areas which have only a relatively thin overburden and/or are heavily influenced by nearby pumping from the bedrock aquifer.

This seasonal pattern has a significant influence on the directions and rates of contaminant migration in the subsurface. In areas of Bucks and Montgomery counties where surface spills of contaminants have been known the saturated overburden groundwater in commonly found to exhibit concentrations of the contaminants of interest several orders of magnitude higher than groundwater in the underlying bedrock Furthermore, concentrations in the overburden are found to vary seasonally, often increasing in the spring as additional contaminants are carried down to the saturated zone from the surface soil by infiltration. same time, baseflow to streams may exhibit high concentrations due to contributions from the water Due to the restricted saturated thickness of aquifer. the water table aquifer and its sometimes ephemeral nature, it is extremely difficult to effectively recover contaminated groundwater directly from this zone.



A rough water table map for the ARF in October 1956 (Figure 3-6) has been constructed from water level data available from the same boring logs used in Figure 3-5. According to this map, the water table at this time roughly paralleled bedrock surface and was almost coincident with it over much of the facility area, particularly to the north. Along the boundary, the water table was 5.6 feet higher than bedrock surface. Two apparent "valleys" in the water table map indicate directions of concentrated groundflow discharge along topographic stream water or valleys, with the major one flowing through the area the current ponding basin. Based on this information, the water table aguifer underlying the site can be assumed to be quite shallow, on the order of 2 to 8 feet thick, and probably ephemeral. Although there are no current groundwater level measurements available for the facility, the present water table can be assumed to be strongly influenced by pumping from the Air Force supply well (AF-I) and nearby Navy wells (NAS-1 and NAS-2).

#### 3.4.3 Groundwater Quality

#### 3.4.3.1 Natural Groundwater Quality

Water quality analyses for 15 wells in the Stockton Formation were selected from the U.S. Geological Survey Chemistry Data Base by REWAI (1982) as representative of background groundwater quality for that formation. A statistical summary of inorganic parameters in these wells is presented in Table 3-4, and is compared with a similar summary for analysis of 55 wells samples from the Stockton reported by Rima and Others (1962).



TABLE 3-4

STATISTICAL SUMMARY OF BACKGROUND GROUNDWATER QUALITY IN THE STOCKTON FORMATION (1)

Parameters	REWAI 5-15 V	• •	Rima & Others (1962)		
	Range	Median	Range	Median	
Hq	5.2-8.1	7.2	6.2-8.5	7.8	
Specific Conductance (umhos/cm)	95-397	255	69-1230	317	
Nitrate-NO <sub>3</sub> (mg/L)	1.1-278	10	0.0-10.7	1.6	
Chloride (mg/L)	5.5-26	9.5	1.2-80.0	8.6	
Sulfate (mg/L)	15-350	24	8.4-725.0	28.0	
Sodium (mg/L)	8.1-87	8.2	6.8-21.0	12.0	
Iron (mg/L)	<0.01-1.2	0.10	0.02-1.3	0.16	
Manganese (mg/L)	<0.01-0.80	0.04			
Hardness (mg/L)	18-450	100	•		
Bicarbonate (mg/L)	7-188	84			
Total Dissolved Solids (mg/L)	120-872	152			

### Reference

<sup>(1)</sup> REWAI (1982), p. 8-17, 18, 25

### MESTER

Based on this table, groundwater in the Stockton is moderately hard, moderately mineralized, and generally has a neutral pH. A few of the wells sampled exhibited elevated levels of iron and manganese, but median values parameters are below the EPA-recommended these secondary drinking water standards of 0.3 and 0.05 mg/l respectively. High sulfate concentrations (up to 460 mg/l) are locally encountered in the Stockton. They are associated with elevated calcium levels, presumably from dissolution of natural calcium sulfate minerals in the rocks (Sloto and Davis, 1983). However, no correlation has been found between sulfate concentration and geographic distribution, topographic, well depth, or the presence of a diabase dike. cases, natural water quality in the Stockton meets all requirements for a drinking water supply.

### 3.4.3.2 Regional Groundwater Quality

Incidents of groundwater quality degradation from contamination, primarily with synthetic organic chemicals, have been well documented in Warminster and surrounding areas.

Table 3-5 lists maximum reported concentrations of volatile organic compounds found in groundwater The primary contaminants of concern Warminster area. are trichloroethylene (TCE) and tetrachloroethylene Table 3-6 lists the concentrations of TCE and PCE in samples taken from wells at Willow Grove ARF. shown in the tables, the concentrations detected Willow Grove are significantly lower than found elsewhere in the region. TCE and PCE are solvents, commonly used metal degreasers, dry cleaning as



### MAXIMUM REPORTED CONCENTRATIONS OF VOLATILE ORGANIC COMPOUNDS IN GROUNDWATER (1)

Compound	Maximum Reported Concentration (ug/L)(PPb))
Benzene	2
Bromodichloromethane	240
Bromoform	250
Carbon tetrachloride	50
Chlorobenzene	500
Chloroform	500
p Dichlorobenzene	0.1
1,1-Dichloroethane	24
1,2-Dichloroethane	370
1,1-Dichloroethylene	660
cis-1,2-Dichloroethylene	11,000
trans-1,2-Dichloroethylene	51
1,2-Dichloropropane	250
trans-1,3-Dichloropropylene	4.7
Methyl chloride	9.3
Tetrachloroethane	2.6
Tetrachloroethylene (PCE)	26,000
1,1,1-Trichloroethane	900
Trichloroethylene (TCE)	87,000

### Reference:

(1) Sloto and Davis, 1983. Data provided by the U.S. Environmental Protection Agency

### W. Surgin

### TABLE 3-6

# RANGES OF TCE AND PCE CONCENTRATIONS IN WILLOW GROVE NAVAL AIR STATION SUPPLY WELLS OCTOBER 1979 THROUGH JUNE 1984

	Concent	Concentration		
Well Name	TCE (ug/L) (ppb)	PCE (ug/L)(ppb)		
NAS-1	2.0 to 38.4	1.1 to 68.8		
NAS-2	2.3 to 42.4	1.2 to 30.8		
AF-1	0.1 to 23.7	1.9 to 9.4		



products, and septic tank cleaners. They are known to have reached groundwater from leaking storage tanks, spills, and improper handling and disposal methods.

TCE and PCE are related halogenated hydrocarbons, commonly found together. Both are stable, mobile, and only slightly soluble in water. Their molecules are heavier than water and tend to move downward in Both are confirmed animal carcinogens and aquifers. affect the human central nervous system, causing depression, dizziness, and fatigue at high concentrations (Council on Environmental Quality, 1981). Sloto and Davis (1983) described the development of concern over groundwater contamination with TCE and PCE, and subsequent effects on public water supplies in the Warminster area as follows:

In 1979, some wells in central Montgomery County found to be contaminated trichloroethylene as the result of industrial spills. Public water suppliers in southeastern Pennsylvania began testing for and finding volatile organic compounds in well water. September 1979, the Warminster Municipal Authority removed two wells from service, and the Upper Southampton Authority removed three wells from service because of trichloroethylene and tetrachloroethylene contamination. The Hatboro Water Authority removed five wells from service October and one in November. In October, the Warminster Heights Development Corporation found volatile organic compounds in both of their wells, and the Warrington Water Company removed two of their four wells from service because of trichloroethylene contamination. In October, the Environmental Protection Agency (EPA) began testing municipal, industrial, and domestic wells for volatile organic contamination. In November, the U.S. Naval Air Development Center removed three wells from service. The Horsham Township Authority removed one well from service in January 1980 and another in April 1980. The locations of wells sampled for trichloroethylene



and tetrachloroethylene are shown in Figure 20. Data were provided by the Bucks County Health Department, EPA, and municipal water authorities.

Through an aggressive sampling and enforcement program, the EPA, Pennsylvania Department of Environmental Resources (PA DER) and the county health departments have succeeded in identifying several major industrial sources of TCE and PCE in the area, and measures have been undertaken at some sites. However, contamination with TCE and PCE remains widespread. Willow Grove Naval Air Station, TCE and PCE concentrations are measured monthly in all three production wells, and production rates are adjusted to bring the combined effluent concentration below the EPA recommended limit of 4.5 ug/L for drinking water. Ranges for TCE and PCE concentrations in the three wells, including AF-1, the well on the Willow Grove ARF, are listed in Table 3-6.

A contract has recently (June 1984) been awarded by the U.S. Navy to Earth Data, Inc. of West Chester, Pennsylvania for a complete hydrogeologic investigation of the Willow Grove NAS facility including location of nearby sources of TCE and PCE, and a treatability study to develop an adequate and cost-effective treatment alternative for water supply at the facility.

In addition to contamination with volatile organic compounds, there has been relatively localized groundwater contamination in the area with other organics, particularly hydrocarbons spilled or leaking Among inorganic parameters, iron, manganese and sulfate are locally found at elevated concentrations, these are generally attributable to natural Both REWAI (1982) and Sloto and Davis indicated a widespread increase in nitrate levels in groundwater since the 1950's, probably attributable to contamination in rural areas from application of



nitrogen fertilizers and use of on-lot sewerage sys-Sloto and Davis (1983) noted that lead concentrations in 26 wells sampled in the Warminster area in 1979 to 1981 ranged from 0 to 55 ug/L, with a median of 17 ug/L. Although only one sample exceeded the EPA National Interim Primary Drinking Water Standard of 50 ug/L, the median was higher than reported nearby and national medians. They attributed this to the urbanized character of the area, and the widespread occurrence of lead presence as a component of automobile exhaust. Eleven inorganic parameters are sampled for quarterly in the base supply wells. The result from the May analysis are given in Table 3-7. All concentrations measured are well below EPA recommended drinking water The locations of the wells are shown in standards. Figure 3-7.

#### 3.4.4 Groundwater Use

#### 3.4.4.1 On-Base Wells


The Willow Grove Naval Air Station (NAS) and Air Reserve Facility (ARF) are supplied by a dual water distribution system drawing water from three wells: two on NAS property (NAS-1 and NAS-2), and one on ARF property (AF-1). A fourth well (AF-2) was drilled at the same time as AF-1 and was the principal ARF supply well in the late 1950's. Its use was discontinued due to excessive hardness of the well water, and AF-1 became the principal supply well for the ARF. Locations of the base supply wells are shown in Figure 3-7. Well specifications for which records were available are given in Table 3-8.



### TABLE 3-7

# INORGANIC PARAMETER CONCENTRATIONS IN WILLOW GROVE AIR STATION SUPPLY WELLS MAY 9, 1983

	Co	ncentration	ug/L
Parameters	AF-1	NAS-1	NAS-2
F1	0.12	0.17	0.13
<b>NO3-N</b>	1.3	0.16	0.65
As	0.0032	0.0082	0.0039
Ва	0.29	0.15	0.22
Cd	<0.0001	<0.0001	<0.0001
Cr	0.0014	<0.001	0.0016
Pb	<0.001	<0.001	0.0018
Hg	<0.0002	<0.0002	<0.0002
Sc	<0.002	<0.002	<0.002
Ag	<0.0002	<0.0002	<0.0002
Na	10.9	10.6	11.3



SUPPLY WELL SPECIFICATIONS WILLOW GROVE NAVAL AIR STATION

Static Water Level Below G.S. (feet)	55	110	1	
Static Water Level Below G.S. (feet)	<b>co</b>	14	1	
Nominal Yield (gpm)	100	180	300	360
Cased Interval Below G.S. (feet)	0 to 52	0 to 43	ł	-1
Casing Diameter (inches)	10	10	10	10
Total Depth Below G.S. (feet)	397	351	350	330
Year Comp.	1942	1942	1957	1957
Well Driller	MG-209 F.L.Bollinger & Sons	MG-210 F.L.Bollinger & Sons	MG-489 Phila. Drlg. Co. 1957	MG-490 Phila. Drlg. Co. 1957
USGS No.	MG-209	MG-210	MG-489	MG-490
We]] Name	NAS-1	NAS-2	AF-1	AF-2 (out of use)

# References:

REWAI, 1982 Sloto and Davis, 1983



The ARF and NAS water supply systems were originally operated independently, and have a single tie-in line connecting the two systems. Since concern over TCE and PCE concentrations in well water developed in 1979, the wells have been operated as a combined system, with production rates for each well assigned on the basis of well yield and measured contamination levels. combined nominal yield of the three supply wells is 580 In general, TCE and PCE gallons per minute (gpm). concentrations have remained lower in AF-1 than in NAS-1 NAS-2 (Table 3-6). For this reason, AF-1 currently being used preferentially over the other At the time of the site visit (June 25 to 29, 1984), AF-1 was being used exclusively to supply both NAS ARF, at an average rate of 210 gpm for 18 hours per day, or 0.227 million gallons per day (mgd).

### 3.4.4.2 Regional Groundwater Use

According to Sloto and Davis (1983, p. 8) "all the municipal authorities, private water suppliers, industries, and government facilities [in the Warminster area] obtain their water supply from wells". Table 3-9 lists groundwater pumpage in 1980 for major users in the area. In addition, Sloto and Davis (1983) estimate about 25 million gallons were pumped by domestic and small commercial and industrial users.

Both total groundwater use and per capita use increased as the population grew. Between 1960 and 1980, Warminster Township experienced a 122% increase in population. During the same period, groundwater pumpage increased 755% to 1.06 billion gallons per year and per capita use increased 290% to 82 gpd per person.



TABLE 3-9

### GROUNDWATER PUMPAGE IN 1980 BY PUBLIC WATER SUPPLIERS & GOVERNMENT FACILITIES

	Number of Wells	Groundwater Pumpage (million gals.)
Hatboro Water Authority	10	571.7
Horsham Township Authority	13	386.7
Northampton Municipal Authority	5	205.3
Warminster Heights Development Corp.	2	66.5
Warminster Municipal Authority	14	1,063.4
Warrington Municipal Authority	2	106.0
Warrington Water Company	2	3.3
U.S. Naval Air Development Center	3	65.4
U.S. Naval Air Station	3	108.6
Upper Southampton Municipal Authority	_4	142.6
TOTALS	58	2,719.5



Groundwater use in the Warminster area falls under jurisdiction of the Delaware River Basin Commission (DRBC), a regulatory body created in 1961 and including representatives of Delaware, New Jersey, New York and Pennsylvania. The DRBC has the authority to resolve disputes concerning water supplies and water resources management between these states with the Delaware River It permits withdrawal from and discharge into surface water bodies within the basin, and groundwater withdrawals exceeding 100,000 gpd. It also reviews and approves industrial wastewater discharges to water, land use changes in groundwater recharge areas, and dewatering and filling of wetlands (REWAI, In 1980, the DRBC designated portions of southeastern Pennsylvania including Warminster Township as groundwater protected areas, due to high demands on groundsupplies aggravated by the drought of 1980 to In these areas, groundwater allocation permits are required for all new groundwater uses averaging more than 10,000 gpd. Permit requirements include notification of drilling, report on a detailed pumping test including impact on adjacent water supplies and streamflow, and description of conservation and emergency plans.

### 3.5 BIOTIC ENVIRONMENT

Development has destroyed most of the natural vegetation, particularly trees and large shrubs, in the vicinity of Willow Grove. The variety, distribution and abundance of wildlife is determined primarily by habitat, food availability and proximity to man. The remaining habitat in the area supports a diversity of



mammals due to the availability of edge habitat created by the proximity of cultivated fields, woodlands, wetlands, old fields, streams and ponds (U.S. Navy, file information).

According to the U.S. Department of Agriculture, wild-life species normally found in cropped fields, pastures, meadows, lawns and areas overgrown with weeds, grass and shrubs in Montgomery County include quail, pheasant, morning doves, meadowlarks, rabbit, red fox and ground-hog. Species normally found in wooded area are ruffed grouse, wild turkey, deer, squirrel, raccoon, wood thrushes, worblers, and viroes. Non-game species of birds, such as songbirds, are also numerous. A variety of waterfowl species inhabit wet areas, such as swamps, marshes and ponds (USDA, 1967).

#### 3.6 SENSITIVE ENVIRONMENTAL FEATURES

There are no known threatened or endangered species at Willow Grove, ARF. The peregrine falcon, which is recognized as endangered or threatened on the federal endangered species list, has been recorded in the local area, but is a rare transient during the period of March to November (U.S. Navy, file information).

The Graeme Historical Site is located approximately one mile northwest of the Willow Grove ARF. The historical site is downstream from the Willow Grove ponding basin. Discharges from Willow Grove ARF flow through a duck pond on the property of the historic site, via Park Creek.



### 3.7 SUMMARY OF ENVIRONMENTAL CONDITIONS AT WILLOW GROVE ARE

The following environmental conditions are of particular importance in the evaluation of past hazardous waste disposal practices at Willow Grove ARF:

- 1. The mean annual precipitation is 41 inches, the net precipitation is 18 inches and the one-year, 24-hour rainfall event is estimated to be 2.7 inches. These data indicate there is moderate to high potential for infiltration into the surface soils on the base, and that there is moderate to high potential for runoff and erosion.
- 2. The natural soils on the base are loams and silt Soil permeabilities range from 0.2 to 6.3 loams. inches per hour, which correspond to slow moderately rapid permeability. Soils data indicate that recharge of infiltration through the soil will be slow to moderately rapid. The soils and other consolidated material overlying bedrock are considerably more porous then the bedrock.
- 3. Surface water is controlled on base by open ditches, and underground storm sewers. There are no natural surface water features on the base. No 100-year flood plain has been delineated on the base, but highly localized flooding does occur.
- 4. Bedrock in the vicinity of Willow Grove is the Stockton Formation, which consists primarily of gray and red sandstone with interlayers of red



shale. The Stockton formation lies approximately 10 feet below the surface at Willow Grove, and as far as 15 to 20 feet below the surface in areas where structural fill has been placed.

- 5. Groundwater important resource in the is an vicinity of Willow Grove. The Stockton formation, the bedrock aquifer, is an important source of private and public water supplies. The water table in the unconsolidated upper aquifer fluctuates seasonally. This fluctuation have a significant influence on the direction and rate of contaminant migration in both unconsolidated and bedrock aquifers, because primary source of recharge for the bedrock aquifer is the unconsolidated aquifer.
- 6. There are no known federal endangered or threatened species which inhabit the area.



### SECTION 4

### FINDINGS

### 4.1 INTRODUCTION

This section presents information on the 913th TAG of the U.S. Air Force Reserve, and the Pennsylvania Air National Guard (111th PaANG) activities at Willow Grove Air Reserve Facility. The information describes past and present activities which have resulted in the generation, storage and disposal of industrial wastes; identifies fuel spill sites located on the base; and summarizes industrial waste disposal methods.

This section is organized to describe the individual practices and environmental concerns at each facility separately. Information included in this section was obtained primarily from interviews with current and former base employees, a review of files and records, and site inspections.

### 4.2 913th TACTICAL AIR GROUP

### 4.2.1 Overview of Industrial Operations

Industrial activities conducted by the 913th TAG at Willow Grove ARF can be grouped into three broad categories: 1) Aircraft Maintenance, 2) Base Civil Engineering, and 3) Fuel Operations. Each of these



operations occur in several different shops and spaces at Willow Grove ARF.

This subsection provides an overview description of the major activities that occur under each of these three major categories. Shop by shop descriptions and specific wastes generated will be presented in a subsequent subsection of this report. Figure 4-1 shows all major buildings and facilities at Willow Grove ARF.

### Aircraft Maintenance

Most aircraft maintenance operations occur in Building #201 which is the main aircraft maintenance hangar for the 913th TAG. Several shops are located in this facility, including a machine shop, sheet metal shop, welding shop, pneudraulics systems shop, repair and reclamation shop, corrosion control shop, aircraft washing facilities, as well as other facilities, which will be presented in more detail in a subsequent section.

These shops perform the full spectrum of repair and maintenance activities on the C-130 aircraft and ground support equipment owned by the 913th TAG.

Typical chemicals and hazardous materials handled in these facilities are oils, solvents, batteries and contaminated fuels. Most wastes generated are accumulated by Base Supply for eventual pickup by DPDO Philadelphia. Some liquid wastes, such as battery acid, are diluted and neutralized, and drained to the sanitary sewage system.



There are no dumps or landfills at Willow Grove ARF. However, in the past some hazardous wastes from Willow Grove ARF have been disposed of in a dump which is owned and operated by the U.S. Navy. This Navy dump is located on Navy property and has not accepted hazardous wastes since 1980.

### Base Civil Engineering

Most industrial operations under Base Civil Engineering occur in Building \$232. Shops include a paint shop, plumbing shop, carpenter shop, flammable materials storage facilities. Solvents, oils and paints generated by these facilities are accumulated by Base Supply for eventual pick-up by DPDO Philadelphia.

Other wastes such as grease and oily wastes from oil water separators are disposed of off-site by contract disposal. Base Civil Engineering is also responsible for the seven oil/water separators and underground tanks at Willow Grove ARF.

### Fuel Operations

The third major category of industrial operations at Willow Grove ARF is the POL Fuel Farm area. This area (Building #231) consists of two fuel tanks (#207 - 210,000 gallons and #224 - 105,000 gallons), which store JP-4 fuel for use by the C-130 aircraft assigned to the 913th TAG. Fueling activities also include storage of contaminated JP-4 fuel in a 2000 gallon underground storage tank for eventual pickup by DPDO Philadelphia for sale, reclamation, or final disposal.




### 4.2.2 Hazardous Waste Generation and Management


While several areas throughout the Willow Grove ARF have been designated for temporary accumulation of hazardous materials, only one central waste storage location has been used for contractor or DPDO pick ups activation of the base. The temporary accumulation areas are located adjacent to shop generation areas. Open Storage Area No. 42 is located in the northeastern portion of the base along Cinder Road adjacent to the POL Area. and the central hazardous waste accumulation location.

The Hazardous Waste Management Plan for the 913th TAG outlines the locations and operations of the generator accumulation points. These accumulation point locations are illustrated in Figure 4-2. Figure 4-3 describes the key elements of the base hazardous waste management the figure illustrates, the generator system. As accumulation points collect wastes from the shops and are managed by accumulation point managers. These individuals maintain records on the amount, type of waste, condition of containers, and dates of collec-The accumulation point managers are also sponsible for conducting periodic inspections of The following accumulation points accumulation areas. comprise the operating hazardous waste management system for the base:

- Aircraft Maintenance: AGE Storage Yard (Building #432)
- Aircraft Maintenance: Engine Shop (Building #201)







WILLOW GROVE ARF 913TH TAG (1980 TO PRESENT)

4-7

## WESTERN

- Aircraft Maintenance: Paint Shop (Building #201)
- POL: Underground Waste Fuel Oil Tank (Building #208)
- Civil Engineering: Paint Storage Building (Building #205)
- Open Storage Area No. 42: Base Supply Secure Storage

The Open Storage area is intended to be a secure area for temporary accumulation of used petroleum products, hazardous materials and wastes, prior to pickup by the DPDO contractor. This site will be discussed in more detail in Section 5, because it is recommended for further confirmation analysis.

The list of hazardous wastes/materials generated by the 913th TAG are shown in Table 4-1. Also shown is the hazard classification, typical amount generated monthly, and type of accumulation point. Table 4-1 indicates that the major hazard associated with the wastes generated by the 913th TAG is flammability. All wastes generated are stored above ground in drums, with the exception of contaminated JP-4 fuel, which is stored in an underground tank.

As shown in Figure 4-3, materials accumulated at Open Storage Area No. 42 are picked up by DPDO Philadelphia when requested bу Base Supply. Other materials accumulated by Base Civil Engineering, such as oily wastes (from the seven oil/water separators the grease, solvents, and washdown solutions picked up by commercial disposal contractors. This is also the primary method of disposal for contaminated JP-4 fuel oil generated at the POL fuel farm. Table 4-2 summarizes the shop-by-shop generation of hazardous materials/wastes at the 913th TAG.



TABLE 4-1

### HAZARDOUS MATERIAL/WASTE GENERATION 913th TAG WILLOW GROVE AIR RESERVE FACILITY

Common/Chemical Name	Hazard. Class	Typical Monthly Qty. Gener.	Type of Storage
Contaminated JP-4	Flammable Liquid	315 Gal.	2,000 Gal. Under- ground Storage Tank
PD-680 Degreaser	Flammable Liquid	70 Gal.	55 Gal. Drums
Lacquer & Enamel Stripper	Flammable Liquid	4 Gal.	5 Gal. Drums
Epoxy Stripper	Flammable Liquid	4 Gal.	5 Gal. Drums
Astrocoat Stripper	Flammable Liquid	10 Gal.	5 Gal. Drums
Polyurethane Thinner	Flammable Liquid	10 Gal.	5 Gal. Drums
Acetone	Flammable Liquid	10 Gal.	5 Gal. Drums
Toluene	Flammable Liquid	20 Gal.	5 Gal. Drums
Poly-Primer Thinner	Flammable Liquid	6 Gal.	5 Gal. Drums
Acrylic Thinner	Flammable Liquid	20 Gal.	5 Gal. Drums
Mythyl Ethyl Ketone	Flammable Liquid	8 Gal.	5 Gal. Drums
Isopropyl Alcohol	Flammable Liquid	2 Gal.	5 Gal. Drums
Paint & Dope Thinner	Flammable Liquid	20 Gal.	5 Gal. Drums
Aircraft Engine Oil	Flammable Liquid	50 Gal.	55 Gal. Drums
Mineral Oil	Flammable Liquid	20 Gal.	55 Gal. Drums
Hydraulic Fluid	Flammable Liquid	30 Gal.	55 Gal. Drums

TABLE 4-2

SHOP-BY-SHOP HAZARDOUS MATERIALS/WASTES GENERATION - 913th TAG (1957 to Present)

			WESTERN .				
Waste Management Practices 1960 1970 1980	+ Pire Training DPDO + Sanitary Sewer	+ Neutralized to Sanitary Sewepment	Contractor/Fire Training -   FDFDO -     Contractor	FContractor/Fire Training ←DFDO-	<pre>HContractor/Fire Training - + DPDO==+ HContractor/Fire Training - + DPDO==+ HContractor DPDO==+</pre>	Contractor	<pre>FContractor or Fire Training-PDFDO==&gt; FContractor or Fire Training-PDFDO==&gt;</pre>
Waste Quantity	220 gal./yr. 55 gal./yr. 2 gal./yr.	350 gal./yr.	40 gal./mo. 40 gal./mo. 12 gal./yr. 12 gal./yr. 45 gal./mo. 1-1/2 gal./yr. 16 gal./mo.	12 gal./yr.	50 gal/yr Unknown 50 gal./yr.	10 gal./yr. Unknown	4 gal./mo. 80 gal./yr.
Waste Materials	PD-680 Solvent Penetone Power Cleaner 155 Lubricating Oil	Sulfuric Acid	Acetone Toluene Epoxy Stripper Astrocoat Stripper Paint Thinners Alodine 1201 Zinc Chromate	111 Trichloroethane	Motor Oils 111 Trichloroethane Grease	Film Developer ZY-GLO Developer	<pre>111 Trichloroethane   (Inhibisol)   PD-680</pre>
Location (Building Number)	201	201	201	rt 201	op 201	201	cs 201
Shop	AGE	Battery	Oprrosion Control	Life Support 201	Machine Shop 201	IQI	Preudraulics 201

TABLE 4-2 (Con't)

SHOP-BY-SHOP HAZARDOUS MATERIALS/WASTES GENERATION - 913th TMG (1957 to Present)

		. Ø	<b>TELIFE</b> IN
Waste Management Practices 1960 1970 1980	F Contractor/Fire Training DPD F Contractor/Fire Training DPD Contractor/Fire Training DPD	<pre>⊢Contractor/Fire Training I=DFDO==+</pre> ⊢Contractor/Fire Training I=DFDO==+	<pre>⊢Contractor/Fire Training I - DFDO Contractor/Fire Training I - DFDO</pre>
Waste Quantity	500 gal./yr. 10 gal./yr. Unknown	12 gal./yr. 100 gal./yr.	500 gal./yr. 2 gal./mo.
Waste Materials	JP-4 Gasoline Fuel Oils	111 Trichloroethane FD-680	PD-680 111 Trichloroethane
Location (Building Number)	231	1 201	ion
Shop	POL	Propulsion	Repair/ Reclamation

## WESTERN

The base has not operated any open dumping or chemical landfill areas during its operations, although occasional spillage of hazardous materials in the past may have occurred near Open Storage Area No. 42. cleaning sludges at the POL area have been buried in accordance with Air Force technical orders. operated landfills have been used for refuse disposal, and most hazardous chemical wastes have been removed from the base for contractor disposal, open burning or DPDO disposal. Up until the mid-1970's, flammable materials/wastes (contaminated fuels. oils. and solvents) were collected by the base fire department for exercises training at the Navy-operated open burning pit. All remaining waste materials (including flammable wastes burned during fire training not exercises) were collected by an off-base contractor for disposal or resale.

materials/waste Hazardous have been segregated in 55-gallon drums for DPDO collection since about 1975. The overall goal of DoD has been to implement a plan for recovery of waste petroleum products. Waste-generating activities (base shops) produce either recoverable products or waste products. Waste products are suitable for any use, because of excessive contamination or degradation, and cannot be reprocessed or re-refined. Recoverable products, however, can be either reclaimed (used to meet another grade or specification without re-refining) or recycled (recovered for original use or specification through reprocessing). of the recoverable products at the 913th TAG handled by DPDO include:

- Aviation Fuels
- Ground Fuels

- Engine and Equipment Lubricating Oils
- Petroleum-base Solvents
- Hydraulic Fluids
- Calibrating and Purging Fluids

### 4.3 111th Pa AIR NATIONAL GUARD


The lllth PaANG industrial operations include a variety of aircraft repair and maintenance activities. The facilities of the lllth PaANG are shown in Figure 4-3. The major aircraft maintenance work centers are in Building \$320, which is the location for Buildings \$330 and \$340, which are the major aircraft maintenance hangars.

A summary of the major types of hazardous materials/hazardous wastes handled by the lllth PaANG is shown in Table 4-3. As shown, the monthly generation of these materials is relatively small. Table 4-4 presents estimates of hazardous waste quantities and methods of disposal for each major shop. The lllth PaANG started operating at Willow Grove in 1963, and, therefore, the information presented includes 1963 to present.

### 4.4 FUELS MANAGEMENT

### 4.4.1 POL Fuel Area

The fuels management system at the Willow Grove ARF comprises the POL area, which is located in the north-central section of the base, as well as other fuel storage tanks throughout the base. Table 4-5 outlines these fuel storage tanks, and Figure 4-5 provides a schematic of the fuel tanks. The POL consists of two concrete-lined areas for aircraft fuel storage tanks.





### TABLE 4-3

# HAZARDOUS MATERIAL/WASTE GENERATION 111th PaANG WILLOW GROVE AIR RESERVE FACILITY

Common/Chemical Name	Hazard. Class	Typical Monthly Qty. Gener.	Type of Storage
PD-680 Degreaser	Flammable Liquid	50 Gal.	55 Gallon Drums
Hydraulic Fluid	Flammable Liquid	20 Gal.	55 Gallon Drums
Mineral Oil	Flammable Liquid	2 Gal.	55 Gallon Drums
Aircraft Engine Oil	Flammable Liquid	30 Gal.	55 Gallon Drums
Toluene	Flammable Liquid	2 Gal.	5 Gallon Drums
Paint & Dope Thinner	Flammable Liquid	2 Gal.	5 Gallon Drums
Sulfuric Acid H <sub>2</sub> SO <sub>4</sub> (Battery Acid)	Corrosive	2 Gal.	5 Gallon Drums
Used Motor Oil and Hydraulic Fluids	Flammable Liquid	40 Gal.	55 Gallon Drums

TABLE 1

SHOP-BY-SHOP HAZARDOUS MATERIAL/WASTE GENERATION - 111th PAANG (1963 to Present)

			W.E		3		
Waste Management Practices 1960 1970 1980	► Sanitary Sewer/Contr	OPDO	Sanitary Sewer	Sanitary Sewer	Contractor Disposal	DPDO	Contractor Disposal
Waste Quantity M66) (1966-Present)	4 cans/yr.	6/то.	1/2 gal./yr.	l qt./mo.	40 cans/yr.	2 gal./mo.	1.2 cu.yd./mo.
<u>Waste</u> (1963–1966)	3 cans/yr.	5/mo.	1/3 gal./yr.	1 qt./mo.	20 cans/yr.	l gal./mo.	1 cu.yd./mo.
Waste Materials	Bromochloromethane	Bmpty Lead Acid Batteries	Acetic Acid	NH-5 Hypoconcentrate,	Empty Paint Cans, Thinner Cans, Spray Cans, and Cleaning Cloths	Paint Thinner	Cleaning Cloths and Granular Materials for Collection of Oil Droppings, Contaminated with Oil and Brake Fluid; Empty Oil Cans
Location (Building Number)	232	310	300	300	320, 330, 340	320, 330,340	320, 330, 340
Shop (Bu	Base Civil Engineering	Base Supply 310	Base Photo Lab	Base Photo Lab	Aircraft Maintenance	Aircraft Maintenance	Aircraft Maintenance 3

TABLE 4-4 (Con't)

マンスを見てつつつつのでは<br/>
を開きるのの名の<br/>
を開きるのの名の<br/>
を開きるのの名の<br/>
を開きるのの名の<br/>
を開きるのの名の<br/>
を開きるのの名の<br/>
を見きるのできる。<br/>

SHOP-BY-SHOP HAZARDOUS MATERIAL/WASTE GENERATION - 111th PaanG (1963 to Present)

1	1 4	,	<b>ल्लिं</b>				
Waste Management Practices 1960 1970 1980	+ -Contractor Digno-	-Pire Training- HOPDO-	Ogig	► -Contractor +DPD0	Fire Training- FDFD0	►-Neutrlz./Sanitary Sewer	DPDO
Waste Quantity M6) (1966-Present)	3 qt./mo.	5 gal./mo.	40 gal./mo.	.8 gal./mo.	2 gal./mo.	2 qt./mo.	40 gal./mo.
<u>Waste</u> (1963-1966)	2 qt./mo.	3 gal./mo	50 gal./mo.	.5 gal./mo.	l gal./mo.	1 qt./mo.	40 gal./mo.
Waste Materials	Hydraulic Fluid	PD-680 Degreaser	Waste Engine Oil	Hydraulic Fluid	PD-680 Degreaser	Hydrochloric Acid	Used Motor Oil
Location (Building Number)	drcraft 320, Maintenance 330, 340	Waintenance 330, 340	Wircraft 320, Waintenance 330, 340	ranspor- 350 tation Motor Pool	ranspor- 350 tation Motor Rool	ranspor- 350 tation Motor Pool	ranspor— 350 tation Motor Pool
Shop	Aircraft Mainten	Aircraft Mainten	Aircraft Mainten	Transportation M Fool	Transportation M Fool	Transportation M Pool	Transportation M Fool

TABLE 4-4 (Con't)

SHOP-BY-SHOP HAZARDOUS MATERIAL/WASTE GENERATION - 111th PAANG (1963 to Present)

Shop	Location (Building Number)	Waste Materials	Waste (	Waste Quantity 766) (1966-Present)	Waste Management Practices 1960 1970 1980
Transportation Motor Pool	350 tor	Bmpty Paint Cans, Thinner 80 cans/yr. Cans, Spray Cans, and Cleaning Cloths	80 cans/yr.	160 cans/yr.	Contractor
Transpor- tation Motor Pool	350 tor	Paint Thinner	2 gal./mo.	3 gal./mo.	OPTO
Transportation Motor Pool	350 tor	Cleaning Cloths and Granular Material for Collection of Oil Droppings, Contaminated with Brake Fluid; Oil Cans	1 cu.yd./mo.	1.5 cu.yd./mo.	Contractor
Transportation Motor Pool	350 tor	Battery Acid "Sulfuric"	1 gal./mo.	1.2 gal./mo.	meNeutrlz./Sanitary Sewer

## W STEEN

FUEL STORAGE TANKS
WILLOW GROVE AIR RESERVE FACILITY

<del></del>	<del></del>			
Location	Fuel Type	Capacity (gal.)	Above or Below Ground	Tank Type
Power Plant Bldg. 212	No. 2 Fuel Oil	588	Above	Steel
Maint. Hangar Bldg. 201	Waste Oil (Separator)	250	Below	Steel
Maint. Hangar Bldg. 201	Waste Oil (Separator)	250	Below	Steel
FOL Bldg. 208	POL Waste Oil	2,000	Below	Steel
Pump Station Bldg. 211	Diesel Fuel	533	Below	Steel
Well House Bldg. 209	Diesel Fuel	533	Below	Steel
Lift Station Bldg. 220	Diesel Fuel	275	Below	Steel
PaANG Maint. Bldg. 330	Waste Oil (Separator)	275	Below	Steel
Admin. Bldg. 203	Diesel Fuel	275	Below	Steel
PaANG Motor Pool Bldg. 3 F'glass	52	Gasoline	6,000	Below
ANG Motor Pool Bldg. 352	Diesel Fuel	6,000	Below	F'glass
ANG Motor Pool Bldg. 350	Waste Oil (Separator)	850	Below	F'glass
Puel Cell Repair Bldg. 230	Waste Oil (Separator)	5,000	Below	Concrete
Fuel Cell Repair Bldg. 230	No. 2 Fuel Oil	6,000	Below	Steel
POL Lab Bldg. 231	No. 2 Fuel Oil	1,000	Below	Steel
POL Lab Bldg. 231	Waste Oil (Separator)	150	Below	F'glass
CE Yard Bldg. 232	Waste Oil (Separator)	150	Below	F'glass
POL Tank 207	JP-4 Fuel	210,000	Above	Steel
Power Plant Tank 221	No 6 Fuel Oil	20,000	Above	Steel
POL Area Tank 222	No. 6 Fuel Oil	14,994	Above	Steel
FOL Tank 224	JP-4 Fuel	105,000	Above	Steel

resident minimizations residentials

THE WASHINGTON TO CONTROL OF THE WASHINGTON THE WAS

## W.S.E.

The two storage tanks (\$207 - 210,000 gallons and \$224 - 105,000 gallons) contain JP-4. Each steel tank is constructed above ground within a separate containment dike. The containment volume of each dike is greater than the tank capacity plus one foot freeboard.

Drains from the containment dike areas are equipped with manual valves to remove rainwater. All drainage flows through a catch basin before discharge into the base holding pond. The concrete-lined dikes and catch basin were constructed in 1981. During these tank reconstruction activities, a french drain system was installed under Tank \$207 to collect and drain high groundwater flows into the sump. The french drain did not operate properly and was subsequently abandoned.

The POL area contains a storage tank for heating oil, with a capacity of 15,000 gallons. The tank is located on a raised platform with no spill containment structures. The tank is currently empty, but was used from 1958 to 1971 for the storage of aviation lube oils, and from 1978 to 1984 for the storage of #6 fuel oil as a backup supply for the heating plant.

In addition to the above-ground heating oil tank, the POL area contains an underground waste oil tank with a capacity of 2,000 gallons. Contaminated JP-4 fuel is stored in this tank prior to removal and disposal. Removal is contracted out approximately twice a year. Prior to 1980, these waste fuels were burned for fire training exercises.

Five fuel storage tank trucks, each with a 5,000 gallon capacity are maintained on the base. Four of the trucks are used for JP-4 jet fuel and the fifth is used for MOGAS. No spill containment measures exist for the tank truck loading/unloading areas.



Tank inspections and cleaning activities are performed at a 3-year frequency. The tank contents are pumped down for use as far as possible, and the remaining fuel and contaminated fuel/residue is removed by contractor. The sludge is removed and disposed through the contractor. Until mid-1970's, this tank residue was buried within the POL area.

### 4.4.2 Fuel Spills

Small fuel spills have occurred frequently throughout many areas of the base, predominantly on the flightline and the aircraft apron. Table 4-6 outlines a compilation of small fuel spills as described within base fire department records. Small fuel spills on paved areas have been typically washed down by the fire department with the resulting wastewater flowing through storm sewers to the base holding pond.

The base Spill Prevention Control and Countermeasures Plan (SPCC Plan) outlines four additional areas where polluting substances are stored and contaminated spills are possible. These areas include:

- POL Storage Tank Areas
- Heating Oil Storage Tank (#212)
- Heating Plant Oil Storage Tank (#221)
- Tank Truck Area

At least three significant fuel spills have been identified at the POL storage tank area, and a smaller fuel oil spill has been identified at the Heating Plant oil storage tank. Approximately 50 gallons of \$6 fuel oil was spilled in the winter 1984 during refueling



### TABLE 4-6

### SUMMARY OF SMALL OUANTITY FUEL SPILL RESPONSES (October 1980 - May 1983)


	Date	Spill Location	Ç	stimated Quantity (gal.)
24	October 1980	AF Ramp	Fuel Spill Wash Down	50
	November 1980	AF Ramp C-130 Line	Meter Fuel Line on Vehicle	10
	-	AF Ramp	Wash Down Defuel Truck Leak	_
	February 1981		Fuel Spill Wash Down	10
	February 1981		Re_ueling Truck Spill	10
	February 1981	AF Ramp	Fuel Spill Wash Down	20
	March 1981	AF Ramp	Fuel Spill from Valve	20
	May 1981	AF Hangar 201	Disconnect Fuel Line	10
	May 1981	AF Hangar 201	Fuel Spill Wash Down	20
	May 1981	AF Ramp	Fuel Leak at Engine	20
	May 1981	AF Ramp B-1	Fuel Spill Wash Down	10
	May 1981 June 1981	Paang Ramp	Fuel Spill Wash Down	10 10
	June 1981	Paang Ramp Paang Ramp	Fuel Spill Wash Down Fuel Spill Wash Down	20
		Engine Test Stand	Fuel Spill Wash Down	20 20
	July 1981	PaANG Ramp	Fuel Spill Wash Down	25 25
	July 1981	AF Ramp	Fuel Spill Wash Down	20
	July 1981	AF Fuel Dock	Fuel Leak from Engine	10
15	July 1981	AF Ramp	Fuel Gasket Leak	10
15	July 1981	AF Ramp	Fuel Spill Wash Down	25
	July 1981	Old A Turnup Pad		50
	July 1981	PaANG Ramp	Fuel Spill Wash Down	10
	August 1981	AF Line	Fuel Spill Wash Down	20
	August 1981	A37 Line	Fuel Spill Wash Down	20
	August 1981	AF Spot C4	Fuel Spill Wash Down	10
	August 1981	AF POL Area	Open Air/Fuel Vent Release	40
		Rear of Bldg. 320	Top of Truck Spill	10
	October 1981	Hangar 201-S. Ramp		25
17	November 1981	TA-37 Line	Fuel Spill Wash Down	10
3	December 1981	PaANG Ramp	Fuel Spill Wash Down	10
30	December 1981	Paang Ramp Paang Ramp A-37 Line	Fuel Spill Wash Down	10
	January 1982		Fuel Spill Wash Down	10
	January 1982	PaANG Ramp	Fuel Spill Wash Down	20
	January 1982	C-130 Line	Fuel Spill Wash Down	20
	February 1982		Fuel Spill Wash Down	20
	March 1982	A-37 Line	Fuel Spill Wash Down	10
	April 1982	PaANG Parking Ramp		20
	April 1982	PaANG Parking Ramp	Fuel Spill Wash Down	10
30	April 1982	AF Parking Ramp	Fuel Spill Wash Down	20


## WESTERN

### TABLE 4-6 (Con't)

### SUMMARY OF SMALL OUANTITY FUEL SPILL RESPONSES (October 1980 - May 1983)

			<del></del>	<del></del>
	Date	Spill Location		Estimated Quantity (gal.)
2	May 1982	AF Ramo	Fuel Spill Wash Down	10
2	May 1982	AF Ramp	Fuel Spill Wash Down	
13	May 1982	C-130 Line	Fuel Spill Wash Down	10
8	June 1982	AF/PaANG Line Rear of Bldg. 320 C-130 Line	Fuel Spill Wash Down JP-4 & Soil Cleanup Fuel Spill Wash Down	20
	June 1982	Rear of Bldg. 320	JP-4 & Soil Cleanup	250
	July 1982	C-130 Line	Fuel Spill Wash Down	40
	.ไม่ไข 1982	PalNG Runum Area	A-37 Dumping Fuel	15
	August 1982	AF Ramp PaANG Ramp A-37 Line	A-37 Dumping Fuel Fuel Spill Wash Down Fuel Spill Wash Down Fuel Spill Wash Down Fuel Spill Wash Down	10 10 25
19	August 1982	PaANG Ramp	Fuel Spill Wash Down	10
7	September 1982	A-37 Line	Fuel Spill Wash Down	25
11	September 1982	A-37 Nose Dock #1	Fuel Spill Wash Down	10
21	September 1982	AF Ramo Spot 1	MUEL SOILL WASH DOWN	20
	October 1982	AF Ramp	Leaking Fuel Truck	100
2	October 1982	AF Ramp	Wash Fuel Truck Compartmen	nt 10
6	October 1982	Paang Ramp	Leaking Fuel Truck Wash Fuel Truck Compartmen Spill JP-4 Spill JP-4 Maintenance Control Spill	10
6	October 1982	Paang Ramp	Spill JP-4	10
6	October 1982	PaANG Ramp	Maintenance Control Spill Spill JP-4 Fuel Spill Wash Down	10
14	October 1982	PaANG Ramp	Spill JP-4	10
21	October 1982	PaANG Prkq.Ramp A-37	Fuel Spill Wash Down	25
27	October 1982	A-37 Line	Fuel Spill Wash Down	110
3	November 1982	AF Ramp	Fuel Spill Wash Down	25
13	November 1982	AF Ramp	Fuel Spill Wash Down	10
27	December 1982	Paang Ramp	Fuel Spill Wash Down	10
21	January 1983	PaANG A-37 Ramp	Fuel Spill Wash Down	15
9	February 1983	PaANG Ramp	Fuel Spill Wash Down Fuel Spill Wash Down Fuel Spill Wash Down	15
	March 1983	Spot C-3,C-130 Ramp	Fuel Spill Wash Down	25
5	March 1983	AF Ramp	Fuel Spill Wash Down	10
	March 1983	AF Ramp	Fuel Spill Wash Down	10
5	March 1983	PaANG Ramp	Fuel Spill Wash Down	10
	March 1983	AF Ramp Spot B-3	Fuel Spill Wash Down	15
	April 1983	PaANG Spot 2	Fuel Spill Wash Down Fuel Spill Wash Down Fuel Spill Wash Down	10
	April 1983	AF Ramp AF Ramp	Fuel Spill Wash Down	15
8	May 1983	AF Ramp	Thial Chill Weah Down	40
13	May 1983	A-37 Parking Ramp	Fuel Spill Wash Down Fuel Spill Wash Down	10
26	May 1983	A-37 Parking Ramp AF Ramp	Fuel Spill Wash Down	10





MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A



activities at the heating plant Tank #221. The spill was contained within the concrete dike area, but no cleanup of the earthen base was performed.

Two POL fuel spills occurred in the 1960's when AVGAS was utilized on the base. In 1962, approximately 30,000 gallons of fuel spilled into the gravel and tar containment area from Tank #207 when the floating roof drain malfunctioned. The majority of the spill was collected and reclaimed (estimated at 28,000 gallons). An unknown quantity of fuel was discharged from the POL drain line in 1968 when fuel was mistaken for water and was released from the sump at the base of the tank area.

The most significant fuel spill identified at the POL area occurred in January 1979 when valve leaks at Tank \$207 released an estimated 4,000 to 8,000 gallons of JP-4 into the gravel and tar dike area. Although the spill was contained and a large quantity recovered, migration of the fuel into the soil around the POL area identified. Discharges of pure JP-4 were identified from the sidewall banks of the receiving pond in the summer of 1979. A groundwater monitoring program was initiated in 1980 when well points were installed between Tank #207 and the receiving pond. Absorbent booms have been installed at the discharge point of pond and periodic inspections/replacements continue. soil investigations or cleanup have been initiated, hydrocarbon odors persist in the monitoring wells.

## 4.5 <u>INDUSTRIAL WASTE CONTROL - SANITARY SEWER AND STORM</u> SEWER SYSTEMS AT WILLOW GROVE ARF

Liquid industrial wastes have been controlled at the ARF through an established oil/water separator system and



through waste segregation and containerization. Figure 4-6 illustrates the sanitary sewer system as well as oil/water separators tied into the system. The aircraft maintenance hangars at the 913th TAG and the 111th PaANG contain oil/water separators which are tied into sanitary sewer lines. The fuel cell repair shop and the POL laboratory also contain oil/water separators which are connected to the sanitary sewer lines. The aircraft wash rack is equipped with a settling tank/oil skimmer as well as a trickling filter (used until the mid-1970's) which ties into the sanitary sewer line. vent and detergent mixes have been used for aircraft washing activities at the washrack. In addition, past paint stripping operations have been performed at the Waste oils are skimmed from the wastewater in the settling tank, and the effluent is passed through the trickling filter media. This rock and gravel media is not contained, but final effluent can flow into the sanitary sewer line.

All sanitary sewage flows by gravity to the sanitary sewer lift station (Buildings #206 and #220) where the effluent is monitored and pumped via force main to the trickling filter wastewater treatment plant operated by the Naval Reserve Station. The plant's capacity is 0.5 mgd.

All runoff and surface drainage from the 913th TAG flows along established drainage ditches and storm sewer lines into the ponding basin located at the north-central base property line. The surface drainage system for the base was described in Section 3 and is shown in Figure 3-2.

## W. STATEN

### 4.6 SITE FINDINGS

This section describes the seven sites on Willow Grove ARF which were found to have contamination due to past storage or disposal practices. The sites identified through a number of sources, including AFRES and PaANG files, interviews with base personnel, and field examination. Figure 4-7 shows the locations of the seven sites. Each of the seven sites is recommended for a confirmation study. The confirmation study is discussed in Section 5 - Conclusions, and Section 6 -Recommendations.

### 4.6.1 POL Area - Site No. 1

The POL area is located in the northern perimeter between the Open Storage Area \$42 and the ponding basin. The fenced area is approximately 400 feet by 200 feet, although historically, POL operations have taken place in adjacent areas outside the fence. The POL operations office and fuel testing laboratory are located in Building \$231 east of the fenced area.

POL facilities inside the fenced area include two above-ground JP-4 tanks (#207 and #224), a 15,000-gallon above-ground fuel storage tank, a 2,000-gallon underground waste fuel tank next to the pump house (#208), fueling hydrants, and parking space for seven 5,000-gallon JP-4 tank trucks.

A 5,000-gallon tank truck parked on the street adjacent to the POL office (#231) is used to store and supply MOGAS. The fuel laboratory in Building #231 has an associated below-ground small capacity (150 gallon)

## 

waste tank. All fuels used on-base are transported by truck; there are no underground fuel lines associated with the POL area.

The two JP-4 Tanks #207 and #224 have capacities of 210,000 and 105,000 gallons respectively. They were built during base construction in 1957, and have been used for JP-4 storage since that time. Both are built on a ring of concrete filled with four to five feet of The original berms around the tanks were earthen, lined with a tar-gravel compound. In the summer the berms were rebuilt and lined with concrete. Several spills of between 5,000 and 30,000 gallons of JP-4 are known to have occurred, particularly from #207, before the cement liners were installed. Although these spills are not documented in files, they were reportedly cleaned up with a minimum of loss to the subsurface. The latest spill occurred on January 25, 1979, due to a faulty or frozen roof valve, and is documented in a Pennsylvania Department Environmental of Resources At that time, approximately 8,000 gallons of JP-4 spilled into the moat around #207; 2,000 gallons of water were pumped into the bermed area to seal off the moat bottom, and all fuel was then pumped out and hauled away by a private salvage contractor.

Later in the spring of 1979, Tank \$207 was drained for cleaning and remodeling of the roof. At that time, a leak in the floor of the tank was discovered, which accounted for losses of JP-4 from that tank reported in early 1974. Based on a review of the records, Base Civil Engineering estimates that 8,000 gallons of fuel entered the ground from that leak. Four monitor wells constructed of two-inch PVC were later installed between

## W. STEEN

the POL area and the ponding basin to the east, but there are no records available on well construction or on the results of chemical analyses if samples were taken. During WESTON's site visit in June 1984, there was an obvious odor of JP-4 in the casings of the two middle wells. In addition, oil seepage was visible along the western edge of the ponding basin for a length of about 100 feet.

Other POL operations may have resulted in fuel spills, although none are documented. The above-ground 15,000 gallon tank (#222) is supported by two concrete saddles with no liner or containment at ground surface. used to store 1100 aviation oil (a viscous lube oil for reciprocating engines) from about 1964 to about 1971. It was empty from 1971 to 1978, was used to store #6 furnace fuel from 1978 to early 1984, and is now being converted for MOGAS storage. The area outside the fence to the east, between the fence and Bolling Street, was used in the early 1960's as a bermed storage area. was used approximately one year for storage of 1100 aviation oil in 55-gallon drums, then was left empty until it was filled in 1981 with clean fill and seeded Across the street from this area, on the landing mat between Bolling Street and the west fence of the Open Waste Storage Area #42 (Site No. 2), a 4,000-gallon tank trailer was parked from 1958 to about 1964 and used for storage of 1100 aviation oil before it was replaced by Tank #222. The base fire chief reported that when a welder was called in to cut up some of the landing mat in this area in 1983, his torch set off a series of small ground fires indicating the presence of flammable substances on the soil. No major spills oil are known to have occurred. However, assuming that 20 gallons a year were spilled near the tank during normal operations, as much as 120 gallons could be in the ground from this source.



Another practice which would have contributed to contamination of the ground with fuel oil and metals was burying the sludge from cleaning of Tanks \$207 and \$224. Approximately once every three years, between 1958 and the mid-1970's, these tanks were drained andvacuum cleaned. The thickest, leaded sludge from the tank bottom was scraped out and buried underground in the western corner of the fenced area. An estimated 150 gallons of fuel sludge were buried at this site.

### 4.6.2 Open Storage Area #42 - Site No. 2

The open storage area is an area approximately 200 feet by 150 feet that has been used for storage of hazardous materials/waste in drums and equipment (both operational and non-operational) since construction of the base in 1957. The ground is covered with steel landing mat and The site has historically extended beyond the present fence as far as the edge of Bolling Street to the west. The area was unfenced until 1972, then closed with a barbed wire fence until 1982. In 1982 8-foot tall chain-link fence was installed around the perimeter, although some equipment is still outside the fence on the east side. At that time, a fence was also erected through the middle of the site to segregate drummed hazardous materials/wastes equipment on the west side from gas cylinders on east side. Shelters were erected to protect the gas cylinders which contain nitrogen, oxygen and hydrogen. The rest of the site has been and remains open and uncovered.

The site serves as a central collection and storage point for hazardous materials/wastes generated through the ARF. Following a request by either AFRES or PaANG,

## W. STEEN

Base Supply picks up waste materials in cans or drums at an accumulation point or at an individual shop, and transfers them to the Open Storage Area #42. Approximately once every three months, Base Supply contacts the DPDO, Philadelphia to initiate a pick-up of all materials stored at the site which is made by a private contractor. Certain materials, specifically from the NDI Shop and Medical Services, are never transferred to the Open Storage Area, but are picked up by DPDO directly at the point of generation.

Materials currently at the site include spent engine oil, hydraulic fluid, and solvents (PD-680, 1,1,1,trichloroethane, lacquer thinner, paint stripper). Since 1980 these materials have been segregated into different drums, and an attempt has been made to follow a color coding system for the drums. Drums of new including methanol, de-icing fluid and lube oil, were also observed. At the time of the site approximately 100 drums were stored at the site. The last DPDO pick up had been in January 1984. Most of the drums were stored upright, approximately half of them on wooden pallets; a few drums were lying on their sides. In many places, drums of different types of wastes were stored next to each other or mixed together, and several had no visible label, or coded color band. Several drums of waste engine oil were observed to be leaking onto the ground, and ground discoloration was observed through the landing mat in many places. inside fenced area included stored the fencing, metal shelving, and combat training equipment and approximately 30 empty car battery crates, casings were stored on a pallet next to the gate. transformers were stored on a pallet near the west

というというということののののであるというというというというと



fence. However, they do not contain PCB's. Although the gate is locked, access to the site is not restricted to Base Supply. Several services in both the AFRES and PaANG have keys to the site to permit loading and unloading of equipment. Traffic is particularly heavy during weekend training periods, increasing the chances of damage to the waste containers.

## 4.6.3 Ponding Basin - Site No. 3

The ponding basin is a man-made pond approximately two and a half acres in area. It was built by damming and excavating a stream bed at the natural low point of the property when the facility was first developed in 1957. The original capacity of the pond was 3.5 million gallons, and in the summer of 1979 it was enlarged to 5.8 million gallons. The ponding basin receives all storm runoff from the ARF and a portion of the storm runoff from the NAS.

The ponding basin is operated by the U.S. Navy Public Works Water Supply and Wastewater Treatment Facility as a catchment pond where floating products (oil or detergent) can be removed from surface water before it is discharged from the property. Prior to 1979, the pond was maintained at a single level. After enlargement in 1979, it was equipped with a gate which can be manually adjusted according to rainfall and rate of runoff. The discharge area is equipped with two sets of absorbent booms designed to skim petroleum products from the water surface. When large slicks of oil or foaming detergents form on the surface, a private contractor is called in to pump them off.



Due to its position at the discharge point for surface water and its function as a retention pond, the ponding basin is suspected of being the receptacle of a variety of wastes over the last 26 years. Fuels, solvents and detergents are likely to have been carried to ponding basin through the storm sewer system due to improper handling or accidental spills on the flight in shop areas or in the POL area. When the pondwas enlarged in 1979, JP-4 was observed flowing into Lhe excavated along the area bedrock-overburden interface on the east bank, and oil seeps are still evidence today. Most floating and soluble waste products would have been skimmed off or washed downstream to Graeme Park and Park Creek. In fact, several fish kills have reportedly occurred downstream during the years of base operation. These were not documented, however, in either Air Force or Pennsylvania Department of Environmental Resources addition, the heavier solid components of liquid wastes may have settled to the bottom of the pond and become bound in the bottom sediments.

### 4.6.4 Washrack Area - Site No. 4

The washrack area includes the washrack, (located southeast of Hangar 201), and associated structures including an oil/water separator and filter bed, two paint storage buildings (#215 and #223), the grassy area (approximately 50 feet by 50 feet) contained between these structures, and a ditch to the east.

The washrack is used primarily for washing aircraft from both AFRES and PaANG facilities. Personnel from the Paint Shop in Hangar 201 are responsible for supervising aircraft washing for the 913th TAG. Since 1979, air-

## WESTERN

craft washing has been done by a private contractor. Currently, approximately 20 aircraft a year are washed on the washrack. In the past, as many as 160 aircraft a year have been washed there. Since 1979, approximately 10 gallons per aircraft of Super II Detergent (Mil. Spec. No. C-25769) have been used, and two gallons per aircraft of "soil barrier", an anti-corrosion painted on behind the engines after washing. thepast, a cleanser/solvent (Mil. Spec. No. C-43616B) was used in combination with the detergent for aircraft cleaning. A small amount of the solvent PD-680 is still sprayed on parts of the aircraft to loosen dirt just before washing.

A secondary use for the washrack has been paint stripping. Parts too large to fit in a dip tank have been stripped directly on the washrack, then Other small parts have been hosed off on the washrack after stripping in a tank. Solvents used in stripping include lacquer and enamel strippers, epoxy stripper, astrocoat stripper and methyl ethyl ketone gallons per (MEK). Approximately five strippers are used in the paint shop. It can be assumed that approximately 20% of these are not recovered, are instead flushed into the washrack effluent treatment system, amounting to 12 gallons per year.

A portion of the washrack effluent is passed through a filter bed which is in direct connection with the subsurface, probably at or very close to the water table. The estimated depth to bedrock at this site is six feet, and the stone filter bed appears to have been excavated to that depth based on design drawings provided by AFRES-CE. Assuming that an average of 30

## CXESTEN.

aircraft a year were washed on the washrack over 26-year period, and that 12 gallons per year of paint strippers were discharged in the effluent, estimated that 7,800 gallons of detergent (including solvent), and 300 gallons of paint strippers, have been discharged to the disposal system in the operating life of the ARF. Of this, it can be assumed that approximately 10% was lost to the ground. Thus 780 gallons of detergent/solvent and 30 gallons of paint strippers have reached the groundwater system. In addition, small portion of the oils and fuel combustion by-products washed from the aircraft may have also reached the aquifer.

to the washrack area are Immediately adiacent storage buildings (Building #215 and #223), historically used for storage of partially used containers of paint, thinners, paint strippers, solvents paint Since 1983, Building #215 has been used to house a cold dip tank containing the stripper B&B Touch-up stripping using solvents such as MEK is also performed in the shed by the 913th TAG, and outdoors back of the shed by the 111th PaANG. Evidence vegetation stress around this building indicates that improper handling of these materials may have It is not possible, in some spillage to the ground. however, to quantify these losses.

## 4.6.5 Building #330 Waste Oil Storage Area - Site No. 5

The Waste Oil Storage Area is a relatively small area (100 sq. ft.) behind Building \$330 which was used as a storage area for an above ground tank (bowser). The bowser was used between 1970 to 1980 as a receptacle of waste oils from various shops of the 111th PaANG.

## WESTEN

The bowser was removed in 1980, however, evidence of oil contamination was found in the area around the tank. Overfilling and spillage was reported to occur in quantities ranging from 100 to 200 gallons per year. Over the period of 10 years, it is estimated that 1,000 to 2,000 gallons of waste oils and solvents were discharged on to the ground in this area.

Adjacent to this site, a spill of about 300 gallons of JP-4 fuel occurred in 1982. The spill occurred on an area used for storage of vehicles, now referred to an Antenna Hill. It was reported that the Base Fire Department responded, foamed the area, and excavated the contaminated soil. However, it is possible that some of the JP-4 migrated down into the soil.

## 4.6.6 Heating Plant - Site No. 6

The heating plant (Building #212) supplies heat in the form of hot water to 14 buildings on the ARF. Two furnaces in the building produce approximately 34,000,000 BTU/hour.

The plant is operated by a private contractor on a 3-year contract. The current contractor has been in charge of the building for approximately two years. No records were available on historic operations by previous contractors.

The plant burns \$6 fuel oil at the rate of approximately 320,000 gallons per year. A small amount (approximately 500 gallons per year) of \$2 fuel oil is used to fire up the furnaces and purge the fuel lines after a burn period. Chemicals used at the plant include small

## WESTEN

amounts (approximately 20 gallons per year) of solvents such as petroleum naptha, corrosion inhibitors (e.g. Acidine), and water softening chemicals used to pretreat water heated in the furnaces (OS15G - liquid oxygen scavenger, BSC-30G - alkalinity control agent, and sludge dispersant).

Two, \$6 fuel oil storage tanks are located in an open area east of the building. The older \$6 fuel oil storage tank (\$221) has a capacity of 20,000 gallons. A new 15,000-gallon tank was installed in summer of 1983. Both are installed above ground and have containment walls, but no liners to prevent downward infiltration. In early 1984, Tank \$221 was overtopped, and 20 to 30 gallons of \$6 fuel oil were spilled on the ground below the tank. At the time of the WESTON site visit, no action had been taken to clean up this spill.

The \$2 fuel oil is stored in a 600-gallon tank on the west side of Building \$212. Other chemicals are stored in miscellaneous drums in and around the building. Based on observed handling practices during the site visit, there is a possibility that spills or leaks of other compounds besides \$6 fuel oil could have occurred.

## 4.6.7 Old Well House - Site No. 7

The old well house is a small building (\$205) located on the northern corner of the ARF property built over Well AF-2. This building housed the well pump in the past and is underlain in part by a valve pit housing the top of the well casing, the T-connection to the main distribution lines, and valves for these lines. Use of the well was discontinued in 1962 and the pump was removed.



The well casing was flanged off above ground surface in the well house. However, the floor of the well house is open to the valve pit below through a hole around the well casing. The valve pit generally has some water ponded in it, and the type and integrity of the seal between this pit and the well casing could not be ascertained.

The building has been used since 1962 by Base Civil Engineering for storage of unused and partially used cans of paint, paint thinner, lacquer thinner and paint wastes. Since 1983, it has become a designated "waste accumulation point". Materials in the well house include approximately 30, one-gallon cans of paint and paint thinner inside the building. There were ten, one-gallon and five-gallon cans outside the building, including two full cans labeled 'Toluene- Technical', and miscellaneous five-gallon cans of unknown materials.



#### SECTION 5

### CONCLUSIONS

### 5.1 INTRODUCTION

This section summarizes the conclusions reached relative to the need for further confirmation studies at each of the seven sites discussed in the previous section. The seven sites are listed in Table 5-1 in order of descending priority, based on the Hazard Assessment Rating Methodology (HARM) scores. The HARM methodology is described in Appendix D. Rating forms for each site are presented in Appendix E. The objective of the Phase I Study is to develop sufficient evidence to justify further confirmation studies in Phase II.

All seven sites identified were rated as having sufficient reason to justify further confirmation analysis. A summary of the conclusions for each site is presented in the subsections below.

### 5.2 POL AREA - SITE NO. 1

Sufficient evidence exists that a significant volume (8,000 to 10,000 gallons) of JP-4 has been discharged in the past and may have migrated into the water table beneath the POL area.

In addition, there may be smaller amounts of 1100 aviation oil, MOGAS and #6 furnace fuel in the ground from undocumented spills or leaks associated with past



## TABLE 5-1

# SUMMARY OF WASTE TYPES AND HARM SCORES FOR CONFIRMATION SITES AT WILLOW GROVE ARF

Site Number	Site Name	Waste Type	HARM Score
1	POL Area	JP-4 Fuel JP-4 Fuel Sludge 1100 Aviation Fuel	82
2	Open Waste Storage Area #42	Engine Oil Hydraulic Fluid Solvents (PD-680,1,1,1-Tri- chloroeth ne, Lacquer Thinner, Paint Stripper) Methanol De-Icing Fluid (Ethylene Glycol)	79
3	Ponding Basin	JP-4 Fuel Other Fuel Oils Solvents	70
4	Washrack Area	Super II Detergent Solvents (PD-680, Dexyl) Paint Strippers (Lacquer and Enamel Stripper, MEK)	69
5	Building #330 Waste Oil Storage Area		69



# TABLE 5-1 (Con't)

# SUMMARY OF WASTE TYPES AND HARM SCORES FOR CONFIRMATION SITES AT WILLOW GROVE ARF

Site Number	Site	Name	Waste Type	HARM Score
6	Heating	Plant	<pre>#6 Fuel Oil #2 Fuel Oil Solvents (Petroleum Naptha) Corrosion Inhibitor (Acidine) Liquid Oxygen Scavenger Alkalinity Control Agent</pre>	66
7	Old Wel	l House	Paint and Paint Wastes Paint Thinners Solvents (Toluene)	57



POL operations. The potential for migration is high, since the water table is shallow. During remodeling of Tank #207, a special drain had to be put in to drain off seasonally high groundwater from beneath the tank and fuel has been observed in monitor wells and in oily seeps on the edge of the ponding Since the full extent of the fuel plume and the of contamination of the underlying bedrock aquifer are not known at this time, the POL site is recommended for further confirmation. Specific recommendations for a confirmation study at this site are given in Section 6.

### 5.3 OPEN STORAGE AREA #42 - SITE NO. 2

Although it is difficult to quantify the amount of spillage and leakage of waste oils and other hazardous materials at the Open Storage Area #42, the evidence is strong that contamination has occurred at this site.

The potential exists for contaminant migration to both surface and groundwater from the site. The landing mat covering the ground does not constitute a barrier to infiltration, so that spilled materials can directly percolate the ground. However, the mat does offer some protection from surface erosion. The ground slopes to the northeast, allowing runoff to flow across Andrews Street into the perimeter ditch leading to the ponding basins, either by overland flow or through culverts at the northeast corner of the site. Assuming that the water table is approximately coincident with the bedrock surface, depth to groundwater beneath the site is about 12 feet. Surface soils at the site are moderately permeable Lawrenceville silt loam, indicating



contaminants could have migrated downward to the water table. Recommendations for confirmation analysis at this site are presented in Chapter 6.

### 5.4 PONDING BASIN - SITE NO. 3

Sufficient evidence exists that the ponding basin has served as a receptacle of JP-4 waste oils and solvents, which have been washed off in runoff from various areas of the ARF. Although the amount of contamination is difficult to quantify, the use of the ponding basin as a stormwater receptacle for 26 years strongly suggests that a sufficient amount of contamination exists to warrant further confirmation analysis.

The potential for migration from the ponding exists through both surface and groundwater. According to Base Civil Engineering, the basin is excavated into bedrock well below the water table, and will partially refill with groundwater seepage if it is drained. therefore, be considered a good hydraulic connection with the underlying aquifer and subject to contaminant exchange with that aquifer. For reason, it is concluded that the ponding basin should be confirmation study in Recommendations for a confirmation study for this site are presented in Section 6.

### 5.5 WASHRACK AREA - SITE NO. 4

It has been determined that sufficient quantities of solvents and paint strippers were discharged onto the ground at this site over the past 26 years from aircraft and parts cleaning activities.



Based on the high likelihood of direct discharge to the subsurface, the washrack area, including the paint sheds and adjacent open area, are recommended for confirmation In addition to the potential for study. through the groundwater pathway, there is evidence of both direct runoff and seepage from this area to a drainage ditch immediately adjacent on two sides to the southeast and northeast. This ditch is relatively to three feet below ground surface) and may intercept seasonal high groundwater. An oily seep was observed on the bank of the ditch adjacent to the washrack just upstream from Eglin Street.

### 5.6 BUILDING #330 WASTE OIL STORAGE AREA - SITE NO. 5

Visual observation and interviews with ARF personnel strongly suggest that oil contamination occurred at this site over a ten-year period (1970 to 1980). The soils are moderately well drained in this area and groundwater contamination could have occurred. It is estimated that the water table is 10 to 12 feet below the ground surface at the site. Recommendations for further confirmation are given in Section 6.

### 5.7 HEATING PLANT - SITE NO. 6

Based on visual observation, it appears that an undetermined quantity of #6 fuel oil and perhaps hazardous chemicals were spilled or discharged to the ground at this site.

There is potential for contaminant migration from the site through either the storm drain into the surface water system or through the subsurface to groundwater.

## W. STEEN

The static water table is estimated to be coincident with the bedrock surface at approximately eight feet below ground surface. Due to the proximity of the site to supply well AF-1, (approximately 200 feet), groundwater levels, flow directions and flow velocity are likely to be strongly influenced by pumping from that well. The site is recommended for further confirmation as discussed in Section 6.

## 5.8 OLD WELL HOUSE (BUILDING \$205) - SITE NO. 7

It is not possible to document how much, if hazardous material have been spilled or leaked in the vicinity of Building #205. However, observations of indicated that spills may have occurred. The potential for contaminant migration from the site is high because of proximity to the base boundary and because many products spilled in or near the building would most likely end up in the valve pit. valve pit floods, it drains through an outlet pipe into the perimeter ditch, which appears to spill out onto adjacent (off-base) property during high-flow events. During periods of low or no runoff, standing water in the valve pit may seep into the ground, and could run down the well casing, providing a direct connection to the bedrock aguifer, if the casing seal is inadequate. A confirmation study is recommended at this site and is presented in Section 6.



#### SECTION 6

#### RECOMMENDATIONS

### 6.1 INTRODUCTION

The following recommendations are made for work to be performed in Phase II (Problem Confirmation). The recommended actions are generally one-time sampling and analytical programs. They are designed on a site-by-site basis to verify the presence or absence of contamination at a site, and to further assess the potential for adverse environmental impact from contamination should it be present at a site. The recommended actions are summarized in Table 6-1.

### 6.2 POL AREA - SITE NO. 1

The POL area has had confirmed contamination through loss of JP-4 to the subsurface from a leak in Tank To determine the current areal extent of the plume of fuel between the POL area and the ponding basin, it is recommended that three soil borings be drilled to bedrock in a line approximately parallel to Langley Street, between the west fence and the existing monitor wells. Three additional soil borings recommended to confirm presence or absence of contamination in soil: one beneath or near the fuel oil tank #222; one next to the underground waste fuel storage tank; and one just outside and immediately adjacent to the fence surrounding the reported fuel sludge burial



### TABLE 6-1

## RECOMMENDED PHASE II SAMPLING PROGRAM WILLOW GROVE ARF

					mended Phar oling Progr		
Site No.	Site Name	Harm Score	No. of Soil Borings <sup>1</sup>	No. of Monitor Wells <sup>2</sup>		GW .	No. of Surface Water
1	POL Area	82	6	1	18	5	-
2	Open Storage Area No. 42	79	6	4	18	4	
3	Ponding Basin	70	_		6	3 (seeps)	6
4	Washrack Area	69	3	3	14	5 (3 wells, 2 seeps)	-
5	Bldg. 330 Waste Oil Storage Area	69 a	_	1	8 (5 hand auger)	1	
6	Heating Plant	66	_		5 (all hand auger)		
7	Old Well House	57			1	2	1
TOTAL	s		15	9	71	20*	7

<sup>\* 20 = 2</sup> from AF-2, 4 from existing monitor wells, 9 from new monitor wells, 5 from seeps

### NOTES:

Soil borings refer to hollow stem auger holes not finished as monitor wells.

<sup>&</sup>lt;sup>2</sup> All monitor wells to be drilled 20 feet into bedrock, screened above seasonal high water and sand packed.

<sup>3</sup> Sediment samples to be preserved for analysis to be determined by use of on-site OVA.

A seep is defined as an area of ground where water or other liquid cozes from the earth; water collected from a seep is treated as groundwater.



area. (Note: drilling directly over the area may be impossible due to the steep grade on the new tank berm.) Sampling intervals and protocols are described in Section 6.9.

To confirm presence or absence of contamination groundwater, it is recommended that the four existing monitor wells be sounded for depth and sampled. Assuming that these wells were completed above bedrock, it is recommended that one additional well be drilled the specifications outlined into bedrock following The location will be chosen in the presumed above. downgradient direction based on existing information, study of aerial photography, and the results of drilling around Open Storage Area #42. Minimum well construction requirements are summarized in Table 6-2 and illustrated diagrammatically in Figure 6-1.

### 6.3 OPEN STORAGE AREA #42 - SITE NO. 2

This site has a potential for resulting in an adverse environmental impact, with subsurface percolation through soil into the bedrock aquifer the most obvious and persistent pathway.

To adequately evaluate presence or absence of contamination in subsurface sediments, it is recommended that six soil borings be drilled to bedrock (approximately 12 feet) and be sampled at three intervals (0 to 2 feet, 4 to 6 feet, and 10 to 12 feet, or at the bedrock interface). The subsurface sediment samples to be preserved for analysis will be selected in the field based on measurements of soil vapor made with a portable Organic Vapor Analyzer (OVA) or equivalent field instrument. Every sample exhibiting OVA readings above background levels should be preserved, within a range of a minimum




## TABLE 6-2

## MINIMUM WELL CONSTRUCTION REQUIREMENTS

Item	Description
Casing	PVC with nonglue fittings
Minimum casing diameter	Four inches
Screen	PVC wound with nonglue connectors and bottom cap
Top of screen	3 feet above the water table
Gravel pack	2 feet above top of the screen
Bentonite seal	A 2-foot bentonite seal should be placed above the gravel pack.
Grout	6 to 1 bentonite/cement mix to 2 feet below surface. Grout emplaced with a grout pipe. Grout pumped through pipe to the bottom of the open annulus (above the seal).
Protective cover	5-foot length of black iron pipe extending 3 feet above the ground surface and set in cement grout. Pipe diameter must be at least 2 inches greater than casing diamter.
Cap	A secure locking cap should be provided.
Survey	Locations and elevations of all wells should be surveyed.







of six (one from each boring) and a maximum of 18. Parameters for analysis are listed in Table 6-3. It is recommended that the borings be drilled following a grid pattern within the fenced portion of the storage area.

To adequately assess presence or absence of contamination in groundwater, it is recommended that four wells be installed on the perimeters of the #42 Open Storage Area. The wells should penetrate 20 feet into bedrock and be screened above the water table to ensure that the upper portion of the shallow aguifer, including any floating product on top of the water table, is Minimum well construction requirements sampled. listed in Table 6-2. Wells should be located approximately at 900 from each other around the site, following the orientation of dip and strike, or lineation evident in an aerial photography study to be performed prior to drilling. One monitor well should be placed next to Bolling Street, between Open Storage Area #42 and the POL area.

### 6.4 PONDING BASIN - SITE NO. 3

This site has a high potential for environmental impact due to its function as a collection point for surface discharge from the facility, and its connection with the underlying bedrock aquifer.

To adequately assess presence or absence of contamination, it is recommended that the pond bottom be sampled at three locations, with a sample of bottom sediment and a sample of water one foot off the bottom to be collected at each location. In addition, it is recommended that three sidewall seeps be sampled, with a sediment and a water sample to be collected from each. The surface discharge from the pond should also be



### TABLE 6-3

## RECOMMENDED LIST OF ANALYTICAL PARAMETERS FOR SELECTED SITES AT WILLOW GROVE ARF

## Sampled Media:

- Soil from surface, collected by hand auger
- Subsurface soil and sediment, collected by hollow stem auger rig
- Groundwater from monitoring wells
- Surface water from ponding areas

## Recommended Analytical Parameters:

- Total Organic Carbon (TOC)
- Total Halogenated Hydrocarbons (TOX)
- Oils and Greases
- VOA's Including Xylene
- Temperature (Field Determination on Water Only)
- pH (Field Determination on Water Only)
- Specific Conductance (Field Determination on Water Only)



sampled three times, approximately at one-week intervals, and preferably under differing flow rate conditions. It will be necessary to secure the cooperation of the U.S. Navy Office of Public Works, especially for the seep sampling, so that the pond level can be adjusted to an appropriate working elevation. The parameters listed in Table 6-3 should be analyzed.

### 6.5 WASHRACK AREA - SITE NO. 4

This site has a high potential for environmental impact due to the possibility of direct discharge from the washrack effluent treatment system into the bedrock aquifer, as well as possible surface spills in the vicinity of Buildings #215 and #223.

To adequately assess the presence or absence of contamination in subsurface sediments, it is recommended that six soil borings be drilled to bedrock (estimated depth 6 feet), and sediment samples collected from 0 to 2 feet and from 4 to 6 feet (or at the bedrock interface). Furthermore, it is recommended that three of these borings be continued into bedrock and finished as monitor wells following the specifications described in Table 6-2.

To evaluate the potential for contaminant migration along a surface water pathway, it is recommended that one sediment and one water sample be collected at two locations in the ditch bordering the area on the south and east sides. If seeps are present in the sidewall of the ditch, sampling locations should correspond to these seeps.

## WESTER

### 6.6 BUILDING #330 WASTE OIL STORAGE AREA - SITE NO. 5

This site has potential for environmental impact due to percolation of waste oils and possibly solvents into the ground.

To assess the presence or absence and surface extent of contamination, it is recommended that five samples be collected with a hand auger from a depth of 0 to 2 feet following the protocol described above. At least one of these samples should be collected from the JP-4 spill area on antenna hill just southeast of Building \$330. In addition, it is recommended that three sediment samples be collected from an auger boring to bedrock drilled in the approximate center of the area of waste oil spillage. This boring should be continued 20 feet into bedrock and finished as a monitor well following the specifications outlined in Table 6-2.

### 6.7 HEATING PLANT - SITE NO. 6

This site has potential for environmental impact due to a confirmed spill of \$6 fuel oil and observed chemical handling practices.

To adequately assess the presence or absence of contamination below Tank \$221, the site of the \$6 fuel oil spill, it is recommended that a hand auger be used to collect two sediment samples from depths between 0 and 4 feet inside the tank containment area. Visual observation and OVA measurements should be used to define the extent of vertical migration and identify samples for analysis. It is not recommended that an auger rig be used at this site due to the inaccessibility of the area beneath Tank \$221 and around the heating plant in



general. Based on the viscosity of #6 fuel oil, its migration rate through soil is estimated to be very slow. Deeper sampling of sediment may be warranted in a later phase, however, should the degree of contamination identified during the recommended Phase II investigation turn out to be extensive.

In addition, it is recommended that three more soil samples be collected outside of the tank containment area, adjacent to the heating plant building in areas of suspected spills. The sampling protocol as described in Table 6-1 should be used.

## 6.8 OLD WELL HOUSE - SITE NO. 7

This site has a potential for environmental impact through contaminant migration along both surface water and groundwater pathways, but the presence of contamination is presently not confirmed. To adequately assess the presence or absence of contamination, and identify the most likely pathway(s), it is recommended that one sample be collected from the water ponded in the valve pit, and that two groundwater samples be collected from the production well (AF-2) itself, one from the stagnant casing water and one after purging three well volumes. In addition, it is recommended that one sediment sample be collected from the area of surface water ponding immediately north of the valve pit (on the northeast corner of the old well house).

### 6.9 GENERAL CONFIRMATION RECOMMENDATIONS

### 6.9.1 Soil Borings and Well Installation

It is recommended that soil borings be drilled with a truck or trailer-mounted hollow stem auger rig, and



samples collected with a split spoon sampler following the Standard Penetration Test (ASTM D-1586). This will ensure collection of representative samples from known Drilling into bedrock should be performed by a rotary or rock hammer rig, and the hole should be thoroughly developed before completion. The recommended depth of 20 feet into bedrock has been chosen to ensure adequate monitoring of the upper portion of the bedrock aquifer without unnecessary risk of contaminating lower zones. The well completion specifications outlined in Table 6-2 have been designed primarily to ensure that the well is in good hydraulic connection with aquifer, that product floating on the water table can enter the well freely, and that the casing is sealed to prevent surface water from running down to the screened area.

### 6.9.2 <u>Analytical Parameters</u>

Recommended analytical parameters for the Phase II confirmation study sampling are listed in Table 6-3. They are the same for water and sediment, except for field determinations of temperature, pH, and specific conductance to be performed on water only. They TOX. used to screen samples for organic contamination; oils and greases, used to screen contamination with hydrocarbons; and volatile organic analytes (VOA) including xylene, to identify specific solvents, industrial chemical compounds, and soluble components of fuels that may be present. is no evidence of a need for sampling heavy metals at this time, although these might be included in expanded Phase II sampling program.



Further field investigation at any of these sites may be warranted based on the results of the Problem Confirmation Study, and could be performed as a Quantification Stage in the Phase II Investigation.

The recommendations contained in this report designed primarily to yield sufficient information on presence or absence of suspected contamination. sites where the presence of contamination is confirmed, it may be necessary to perform additional soil sampling, install new wells, and modify or expand the list of analytical parameters to achieve adequate definition and quantification of the extent of contamination.



## APPENDIX A

RESUMES OF THE WESTON TEAM



RAYMOND W. KANE, P.E.

### Registration

Registered Professional Engineer in Pennsylvania

### Fields of Competence

Environmental management and regulatory compliance; energy facility siting; oil, gas and shale technology; water resource planning; hazardous waste management; regional planning; environmental impact assessment; management consulting; strategic planning.

### Experience Summary

Twelve years in a variety of energy/environmental projects for large industrial firms, and Federal and state government clients. Manager of large complex interdisciplinary studies for petroleum, and chemical industries. Program manager for statewide power plant siting study and oil, gas and shale technology research and development activities on the Federal level.

Conducted numerous environmental audits and regulatory compliance reviews at industrial facilities. Conducted several water resource planning and economic base studies. Conducted industrial hazardous waste planning and engineering evaluations.

### Credentials

B.S. - Civil Engineering - Villanova University (1967)

M.S. - Civil Engineering - (Water Resources) Villanova University (1976)

Tau Beta Pi

Water Pollution Control Federation

Society of American Military Engineers

American Defense Preparedness Association

Commander - U.S. Naval Reserve, Civil Engineer Corps

### Employment History

1981-Present	WESTON
1978-1981	Booz-Allen & Hamilton Principal
1975–1978	WESTON
1973–1975	McCormick, Taylor & Associates
1972-1973	Kappa Systems, Inc.



RAYMOND W. KANE, P.E. (continued)

1971-1972 Upper Darby Township

(Pennsylvania)

1967-1971 Submarine Force, U.S.

Navy

### Key Projects

Project Director of Navy Phase I Initial Assessment Study for Portsmouth Naval Shipyard and Brunswick Naval Air Station. Conducted record searches and field investigations to determine existence of any past hazardous waste disposal sites. Developed recommendations for Phase 2 Confirmation and Quantification Study.

Participated in three of WESTON's previous confirmation studies under WESTON's installation restoration contracts for the Air Force and the Army.

Principal Investigator on a hazardous waste storage needs on four Navy installations around the country.

Participated in five other hazardous waste site investigations for EPA and other industrial clients, all of which included hydrogeological investigations, soil, groundwater sampling and analysis, and remedial concept engineering.

Project manager for environmental audit and regulatory compliance review for Occidental Petroleum Corporation. Conducted reviews of over 100 chemical, petroleum and coal preparation facilities. Determined true costs of environmental compliance activities and corporate liability for 3-year period. Study

was in response to SEC consent agreement. As a follow-on also developed an Assessment Program Guidance Document (APGD) to help corporate staff set up programs, policies and procedures to ensure environmental related liabilities and exposure are minimized.

Project Director for "Development of Environmental Audit Program" for the National Institutes of Health. Responsible for establishment of audit protocols and procedures to ensure compliance with Federal, state and local environmental requirements for the main campus of NIH and field facilities around the country.

Project Manager for coal-fired power plant siting study in Western Maryland. Served as program integrator, managing the technical work of several subcontractors. Identified exclusionary and discretionary screening criteria and determined best sites for siting of power plant using state MAGI (environmental data base) system. Participated in Public Involvement Program through public workshops and meetings. Reservoir siting and coal cleaning facility siting studies were also a part of this large complex project.

Project Manager for large oil, gas, and shale technology R&D project for Department of Energy. Conducted a variety of technical resource characterization studies, market studies, strategic planning and environmental assessment evaluations for DOE's program offices. Technologies evaluated included aboveground and modified in situ oil shale retorting and enhanced oil recovery and enhanced gas recovery. Coordination with Bartellsville Energy Technology Center (BETC) staff was a major part of this project.



RAYMOND W. KANE, P.E. (continued)

Project Manager - New York City, Department of Environmental Protection. Responsible for environmental assessment of city-wide sludge management facility plan. Work includes site selection criteria and screening and development of baseline information and impact assessments for a range of landbased alternatives including composting, land application, co-incineration, co-disposal and landfilling.

Project Manager - Pennsylvania Department of Transportation. Responsibilities included regional planning and development of an EIS for 17 miles of a 4-lane interstate highway project and coordination of all study elements. Public participation and client relations were prime management responsibilities, in addition to the technical responsibility for water resources assessment.

Project Manager - Confidential Industrial Client. Determination of potential development constraints for expansion of facilities for a major industrial client, involving investigations of: 1) zoning regulations; 2) municipal services; 3) environmental constraints; 4) traffic transportation constraints.

Project Manager - Jacksonville District Corps of Engineers. Responsibility included: coordination and management of \$150,000 multi-disciplinary study of geologic and biologic resources, land use, soils and other existing natural resources; projection of population and other economic parameters to the year 2030 and forecasts of water demand and

wastewater generation; LANDSAT and other multi-spectral imagery to develop certain types of graphic overlays showing wetlands and other transitional zones.

Project Director for hydrogeologic investigation of TCE contamination for industrial client in New Jersey. Conducted wastewater sampling and analysis, pump tests and groundwater modeling to determine cause and effect relationship of contamination.

Project Manager - Vicksburg District Corps of Engineers. Responsible for the coordination and management of study geared to the projection of population, employment earnings, value added, income, industrial growth, and agricultural production for a 26-county region in northwest Mississippi.

### Publications

Kane, R.W., "Water Resources Impacts of Synthetic Fuels Development in the West," 1981.

Kane, R.W., Cahill, L.W., Burns, H.B., "Energy Choices and Environmental Constraints, 1979.

Kane, R.W., "What Constitutes a Good Corporate Environmental Management and Regulatory Compliance Program?," 1981

Kane, R.W., Emig, D., "DoD's Superfund Program," 1983.

Kane, R.W., Gertz, S.G., "Hazardous Waste - Corporate Risk or Corporate Profit?," 1982.

### Fields of Competence

Groundwater flow sytem analysis and numerical modelling; groundwater contamination assessment and remediation; hydrogeologic evaluation of solid and hazardous waste sites; water supply and recovery well design and testing; monitor well network design and implementation; sampling of soil and water for conventional and hazardous chemical compounds.

## Experience Summary

Three years of experience as field hydrogeologist and project geologist in industrial and hazardous waste disposal site investigations, including two Superfund sites, and in inventories and assessments of various classes of injection wells.

Three years of graduate research in hydraulic properties of shales and mudstones, watershed hydrology, and coastal hydrogeology, including practical applications of numerical groundwater flow models.

### Credentials

B.A., Geology — Mount Holyake College (1976)

M.S., Hydrogeology — University of Arizona (1981)

National Water Well Association, Technical Division

American Geophysical Union, Hydrology Division

### Employment History

1984-Present	WESTON
1981-1984	SMC Martin Inc. Valley Forge, Pennsylvania
1978-1981	University of Arizona Department of Hydrology
1978 (summer)	Office of the State Geologist Montpelier, Vermont

### Key Projects

Field evaluation of potential surface water and groundwater contamination at two Air Force Bases in California, including monitor well installation and sample collection, analysis of the hydrogeologic and chemical data.

Field evaluation of an underground fuel leak at an Air Force Base on the Gulf Coast, Florida, including plume delineation, source identification, water table map preparation and interpretation, and evaluation of tidal effects in contaminant migration.

Installation Restoration Program Phase I investigation of an Air Reserve facility in the mid-atlantic region, including site visit, interviews and file searches, compilation and interpretation of hydrogeologic data, and preparation of recommendations for Phase II investigation.

Site assessment and remediation at an uncontrolled hazardous waste disposal site in New Jersey, including field sampling of highly contaminated ground-water and soils, conceptual development of site remediation measures, and testing of remedial measures on a computer groundwater flow model.

Hydrogeologic investigation of a 50 acre site for impact of past electronic components manufacturing operations on ground and surface water.

Evaluation of the effect of placing an innovating top seal for closure of a 25 acre municipal landfill, including analysis of long-term hydrogeologic and geochemical conditions.

Site assessment and remediation at an uncontrolled hazardous waste disposal site in Chio, including a metal detector survey for buried drums, soil sampling, drilling and well construction supervision, well logging, data analysis.

Evaluation of surface seepage from a 3acre wastewater lagoon, including water level monitoring and a detailed water budget.

### **Publications**

"Trichloroethylene Occurrence and Ground-Water Restoration in Highly Anistopic Bedrock: A Case Study," coauthored, with David L. Kraus. Proceedings of the Third National Symposium and Exposition on Aquifer Restoration and Groundwater Monitoring, National Water Well Association, Columbus, CH, 1983.

"Leachate Quality Improvements after Top Sealing," co-authored with W.W. Beck, Jr. and G.H. Emrich. Proceedings of the 8th Annual U.S. EPA MERL/SHWRD Conference, 1982.

"The Impact of Top-Sealing on the Windham, Connecticut Landfill," co-authored with R.M. Schuller and W.W. Beck, Jr. Proceedings of the 9th Annual U.S. EPA MERL/SHWRD Conference, 1983.

"Preliminary Assessment of the Hydrologic Environment of Klamath Marsh, Oregon," co-authored with M.E. Norvelle, S.L. Vierek, and S. Ince. NADSAT Project Completion Report No. 31, 71 p. 1981. Office of Arid Land Studies, University of Arizona.

- "A Study of Salinity in Effluent Lakes, Puerto Penasco, Sonora, Mexico," Hydrology and Water Resources in Arizona and the Southwest, American Water Resources Association, Arizona Section, 1981.
- "Analysis of a Saline Ground-Water Flow System in Puerto Penasco, Sonora, Mex-
- ico, presented to the <u>Cordilleran Section Meeting of the Geological Society of America</u>, March 1981.
- "A Bibliography of Vermont Geology," compiled with Charles Ratte and Diane Vanacek, Office of the State Geologist, Montpelier, Vermont, 1980.

## Fields of Competence

Solid and hazardous waste management: hazardous waste site remedial actions; solid waste collection, storage and disposal, and resource recovery unit operations.

## Experience Summary

Three years of civil and environmental engineering experience in the fields of hazardous and solid waste management industrial and hazardous including: waste treatment, storage and disposal technologies; hazardous waste site remedial action alternatives; the engineering responses of clay soils to the presence of hazardous waste chemicals; modelling and evaluation of complex cover systems for application at hazardous waste disposal facilities; radioactive waste disposal strategies; resource recovery and refuse to energy technologies.

### Credentials

B.S., Civil Engineering -- Duke Uhiversity (1980), Cum Laude

M.S., Environmental Engineering — Duke University (1981)

Chi Epsilon

## Employment History

1981-Present WESTON

5133A

1980-1981

Duke University

### Key Projects

A Team Engineer on four Phase I studies including the U.S. Air Force Academy; Project Engineer on a project to determine hazardous waste storage needs at DPDO facilities on various Navy installations.

Served as Project Engineer for the following WESTON hazardous waste projects:

- Development of a remedial action clean-up program for Bruin Lagoon, Pennsylvania for EPA under "Superfund" for Bruin Lagoon, a 3-acre acidic oil sludge lagoon located in western Pennsylvania. Prepared the design of a complex cover system, groundwater controls, and sludge dewatering/stabilization methodology for an in situ stabilization of the oily sludge waste at Bruin Lagoon. Prepared contractor bid specifications.
- Evaluation of clean-up scenarios at an existing industrial complex of over 2,000 acres in California contaminating the soil and groundwater quality through storage, spillage, and deep-well injection of organic and halogenated compounds.

- Development of regulatory and technology guidelines for the closure of inactive explosive waste lagoons at over 40 U.S. Army installations. Analyzed the waste lagoon characteristics and installation area characteristics and installation characteristics, as well as the Federal and state regulatory requirements for closure of inactive land disposal facilities. Evaluated inplace closure technologies for application with groundwater isolation and pumping, surface soil capping, and explosive waste desensitization.
- Assessment of available hazardous waste management technologies for implementation on a provincewide scale for Ontario, Canada. Analyzed appropriate chemical and physical treatment strategies, incineration technologies, fixation/stabilization approaches, and ultimate disposal alternatives for application to Ontario's industrial waste streams.
- . Evaluation of potential remedial action clean-up strategies under Superfund for Matthews Electroplating, a site where soil and ground-water contamination resulted from chromium plating operations. Conducted the site characterization field work, environmental sampling, and geologic soils investigations. Prepared the engineering feasibility study for the selected remedial action alternative.
- Evaluation of a municipally-operated refuse-to-energy resource recovery system for Salem County, New Jersey.

Prepared the system design based on Countywide waste stream characterization, identification of potential energy markets, evaluation of incineration technologies, and cost-effective analysis.

Development of a remedial action cleanup program at a major industrial site on Lake Michigan where massive PCB spills and discharges have contaminated soil and surface water quality.

As a Research Assistant at Duke University, supervised the following projects in solid, hazardous, and radioactive waste management:

- . Analysis of permeability rate and other structural alterations in clays and clay soils when exposed to industrial and hazardous waste leachates in completion of a Master's degree thesis in environmental engineering.
- Prepared the methodology for evaluation of a potential low-level radioactive waste disposal facility in Research Triangle Park, North Carolina.
- Evaluation of resource recovery applications in North Carolina, including the potential use of a shredding operation at the Durham sanitary landfill.

### Publications

"The Effect of Electroplating Wastes Upon Clay As An Impermeable Boundary to Leaching," M.S. Thesis by M.F. Coia. "The Leaching of Electroplating Wastes Through Clay Liners," by M.F. Coia, J.J. Peirce, and P.A. Vesilind. Presented at the 1981 AlChE 74th National Conference.

"Bruin Lagoon: Remedial Clean-up of Hazardous Waste Sites Under Superfund," by M.F. Coia and J.W. Thorsen. Presented at the 1982 Mid-Atlantic Industrial Waste Conference.

"Remedial Superfund Actions: Procedures and Results," by J.W. Thorsen and M.F. Coia. Presented at the 1982 Na-

tional Conference of ASCE, Environmental Engineering Division.

"Remedial Actions at Industrial Waste Sites: A Case History, Bruin Lagoon," by M.F. Coia. Presented at the 1982 Engineering Foundation Conference: Industry Response to the Hazardous Waste Challenge.

"In-Place Stabilization and Closure of Oily Sludge Lagoons," by A.A. Metry, M.F. Coia, M.H. Corbin, and A.L. Lenthe. Presented at 1983 WPCAP Technical Conference.



NAME: Jennifer Kauffman

Roy F. Weston, Inc.

ASSIGNMENT/LEVEL: Technical Writer/Editor

Level 2

## EDUCATION:

B.A., Land Use and Regional Planning - Bowling Green State University (1977)

Master's of Regional Planning - University of Michigan (1979)

## **EXPERIENCE SUMMARY:**

- Five years experience in consulting planning and engineering fields as project planner, project coordinator and technical writer and editor.
- Edited workbooks, and developed and implemented promotional programs for hazardous/solid waste, environmental and energy conservation workshops, presentations, and seminars.

## KEY PROJECTS:

Co-author and technical editor of more than a dozen small-scale hydroelectric feasibility studies. Prepared environmental impact assessments, analyzed hydraulic and hydrologic data and researched legal and institutional constraints to development. Prepared FERC preliminary permit, exemption, and license applications.

Edited workbooks and prepared promotional materials for one day seminars on energy conservation in municipal water and wastewater systems, and energy conservation in commercial lodging facilities.

Assistant planner and author for preparation of a coastal zone management plan for the St. Clair Flats, a sensitive freshwater delta in Lake St. Clair near Detroit. Collected, analyzed, and mapped natural resource and cultural data. Assisted in development and analysis of alternate management scenarios, preparation of land management and acquisition priorities plans, and report writing.

Inventoried data sources and conducted preliminary assessment of state hydroelectric development potential for Ohio Department of Energy.

P-84-1665 5048A



Researched and authored environmental assessment for proposed modifications and expansion of the wastewater treatment facility at K. I. Sawyer Air Force Base, Michigan.

Evaluated state policies and procedures governing the issuance of dredge, fill, and construction permits in inland lakes and streams and Great Lakes bottomlands in Michigan.

Researched and participated in preparation of a number of coastal zone management, recreation and community master plans. Conducted facility inventories, natural resource capability analyses and impact assessments. Collected and analyzed data, developed and implemented surveys, researched regulatory, financial and technical programs, and prepared reports.

## EMPLOYMENT HISTORY:

1983 - Present WESTON

1979 - 1983 Ayres, Lewis, Norris & May, Inc.

1978 - 1979 University of Michigan Coastal Zone Laboratory

## PUBLICATIONS, AWARDS, CREDENTIALS:

Project Planner and principal author of comprehensive solid waste management plans for Bay and Midland Counties in Michigan. Analyzed quantity and composition of waste stream. Evaluated feasibility and assessed impacts of management alternatives, including landfilling, energy recovery, recycling and composting. Developed landfill capability maps and management/implementation strategies.

Organized, administered, and promoted a series of workshops on energy conservation in municipal water and wastewater systems in Pennsylvania.

"Multiple Use Issues and Reactivation of Former Hydro Plants." Presented at WATERPOWER 1983, September 1983, Knoxville, Tennessee.

"Integrating Solid Waste Management and Energy Planning," January 1983. Forthcoming publication in an American Planning Association compendium entitled, The Role of Planning in Our Nation's Energy Future.

P-84-1665 5048A



"Multipurpose Planning of Hydroelectric Projects," Energy Planning Network, APA Energy Planning Division, December 1981.

"Multipurpose Planning of Small Hydro Projects: An Opportunity Assessment Approach." Presented at WATERPOWER 1981, June 1981, Washington, DC.

The Water Power Revival in Michigan, The Michigan Riparian, February 1981.

American Planning Association

American Planning Association, Energy Planning Division

National Association of Environmental Professionals

P-84-1665 5048A



APPENDIX B

LIST OF INTERVIEWEES



# APPENDIX B

# LIST OF INTERVIEWEES 913th TAG

Position	Years of Service
Civilian Base Civil Engineering	14
Civilian, Engineering & Construction	14
Aircraft Maintenance Division	15
Civilian, AGE Shop	21
Civilian, Machine Shop	15
Civilian, Sheet Metal Shop	10
Civilian, Paint Shop	26
Civilian Welding Shop	10
Civilian, Pneudraulics Shop	15
Civilian, Corrosion Control Shop	18
Civilian, Fuel Cell Repair	3
Civilian, NDI Lab	6
Civilian, Engine & Prop Shop	12
Civilian, Avionics Shop	10
Civilian, Operations & Maintenance	15
Civilian, Receiving, Base Supply	26
Civilian, Medical Administrator	20
Civilian, Materials Manager, Base Supply	18
Civilian, Fuels Distribution, Base Supply	16
Civilian, Motor Pool Maintenance	15
Public Works NAS Willow Grove	3



# APPENDIX B (Con't)

Position	<u>Years or Experience</u>
Civilian Trash Disposal, PWO, NAS, Willow Grove	20
lllth PaANG	
Deputy Commander Resources	18
Base Civil Engineering	4
Facility Manager	10
ACFT Field Maintenance	25
ACFT Dock Chief	20
ACFT Org. Maintenance	21
Fire Chief	20



APPENDIX C

LIST OF OUTSIDE AGENCIES



## LIST OF OUTSIDE AGENCIES

Jim Beyers
National Archives and National Records Center
Research Assistance and Information
Washington, DC
202-523-3218

Steve Bern
Records Officer
Washington National Records Center
Suitland, Maryland
301-763-1710

Bill Lewis
Washington National Records Center
Suitland, Maryland
301-763-1710

Mr. Eldridge Army Records Office 703-325-6179

Ed Reese Records Office Military Archives Division Modern Military Headquarters Branch Washington, DC 202-523-3340

Grace Rowe
Air Force Records Management
Air Force Records
Washington, DC
202-694-3527

Alan Guyer
Pennsylvania Geological Survey
Harrisburg, Pennsylvania
717-787-2167



# LIST OF OUTSIDE AGENCIES (Con't)

Steve Hearsh
U.S. EPA - Region III
Philadelphia, Pennsylvania
212-597-1177

Joe Feola
Pennsylvania Dept. of Environmental Resources
Norristown, Pennsylvania
215-270-1975

Paul Warmo, Water Quality Sanitarian
Pennsylvania Dept. of Environmental Resources
Norristown, Pennsylvania
215-270-1900

Tom Majusick
U.S. Dept. of Housing and Urban Development
Federal Emergency Management Agency
Philadelphia, Pennsylvania
215-597-3630

Gary Rohn
U.S. Army Corps of Engineers
Philadelphia, Pennsylvania
215-597-4808

Donald J. Baker, Engineer
Delaware River Basin Commission
West Trenton, New Jersey
609-883-9500



# APPENDIX D

HAZARD ASSESSMENT RATING METHODOLOGY

# USAF INSTALLATION RESTORATION PROGRAM HAZARD ASSESSMENT RATING METHODOLOGY

### BACKGROUND

The Department of Defense (DOD) has established a comprehensive program to identify, evaluate, and control problems associated with past disposal practices at DOD facilities. One of the actions required under this program is to:

"develop and maintain a priority listing of contaminated installations and facilities for remedial action based on potential hazard to public health, welfare, and environmental impacts." (Reference: DEOPPH 81-5, 11 December 1981).

Accordingly, the United States Air Force (USAF) has sought to establish a system to set priorities for taking further actions at sites based upon information gathered during the Records Search phase of its Installation Restoration Program (IRP).

The first site rating model was developed in June 1981 at a meeting with representatives from USAF Occupational Environmental Health Laboratory (OEHL), Air Porce Engineering Services Center (AFESC), Engineering-Science (ES) and CH<sub>2</sub>M Hill. The basis for this model was a system developed for EPA by JRB Associates of McLean, Virginia. The JRB model was modified to meet Air Force needs.

After using this model for 6 months at over 20 Air Force installations, certain inadequacies became apparent. Therefore, on January 26 and 27, 1982, representatives of USAF CEHL, AFESC, various major commands, Engineering Science, and CH<sub>2</sub>M Hill met to address the inadequacies. The result of the meeting was a new site rating model designed to present a better picture of the hazards posed by sites at Air Force installations. The new rating model described in this presentation is referred to as the Hazard Assessment Rating Methodology.

### PURPOSE

The purpose of the site rating model is to provide a relative ranking of sites of suspected contamination from hazardous substances. This model will assist the Air Force in setting priorities for follow-on site investigations and confirmation work under Phase II of IRP.

This rating system is used only after it has been determined that (1) potential for contamination exists (hazardous wastes present in sufficient quantity), and (2) potential for migration exists. A site can be deleted from consideration for rating on either basis.

### DESCRIPTION OF MODEL

Like the other hazardous waste site ranking models, the U.S. Air Force's site rating model uses a scoring system to rank sites for priority attention. However, in developing this model, the designers incorporated some special features to meet specific DOD program needs.

The model uses data readily obtained during the Record Search portion (Phase I) of the IRP. Scoring judgments and computations are easily made. In assessing the hazards at a given site, the model develops a score based on the most likely routes of contamination and the worst hazards at the site. Sites are given low scores only if there are clearly no hazards at the site. This approach meshes well with the policy for evaluating and setting restrictions on excess DOD properties.

As with the previous model, this model considers four aspects of the hazard posed by a specific site: the possible receptors of the contamination, the waste and its characteristics, potential pathways for waste contaminant migration, and any efforts to contain the contaminants. Each of these categories contains a number of rating factors that are used in the overall hazard rating.


The receptors category rating is calculated by scoring each factor, multiplying by a factor weighting constant and adding the weighted scores to obtain a total category score.

The pathways category rating is based on evidence of contaminant migration or an evaluation of the highest potential (worst case) for contaminant migration along one of three pathways. If evidence of contaminant migration exists, the category is given a subscore of 80 to 100 points. For indirect evidence, 80 points are assigned and for direct evidence 100 points are assigned. If no evidence is found, the highest score among three possible routes is used. These routes are surface water migration, flooding, and ground-water migration. Evaluation of each route involves factors associated with the particular migration route. The three pathways are evaluated and the highest score among all four of the potential scores is used.

The waste characteristics category is scored in three steps.

Pirst, a point rating is assigned based on an assessment of the waste quantity and the hazard (worst case) associated with the site. The level of confidence in the information is also factored into the assessment. Next, the score is multiplied by a waste persistence factor, which acts to reduce the score if the waste is not very persistent. Pinally, the score is further modified by the physical state of the waste. Liquid wastes receive the maximum score, while scores for sludges and solids are reduced.

The scores for each of the three categories are then added together and normalized to a maximum possible score of 100. Then the waste management practice category is scored. Sites at which there is no containment are not reduced in score. Scores for sites with limited containment can be reduced by 5 percent. If a site is contained and well managed, its score can be reduced by 90 percent. The final site score is calculated by applying the waste management practices category factor to the sum of the scores for the other three categories.



NOTE OF SITE				<del></del>
DYIZ CA CARBYLLON OF CCCARPENCE				<del></del>
OWNER/OPERATOR				
CONSCRITS/DESCREPTION				
SITE MED ST				
L RECEPTORS	-			
Nating Pactor	Pactor Rating (0-3)	Multiplier	Pactor Score	Nexisus Possible Score
A. Population within 1,000 feet of site		4		
B. Distance to nearest well		10		
C. Land use/soning within 1 mile radius		3		
		6		
D. Distance to reservation boundary				
g. Critical environments within 1 mile radius of site	<del></del>	10		
P. Water quality of nearest surface vater body				
G. Ground water use of uppermost aquifer	<del>-}</del>	•		<del></del>
E. Population served by surface veter supply within I siles downstreem of site	<u> </u>	6		
I. Population served by ground-water supply within 3 miles of site		6		
		Subtotals		<del></del>
Receptors subscore (100 % factor acc	ra aubtota	Anarimum acore	subtotal)	<del></del>
IL WASTE CHARACTERISTICS				==
A. Select the factor score based on the estimated quantity the information.	, the degr	oe of hasard, a	nd the confi	dence level d
1. Waste quantity (S = small, H = medium, L = large)				
2. Confidence level (C = confirmed, S = suspected)		•		
3. Hazard sating (E = high, N = medium, L = low)				
to measure controlly to a measure of a measu				
Factor Subscore A (from 20 to 100 based	on factor	score matrix)		
B. Apply persistence factor Factor Subscore & I Persistence Factor - Subscore B				
1	•_			
C. Apply physical state multiplier				
Subscore B X Physical State Multiplier - Weste Characte	risties Su	pacosa		
¥	•			
استاكات الرويسيوني - والبواقي المواقي المواقية المواقية المواقية المواقية المواقية المواقية المواقية	_ =			

_		•	v	ш	A.	Υŧ	ĸ
	71	~ :	п	ŦŦ	~	•	,

Rating Pactor	Pactor Rating (0-3)	Multiplier	Pactor Score	Maximum Possible Score
A. If there is evidence of migration of he direct evidence or 80 points for indirect evidence exists, p	oct evidence. If direct evi	m makisum fact .dence exists t	or subscore of the proceed	of 100 points & to C. If no
			Subscore	
<ol> <li>Rate the migration potential for 3 pot- migration. Select the highest rating,</li> </ol>	ential pathways: surface we and proceed to C.	ster migration,	flooding, a	nd ground-veter
1. Surface water migration		٠		
Distance to mearest surface water		•		
Not precipitation	·			
Surface erosion				
Surface permeability		•		
Reinfall intensity				
•		Subtotale		
Subscore	(100 % factor score subtotal	l/mexisum score	subtotal)	
2. Flooding	1 1	. 1		1
	Subscore (190 x	factor sonre/3)		
3. Ground-water migration	•			
Depth to ground water	1 1	. 1		1
Set precipitation		6	** <del>*** **</del> **** **	
<del></del>				
Soil permeability			<del></del>	
Subsurface flows				
Direct access to ground water				1
		Subtotali		<del></del>
\$ubscore	(100 x factor ecore subtota	L/Maximum ecore	subtotal)	<del></del>
C. Righest pathway Subscore.				
Enter the highest subscore value from	A, B-1, B-2 or B-3 above.			
		Pathva	rs Subscore	
IV. WASTE MANAGEMENT PRACTICES	•			
A. Average the three subscores for recep-	tors, wasta Characteristics,	and pathways.		
	Roceptors Waste Characterist Pathweys	ica		
	70tal_	divided by 3	• @:	ss Total Score
B. Apply factor for waste containment from	om vaste management practice	•		
Gross Total Score X Weste Management	Practices Pactor - Pinal Sco	re .		
	D-6	x	•	

TABLE 1 HAZARD ASSESSMENT RATING METHODOLOGY GUIDELINES

Pot les Pertocs		And aland middle			
Betine Pactors		The same of the same	2		Paltiplier Paltiplier
	•				•
A. Population within 1,000 feet (includes on-base facilities)	•	1 - 25	32 - 180 - 1	Greater than 199	•
nearest.	Orester than 3 miles 1 to 3 miles	1 to 3 miles	3,061 feet to 1 mile	e to 3,000 feet	2
ming (within	Completely remote Agricultural families not explicable)	Agricultural	Compersion or industrial	Resident is 1	m
stallation	Greater than 2 miles	1 to 2 miles	1,001 feet to 1 mile	e to 1,800 feet	9
E. Critical environments (vithin 1 mile redius)	Mot a critical environment	Matural are.	pristing matural areas almost set- lands; presence of sconcelcally impor- tant matural re- mources escoptible to contamination.	Mangered or threatened appeared or threatened appeales; presence of recharge area; asjor wetlands.	<b>:</b>
F. Water quality/use designation of mescet aurisce water body	Apricultural or industrial use.	Mecreation, propegation and sange- ment of fish and wildlife.	Shellfish propess- tion and harvesting.	Potable water supplies	•
G. Ground-Water use of uppermost aquifer	Not used, other sources readily available.	Commercial, industrial, or irrigation, very limited other water sources.	Drinking water, municipal vater available.	Drinking vater, no semi- cipal water svalleble; commercial, industrial, or irrigation, no other water source available.	•
M. Population served by surface veter supplies vithin 3 miles downstreem of mite	•	95 -		drester than 1,000	•
1. Population served by equific supplies within 3 miles of site	•	1 - 50	51 - 1,000	Greater than 1, 000	•

TABLE 1 (Continued)

# HAZARD ASSESSMENT RATING METHODOLOGY GUIDELINES

# Meserdous Meste Quentity 1

- 8 Small quantity (<5 tons or 26 drums of 11quid) 18 Nobersta quantity (5 to 20 tons or 21 to 85 drums of 11quid) L = Large quantity (>20 tons or 85 drums of 11quid)

# Confidence Level of Information A-2

- C Confirmed confidence level (minimum oriteria below)
- o Verbal reports from interviewer (at least 2) or written information from the records.
- o gnowledge of types and quantities of westes generated by shops and other areas on base.

Dased on the above, a determination of the types and quantities of waste disposed of at the site.

o Deed of the

quentities of hazardous vastes generated at Loyle based on a knowledge of the types disposed of at a site.

reports and no written information from

To verbal reports or

the records.

8 - Suspected confidence level

conflicting verbel

# Hoserd Reting 7

		Bating Scale Levels	10	
Heterd Category			2	
<b>Toxicity</b>	Bex's Level 0	Sex's Level 1	Dan's Lavel 2	Ben's Lovel 3
Ignitability	Flash point greater than 200°F	Flash point at 140'P to 200'P		Flesh point at 80'F Flash point less than to 140'F
Rediosetivity	At or below beckground levels	i to 3 times back- ground levels	3 to 5 times back- ground levels	Over 5 times beck- ground levels

Use the highest individual rating based on toxicity, ignitability and radioactivity and determine the hazard rating.

Pointe	~~-
Hetard Hating	High (H) Medium (M) Low (L)

# HAZARD ASSESSMENT RATING METHODOLOGY GUIDELINES

# II. MATE CHAMCTERISTICS (Continued)

# Maste Characteristics Matrix

Beserd	-	==	=	e z	2 2 2 2	# Z .J .
Confidence Level of Information	υ	u u	•	ยย		
Brandous Mate Quantity	٠	J 2	2	<b>.</b> 5	4 4 <b>5</b> 0	
Point Beting	<u>=</u>	8	2	3	<b>3</b>	3

Por a site with more than one hazardous waste, the waste quantities may be added using the following releas Confidence Level

o Confirmed confidence levels (C) can be added o Buspacted confidence levels cannot be added with suspected confidence levels cannot be added with suspected confidence levels cannot be added with augmented confidence levels cannot be added with augmented confidence levels and a added thing on the mass hasard rating can be added to Wastes with different hasard rating can be added to Wastes with different hasard rating can only be added to Wastes with different hasard rating can only be added to Wastes with different hasard rating can only be added to Wastes with different hasard taking can only be added to Wastes with designation (60 points). By adding the quantities of each waste, the designation may change to LCM (80 points). In this case, the correct point rating for the waste is 80.

# B. Persistends Meltiplier for Point Rating

Multiply Point Bating From Part A by the Pollowing	•:-		••		••	•
Persistence Criteria	Metale, polycyclic compounds,	and halogeneted hydrocarbons	Substituted and other ring	components	Straight chain hydrocartons	Resily biodegradable compounds

# C. Physical State Bultiplier

Maitiply Point Total From Parts A and B by the Pollovins	0.1 0.50 08.0
Physical State	Liquid Sludge Rolid

TABLE 1 (Continued)

こうとう できます こうしょく こうしょう かんしゅう しゅうきゅう ないない かんきゅう かんしゅう しゅうきゅう しゅうきゅう しゅうきゅう しゅうきゅう しゅうきゅう しゅうきゅう しゅうしゅ しゅうしゅ しゅうしゅう

- 1960年の日には、1960年間は1960年の1960年の中では、1960年ののののでは、1960年には1970年に1970年の1970

# HAZARD ASSESSMENT RATING METHODOLOGY GUIDELINES

# III. PATHENYS CATEORY

# A. Bridence of Contamination

Direct evidence is obtained from laboratory analyses of hazardous contaminants present above natural bachground levels in surface water, ground water, or air. Byldence should confirm that the source of contamination is the mite being welmted. Indirect evidence might be from viewal observation (i.e., leachate), vegetation stress, aludge deposits, presence of tasts and odors in drinking water, or reported discharges that cannot be directly confirmed as resulting from the site, but the site is greatly suspected of being a source of contamination.

# 8-1 POTESTIAL FOR SERFACE VALUES CONTINUED.

	•	Rating Scale Levels			
Reting Pector	•	-			mitiplior
Distance to mercet exfect vater (includes drainage ditches and storm severs)	Grater than I allo	2,001 feet to 1	901 fact to 2,000 0.to 900 fact.	3.0 55 50 50 50 50 50 50 50 50 50 50 50 50	•
Het precipitation	Less then -10 in.	-10 to + 5 in.	. +5 to +20 in.	Greater then +30 in.	•
Surface eresten	•	Blight	Moderate	Boroce	•
Declace persentility .	66 to 151 clay (>16 as/esc)	150 to 101 caveed)	150 to 301 clay 340 to 5020 clay	Greeter then 500 cley	•
Rainfall intensity based on 1 year 24-br rainfall	<1.0 Inch	1.0-2.0 inches	2.1-3.0 inches	>3.0 inches	•
9-2 POTENTIAL FOR PLOODING					
Ploodplein	Deyond 100-year floodplein	In 25-year flood- plain	In 10-year flood- Floods envelly plain	Floods amuelly	-

# 8-3 FOTENTIAL FOR GROUND-WATER CONTANTRAFICH

Depth to ground veter	Greater than 500 ft	50 to 500 feet	11 to 56 feet	• to 10 feet	•
Het previpitation	Less than -10 in.	-10 to +5 in.	+5 to +28 In.	Greater than +20 in.	•
Soil permeability	Greater than 504 clay (>10 cm/sec) (	391 to 393 clay	391 tr 301 clay 150 to 301 clay 00 to 150 clay (10 to 10 cm/sec) (10 to 10 cm/sec) (410 cm/sec)	6 to 150 clay (c) 0 az/esc)	•
Subsurface flows	Bottom of site greater than 5 feet above high ground-water level	Notice of site cocasionally submerged	Bottom of alte frequently sub-	Dottom of site lo- cated below mean ground-water level	•
blrect access to ground H water (through famile, frectures, family well cacings, subsidence fissures,	To evidence of risk	Low risk	Moderate risk	High riek	•

TABLE 1 (Continued)
HAZARD ASSESSMENT RATING METHODOLOGY GUIDELINES

でのから見ているかないとしているない。

# IV. MATE MANAGEMENT PRACTICES CATSOON

- This category adjusts the total risk as determined from the receptors, pathwoys, and wasts characteristics categories for wasts management practices and empiresring controls designed to reduce this risk. The total risk is determined by first eversaing the receptors, pathways, and wasts characteristics anhecores
- S. WASTE INMANDERS PRICTICES PACTOR

The following multipliers are then applied to the total risk points (from A):

Meste Menegament Prentice	Maltiplier
No containment Limited containment Fully contained and in full compliance	9.1. 8.3
Cuidelines for fully contained:	
Land (1119)	Burface legoundsenter
o Clay cap or other impermeable cover	o Liners in good condition
o Leachate collection system	o Sound dikes and adequate freeboard
o Liners in good condition	o Adequate monitoring walls
o Adequate monitoring wells	
Pellies	Pire Prosetion Training Areas:
o Quick apill cleanup action taken	o Concrete surface and berms
o Conteminated soil removed	o Oil/vater separator for pretreates
o Soil and/or water asspire confirm total cleanup of the spill	o gffluent from oil/vater meparator plant

General Note: If data are not available or known to be complete the factor ratings under items I-A through I, III-B-1 or III-B-1, then leave blank for calculation of factor score and maximus possible score.

ant of remoff to treetment



# APPENDIX E

SITE HARM SCORE CALCULATIONS

NAME OF SITE POL AREA - Site No. 1				
LOCATION Willow Grove ARF near northern	poundary			
DATE OF OPERATION OR OCCUMENCE 1958 - Present			<del></del>	
Willow Grove ARF, Fuels Manageme				
STER BATED BY ALD of JP-4. JP-4 tanks			entea spi	15
SITE SATED ST ALU Of JP-4. JP-4 tanks	built on	sand pads		
L RECEPTORS Rating Factor	Pastor Rating (0-3)	Multiplier	Partor Score	Marinum Possible Score
A. Population within 1,000 feet of site	3	- -	12	12
B. Distance to nearest well	3	10	30	30
C. Land use/soning within 1 mile radius	3	3	9	9
D. Distance to reservation boundary	3	6	18	18
E. Critical environments within 1 mile radius of site	2	10	20	30
7. Water quality of nearest surface water body	1	6	6	18
G. Ground weter use of uppermost aquifer	3	•	27	27
E. Population served by surface veter supply within 3 miles downstream of site	0	6	0	18
I. Population served by ground-water supply within 3 miles of site	3	6	18	_18
		Subtotals	140	180
Receptors Subscore (100 % factor so	core subtotal	/nazimum score	subtotal)	78
IL WASTE CHARACTERISTICS				
A. Select the factor score based on the estimated quantity the information.	ty, the degre	e of hasard, a	nd the confi	dence level
1. Waste quantity (S = small, M = medium, L = large)				<u>_</u>
2. Confidence level (C = confirmed, S = suspected)				<u>C</u>
<ol> <li>Easard rating (E = bigh, N = medium, L = low)</li> </ol>				<u>H</u>
Factor Subscore A (from 20 to 100 bases	d on factor (	core matrix)		100
B. Apply persistence factor Pactor Subscore A X Persistance Pastor - Subscore B				
<u> </u>		30		
C. Apply physical state multiplier				
Subscore S X Physical State Multiplier - Weste Charact	teristics But	ecore		
80 x 1.0	• _ 8	30		

_	۸	Ŧ	м	W	A	N	2	

Rating Pactor	Rating (0-3)	'Multiplier	Factor Score	Possible Score
If there is evidence of migration of hazardor direct evidence or 80 points for indirect evi- evidence or indirect evidence exists, process	idence. If direct evi	n makisum fac dence exists	tor subscore ( then proceed	of 100 point to C. If no
			Subscore	100
Nate the migration potential for 3 potential migration. Select the highest rating, and processing the second secon	pathweys: surface we roceed to C.	ter migration	, flooding, a	nd ground-wa
1. Burface vater migration	1 . 1	_ 1		
Distance to mearest surface water	3	•	24	24
Net precipitation	2		12	18
Surface erosion	0		0	24
Surface permeability	0		0	18
Reinfall intensity	2		16	24
		Subtotal	52	_108_
Subscore (100 I	factor score subtotal	/maximum scor	e subtotal)	48
2. Flooding	0	1	0	3
	Subscore (100 x f	actor score/3	)	0
3. Ground-water migration				
Depth to ground water	2		16	24
Net precipitation	2	6	12	18
Soil permeability	3		24	24
Subsurface flove	1		8	24
Direct access to ground water	3		24	24
		Subtotal	<b>8</b> 4	114
Subscore (100 x	: factor score subtotal	Anaximum acor	e subtotal)	74
Eighest pathway subscore.		•		
Enter the highest subscore value from A, 2-1	, 8-2 or 8-3 above.	Pathwa	As gapacote	100
/. WASTE MANAGEMENT PRACTICES	· · · · · · · · · · · · · · · · · · ·			
Average the three subscores for receptors, w		and pathwave.		
	MARCH GRANTESTELLISETES.			
	- · ·			70
	Receptors Waste Characteristi Pathweys	• • • • • • • • • • • • • • • • • • • •		
	Receptors Waste Characteristi Pethweye	• • • •	a Gro	-80
. Apply factor for waste containment from wast	Receptors Waste Characteristi Pethweye Total 258	cs divided by 3	• Gro	-80
. Apply factor for waste containment from wast Gross Total Score X Waste Management Fractic	Receptors Waste Characteristi Pathways Total 258	cs divided by 3	e Geo	-80

Open Waste Storage Area # 42 - S				
CATION Willow Grove ARE, near northern	boundary	·		
TE OF OFFRATION OR OCCUPATION   1958				
Willow Grove ARF Base Supply	<u> </u>		J. 7 1	
MCDFTS/DESCRIPTION   Uncontained open storage area   Waste of waste of			<u>a leaks o</u>	<u> </u>
na ste or Maste or	is and so	IVERLS		
RECEPTORS	Testos			Maximum
Rating Pactor	Reting (0-3)	Multiplier	<b>Fector</b> Score	Possible Score
Population within 1,000 feet of site	3	4	12	12
Distance to nearest well	3	10	30	30
	3			
Land use/soning within ! mile radius		3	9	9
Distance to reservation boundary	3		18	18
Critical environments within 1 mile radius of site	2	10	20	30 .
Water quality of nearest surface veter body	1_1_	6	6	18
Ground weter use of appearant squifer	3	,	27	27
Population served by surface veter supply		}	· -	
within 3 miles downstream of site	0	•	0	18
Population served by ground-water supply within 1 miles of site	3		18	18
VICEAR / SILLER OF SILLE				
		Subtotals		180
Receptors subscore (100 % Easter ec	eore subtotal	L/maximum score	subtotal)	<u>78</u>
WASTE CHARACTERISTICS				
Select the factor accre based on the estimated quantity the information.	ry, the degre	ee of hesard, a	nd the conf	idence level
1. Waste quantity (S = small, $M$ = medium, $L$ = large)				
2. Confidence level (C = confirmed, S = suspected)				<u> </u>
3. Hesard rating (H = high, H = medium, L = low)				<u>M</u>
Partor Subscore A (from 20 to 100 based	on factor	score satrix)		80
. Apply persistence factor Factor Subscore & I Persistence Pactor - Subscore B				
<u>80 x 1.0</u>	•_	80		
Apply physical state multiplier				
Subscore B X Physical State Multiplier - Waste Charact	Partestes Sul	harora	•	

# EL PATHWAYS

_	Rati	ng Pactor	Pactor Rating (0-3)	'Multiplier	Factor Score	Naximum Possible Score
٨.	dir	there is evidence of migration of basardou est evidence or 80 points for indirect evi- dence or indirect evidence exists, proceed	dense. If direct ev	pn makinum facto idençe exists th	r subscore o en proceed t	of 100 points for to C. If no
					Sapacote	80
<b>3.</b>	Rat	e the migration potential for 3 potential ration. Select the highest rating, and pr	pathways: surface w coool to C.	ster migration,	flooding, an	d ground-water
	1.	Surface voter migration				
		Distance to mearest surface veter	3		24	24
		Not precipitation	2		12	18
		Surface erosion	0		0	24
		Surface permeability	1	6	6	18
		Rainfall intensity	2	•	16	24
				Subtotals	58	108
		Pubecece (100 I	factor score subtota	l/meximum score	subtotal)	54
	2.	Flooding	0		0	3
			Subscore (100 x	factor score/3)		0
	3.	Ground-water migration				
		Depth to ground water	2	• 1	16	24
		Net precipitation	2	6	12	18
		Soil permeability	2		16	24
		Subsurface flows	0		0	24
		Direct access to ground water	0		0	24
				Subtotals	44	114
		Subsecte (160 x	factor score subtota	1/navimum acore	subtotal)	39
c.	Hic	thest pathway subscore.				
-	Ī	the highest subscore value from $A_r$ $B-1$ ,	Bol or Bol shove.			
			0-1 4 1-1 40101	Sachunan	Subscore	80
				remseye		==
ī	. w	ASTE MANAGEMENT PRACTICES	<u></u>			
		orage the three subscores for receptors, we		and mash		
~•	~~	riage car curer supecotes for receptors, we		and pechways.		70
			Noceptors Maste Characterist Pethweys	ics		80 80
			70tal 238	divided by 3	e Gros	79 Total Score
۵.	λpį	ply factor for weste containment from waste	menagement practice	•		
	Œ	oss Total Score X Weste Memagement Practice	s Pactor - Pinel Soc	£0		
		,	79	x 1.0	•	79
			E-4	~ ~		<u> </u>

Ponding Basin - Site No. 3  CATTON Willow Grove ARE near northern bo	undary			<del></del>
ATE OF OFFERATION OR OCCURRENCE 1958 - Present				
MER/OPERATOR Willow Grove NAS - Public Works				
OMERITS/DESCRIPTION Unlined Storm runoff retention				RF
ALD and part of NAS:	presense o	f oily seep	s	
RECEPTORS	Pactor			Mariana
Rating Factor	Rating (0-3)	Multiplier	Fector Score	Possible
Population within 1,000 feet of site	3	4	12	12
. Distance to nearest well	3	10	30	30
Land use/soning within 1 mile radius	3	3	9	9
. Distance to reservation boundary	3		18	18
. Critical environments within 1 Bile radius of site	2	10	20	30
. Water quality of nearest surface water body	1	6	6	18
. Ground weter use of uppermost aquifer	3	. 9	27	27
. Population served by surface water supply within 3 miles downstreem of site	0	6	0	18
. Population served by ground-water supply				
within 3 miles of site	] 3		18	18
		Subtotals	140	180
Receptors subscore (100 % factor so	ore subtotal	/maximum score	subtotal)	78
L WASTE CHARACTERISTICS				
. Select the factor score based on the estimated quantity the information.	y, the degre	e of heserd, a	ed the confi	dence level
1. Waste quantity (S = small, H = medium, L = large)				_\$_
2. Confidence level (C = confirmed, 8 = suspected)				
). Easard rating (E = high, H = medium, L = low)				
Factor Subscore A (from 20 to 100 based	on factor s	core matrixi		40
. Apply persistence factor				
Pactor Subscore A I Persistence Pactor - Subscore B				
40 x 0.80		32		
. Apply physical state sultiplies				
Subscore B X Physical State Multiplier - Waste Charact	eristics Sub	9000 e		

_	_	•	-				V	
-		-	ш	п	77	А	M	8

1	Rati:	ng Pactor	Pactor Rating (0-3)	'Multiplier	Tactor Score	Maximum Possible Score
٠.	dire	there is evidence of migration of basardous or out evidence or 80 points for indirect evidence lenge or indirect evidence exists, proceed to	00. If direct ev	gn mekisus fac idence exists	tor subscore then proceed	of 100 points for to C. If no
					Subscore	100
<b>.</b>	Rate	n the migration potential for 3 potential pateration. Select the highest rating, and process	tweys: surface w of to C.	eter migration	, flooding, a	nd ground-water
	1.	Surface water migration				
		Distance to mearest surface water	3		24	24
		Net precipitation	2	. 6	12	18
		Surface erosion	1		8	24
		Surface permeability	1	6	6	18
		Rainfall intensity	2		16	24
		•		Subtotal	66	108
		Subscere (100 X fact	tor score subtota	l/maximum score	subtotal)	61
	2.	Flooding	3	<u> </u>	3	3
		•	Subscore (190 x	factor score/3	)	_100
	3.	Ground-water migration		ı •		
		Depth to ground water	3		24	24
		Het precipitation	2		12	18
		Soil permeability	2	. 8	16	24
		Subsurface flove	3	-	24	24
		Direct access to ground water	3		24	24
				Subtotal	100	114
		Subscore (100 x fac	tor score subtota	l/maximum ecor	e subtotal)	88
c.	Eig	hest pathway subscore.				
	Ent	or the highest subscore value from $\lambda$ , 3-1, 3-	2 oc 3-3 above.			100
				Pathwa	As ampacote	===
IV.	W	ASTE MANAGEMENT PRACTICES				<del></del>
A.	Ave	rage the three subscores for receptors, waste	characteristics.	and pathways.		•
			oceptors	•		78
		•	este Cherecterist Ethweye	ica		32 100
		•	210 etal	divided by 3	• @:	70
3.	λφφ	ly factor for waste containment from waste may	nagement practice	•		
	Œ	se Total Score I Waste Hanagement Practices Fr	actor - Pinal Sco	E Q		
			70	_ x	1.0_•	70
			E-6			

	facility			
ATE OF OPERATION OR OCCURRENCE 1958 - Present				
MER/COMMATCE Willow Grove ARE				
Discharge of wash rack water strippers oils				
strippers, oils filter.	T to deoned	water via u	lilbed Irl	CKIING
RECEPTORS	Pactor			Haximus
Rating Factor	Rating (0-3)	Multiplier	Tactor Score	Possible Score
Population within 1,000 feet of site	3	4	12	12
. Distance to nearest well	3	10	30	30
. Lend use/soning within 1 mile radius	3	3	9	9
. Distance to reservation boundary	3	6	18	18
. Critical environments within 1 mile radius of site	2	10	20	30
	1	6	6	18
. Water quality of nearest surface vater body	3		27	27
Ground weter use of uppermost aquifer		<u> </u>	21	21
I. Population served by surface veter supply vithin I miles downstream of site	0	6	0	18
. Population served by ground-water supply				
within 3 miles of site	3 1	6	_18	18
		Subtotals	140	1 <u>80</u>
Receptors subecore (100 % factor (	score subtotel	/maximum score	subtotal)	<u>78</u>
L WASTE CHARACTERISTICS				
. Select the factor score based on the estimated quantities information.	ity, the degre	e of basard, a	and the confi	dence level
		e of hasard, a	and the confi	dence level
the information.		e of hazard, a	nd the confi	dence level
the information.  1. Waste quantity (S = small, H = sedium, L = large)		e of basard, a	and the confi	M C M
the information.  1. Waste quantity (S = small, H = medium, L = large  2. Confidence level (C = confirmed, S = suspected)  3. Easard rating (E = high, H = medium, L = low)	<b>)</b>		and the confi	<u>М</u>
the information.  1. Waste quentity (S = small, H = sedium, L = large)  2. Confidence level (C = confirmed, S = suspected)	<b>)</b>		nd the confi	<u>М</u> С
the information.  1. Waste quantity (S = small, H = medium, L = large)  2. Confidence level (C = confirmed, S = suspected)  3. Essard rating (E = high, H = medium, L = low)  Factor Subscore A (from 28 to 100 base)	<b>)</b>		nd the confi	<u>М</u>
the information.  1. Waste quantity (S = small, H = sedium, L = large)  2. Confidence level (C = confirmed, S = suspected)  3. Easard rating (E = high, H = sedium, L = low)  Factor Subscore A (from 20 to 100 base)  3. Apply persistence factor	) ed on factor s	COTE BATTIE)	and the confi	<u>М</u>
the information.  1. Waste quantity (\$ = small, H = sedium, L = large  2. Confidence level (C = confirmed, S = suspected)  3. Easard rating (E = high, H = sedium, L = low)  Factor Subscore A (from 20 to 100 base).  Apply persistence factor Factor Subscore A X Persistence Factor = Subscore B  60 x 1.0	) ed on factor s	COTE BATTIE)	nd the confi	<u>М</u>
the information.  1. Waste quantity (S = small, H = sedium, L = large)  2. Confidence level (C = confirmed, S = suspected)  3. Easard rating (E = high, H = sedium, L = low)  Factor Subscore A (from 20 to 100 base)  8. Apply persistence factor Factor Subscore A X Persistence Factor = Subscore B	ed on factor s	core metrix)	and the confi	<u>М</u>

_	-	-	20.04	 ve
			M	14

	Rati:	ng Pactor	Pactor Rating (0-3)	'Multiplier	Factor Score	Neximum Possible Score
λ.	dir	there is evidence of migration of hazardous set evidence or 80 points for indirect evide lence or indirect evidence exists, proceed t	nce. If direct evi	yn makisum facts idence exists ti	or subscore	of 100 points f to C. If no
					Subscore	80
3.		n the migration potential for 3 potential paration. Select the highest rating, and proc		ater migration,	flooding, (	ind ground-veter
	1.	Surface water migration		•		•
		Distance to mearest surface veter	3	-	24	24
		Not procipitation	2	- 6	12	18
		Surface erosion	0		0	24
		Surface permeability	1		6 .	18
		Reinfell intensity	2	•	16	24
				Subtotals	58	108
		Subscere (100 X &	ator score subtota	l/meximum score	subtotal)	54
	2.	Flooding	L o 1	1	. 0	3
			Subagoce (100 x	factor acore/3)		0
	3.	Ground-water migration				<del></del>
		Depth to ground water	3		24	24
			2	6	12	18
		Net precipitation	2		16	24
		Soil perseability	2		16	24
		Subsurface flove	2	8	16	24
		Direct access to ground water			84	114
				Subtotals		71
		Subscore (100 x fa	octor ecore subtota	l/maximum ecore	subtotal)	<del></del>
c.	E14	hest pathway subscore.				
	Ent	er the highest subscore value from $\lambda$ , 3-1, 1	1-1 or 3-3 ebove.			
				Pathway	s Subscore	80
_			<del></del>			
IV	. W	aste management practices				
A.	Ave	rage the three subscores for receptors, was	to characteristics,	and pathways.		•
			Receptors Waste Characterist Pathways	ics		78 50 80
			Total 218	divided by 3	•	73
3.	λμι	My fastor for waste containment from waste :	Management practice	•	GZ C	oss Total Score
	•	nes Total Score I Wasto Management Proctices				
			73	x0.95	•	69

www. or sits Building 330 Waste Oil Storage Are	ea - Site M	lo. 5		
LOCATION Willow Grove ARE near southeast	ooundary			
DATE OF OPERATION OR OCCURRENCE 1970-1980				
OMER/OPERATOR PA. ANG		oufillian o		
COMMENTS/DESCRIPTION Site used for waste oils in bests make by R. Kane		used contam		<u>e</u>
1. Mile		used Contain	macron	
200000000000000000000000000000000000000				
RECEPTORS	Pactor Rating		Pactor	Maximum Possible
Nating Pactor	(0-3)	Multiplier	Score	Score
Population within 1,000 feet of site	3	•	12	12
. Distance to nearest well	3	10	30	30
. Lend use/soning within 1 mile radius	3	3	9	9
. Distance to reservation boundary	3	6	18	18
. Critical environments within 1 mile radius of site	2	10	20	30
. Water quality of nearest surface water body	1	6	6	18
. Ground water use of uppermost equifer	3	•	27	27
. Population served by surface veter supply				
within 3 miles downstream of site	0	6	0	18
. Population served by ground-veter supply	3	_	10	10
within 3 miles of site		• • • •	18	18
		<u> Subtotal</u> s		180
Receptors Subscore (100 X Esquar s	dore subtotal	L/maximum acore	subtotal)	78
<ol> <li>WASTE CHARACTERISTICS</li> <li>Select the factor spore based on the estimated quantities information.</li> </ol>		ne of hesard, a	nd the confi	dence level
1. Waste quantity (S = small, M = medium, L = large)				<u>_\$</u> _
2. Confidence level (C = confirmed, S = suspected)				<u> </u>
3. Essard rating (E = high, H = medium, L = low)				<u>H</u>
Factor Subscore A (from 20 to 100 base	d on factor :	score matrix)		60
Pactor Subscore & X Persistance Pactor - Subscore &				
60 *0.80		48		
C. Apply physical state multiplier				
Subscore B X Physical State Multiplier - Waste Charac	Iteristics Su	pecote		
48	- 48			

### **EL PATHWAYS**

_	Rati	ng Pactor	Factor Rating (0-3)	'Multiplier	Factor Score	Maximum Possible Score
<b>A.</b>	dir	there is evidence of migration of hazardous out evidence or 80 points for indirect evide dence or indirect evidence exists, proceed t	nce. If direct evi	m makimum factu idence exists ti	or subscore o	of 100 points f to C. If no
					Subscore	80
A. S.	Rati	e the migration potential for 3 potential paration. Select the highest rating, and prod	thways: surface wo	ster migration,	flooding, a	nd ground-water
	1.	Burface water migration				•
		Distance to mearest surface vater	3		24	24
		Met precipitation	2	- 6	12	18
		Surface erosion	0	•	0	24
		Surface permeability	1 1		6	18
		Reinfell intensity	2	•	16	24
		•		Subtotals	58	108
		Subscore (100 X &	ctor score subtotal	L/maximum score	subtotal)	54
	2.	Flooding	0	1	0	
			Subscore (190 x	factor score/3)	-	0
	3.	Ground-water migration		t		
		Depth to ground water	2		16	24
		Net precipitation	2		12	18
		Soil permeability	2		16	24
		Subsurface flows	0		0	24
		Direct access to ground water	0		0	24
				Subtotals	44	114
		12 x 001) ercoadu@	ictor score subtotal	l/maximum score	subtotal)	39
c.		thest pathway subscore.	)-2 or 3-3 above.	Par huav	s Subscore	80
		·	·			
IV	. w	aste management practices				
A.	Ave	orage the three subscores for receptors, wast	e characteristics,	and pathways.		
			Receptors Waste Characterist: Pathweye	ics		78 48 80
			total 206	divided by 3	• @:01	69 Total Score
3.	λρη	ply factor for weste containment from waste m	management practices	3		
	Œro	des Total Score X Weste Management Practices		<del>-</del>		
			69	_ <b>x</b> 1.0		69
			E-10			

Heating Plant - Site No. 6		·		
Willow Grove ARF near center of	facility			
DATE OF OPERATION OR OCCURRENCE 1959 Present DATE OF OPERATOR Outside contractor for USAF				
CONCERTS/CONCERTOR OUTSIDE CONTRACTOR FOR USAF	and miscol	langue for	le colue	<u> </u>
ALD and water softeners:				
L RECEPTORS	Pastor Bating	·	Pactor	Heximum Poseible
Rating Pactor	(0-3)	Multiplier	Score	Score
A. Population within 1,000 feet of site	3	4	12	12
. Distance to nearest well	3	10	30	30
C. Lend use/soning within 1 mile redius	3	3	9	9
D. Distance to reservation boundary	3	6	18	18
E. Critical environments within 1 mile radius of eite	2	10	20	30
P. Water quality of nearest surface water body	1	6	6	18
C. Ground weter use of uppermost equifer	3		27	27
E. Population served by surface water supply within 3 miles downstream of site	0	6	0	18
I. Population served by ground-water supply within 3 miles of site	3	6	18	18
		Subtotals	140	180
Receptors subecore (100 % factor a	core subtotal	/narinum score	subtotal)	<u>78</u>
IL WASTE CHARACTERISTICS			•	
A. Select the factor score based on the estimated quanti- the information.	ty, the degre	e of hazard, a	nd the confi	dence level
1. Waste quantity (S = small, H = medium, L = large)				<u>s</u> _
2. Confidence level (C = confirmed, 8 = suspected)				<u> </u>
3. Hazard rating (E = high, H = medium, L = low)				M
Factor Subscore A (from 20 to 100 base	d on factor (	HOTE BATTIX)		50
B. Apply persistence factor Factor Subscore A I Persistence Factor - Subscore B		•		_
<u>50</u> *0,	30 <u> </u>	10		
C. Apply physical state multiplier		<del></del>		
Subscore B X 7bysical State Multiplier - Weste Charac	teristics Su	0.000ce		
40 x 1.0	_	10		
نظيم حصم * محمد نعم محمد المام ا		<u> </u>		

ı		Δ	1	н١	M	T,	Y	Я	
	~	-				~	•	4	۱

The second of th

1	Rating Factor	Rating (0-1)	'Multiplier	Tactor Score	Possible
۱.	If there is evidence of migration of hasardous co- direct evidence or 80 points for indirect evidence evidence or indirect evidence exists, proceed to	e. If direct or	gn sakinus faci		of 100 points for
				Subscore	80
<b>).</b>	Rate the migration potential for 3 potential path migration. Select the highest rating, and proceed		meter migration	, flooding, a	nd ground-water
	1. Surface veter migration	3	ı . I	24	24
	Distance to mearest surface water	2		12	18
	Not procipitation	0	6	0	24
	Surface erosion	1		6	18
	Surface permeability	2	•	16	24
	Reinfall intensity		Subtotal	50	108
	Subscore (100 X fact	er core subtoti			54
	•	1 0	1 , 1	0	3
	2. <u>Flooding</u>	Subscore (190 x	factor sopre/1	· · · · · · · · · · · · · · · · · · ·	0
	1. Ground-water migration			•	
	Depth to ground water	1 2		16	24
		2	6	12	18
	Het precipitation	2		16	24
	Soil permeability Subsurface flows	0		0	24
	Direct access to ground veter	0		0	24
	DITAGE SOCIAL CO ALONIN MALES		Subtotal	44	114
	Subscore (100 x fact	tor soore subtoti			39
c.					
••	Enter the highest subscore value from A. S-1, S-	or tel shows.			
	THESE GIG STANDAGE STOROGOES ANTIN TIME W. 2-11 2-1		Bachun	ys Subscore	80
			74,000	,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
_ N	/. WASTE MANAGEMENT PRACTICES	<u> </u>			
	Average the three subscores for receptors, waste	ebarastari eti ce	. and nothware.		
~•	•	acestacs	, and becausely.		78
	W	este Charesteris ethusys	ties		<del>40</del> 80
	2	198	divided by 3	• Gro	66 Total Score
<b>B.</b>	Apply factor for weste containment from waste man	nagement practic	••		
	Gross Total Score I Meste Henogement Proctices 7	actor - Pinel So	010		
		66	<u> </u>		66
		_ 4 4			

wave or size 01d well house - Site No. 7		·		
Willow Grove ARE northern bounda	ry corner			
DATE OF CHEATION OR OCCURRENCE 1962 - Present				
Willow Grove ARF. Civil Engineerin				
Paint and paint thinners sto				ing
noising ana	ogonea unb	inggen well		<del></del>
			•	
L RECEPTORS	Pactor			Maximus
Rating Factor	Rating (0-3)	Multiplier	Pactor Score	Possible Score
A. Population within 1,000 feet of site	3	4	12	12
B. Distance to nearest well	3	10	30	30
	3		9	9
C. Lend use/soning within 1 mile radius	3	3		
D. Distance to reservation boundary			18	18
E. Critical environments within 1 mile radius of site	2	10	20	30
P. Water quality of nearest surface water body	1		6	18
G. Ground weter use of uppermost aquifer	3	•	27	27
E. Population served by surface vater supply within 3 miles downstream of site	0	66	0	18
1. Population served by ground-water supply within 3 miles of site	3	6	18	18
		Subtotals	140	180
Receptors subscore (100 % factor of	pore subtotal	/maximum score	subtotal)	78
L WASTE CHARACTERISTICS				
A. Select the factor score based on the estimated quantity the information.	ty, the degre	e of besard, e	nd the confi	idence level
1. Waste quantity (8 - small, H - medium, L - large)				<u>s</u>
2. Confidence level (C = confirmed, S = suspected)				_ <b>S</b>
3. Essard rating (E = high, H = medium, L = low)				М
Pageoc Subscore A (from 20 to 100 based	l on factor :	core matrix)		30
B. Apply persistence factor Factor Subscore A I Persistence Pactor - Subscore B				
<b>30</b> _ <b>z</b> 0.9	•	27		
C. Apply physical state multiplier				
Subscore B X Physical State Multiplier - Waste Charact				
<u>27*1.0</u> _	•	27		

-		•	u	4	<b>A</b> '	Y8
	,	•	•	77	~	19

	Rating Pactor	Rating (0-3)	'Multiplier	Pactor Score	Possible Score		
A.	If there is evidence of migration of basardous direct evidence er 80 points for indirect evidence exists, proceed evidence exists, proceed	ence. If direct ev	gn makisum fact idence exists t	or subscore	of 100 points for to C. If no		
				Subscore	0		
<b>3.</b>	Nate the migration potential for 3 potential punispration. Select the highest rating, and pro-	athways: surface w cood to C.	eter migration,	flooding, a	nd ground-water		
	1. Burface veter signation	3	1 . 1	24	i 24		
	Distance to mearest surface veter	2		24 12	2 <u>4</u> 18		
	Met precipitation	1		8	24		
	Surface erosion	i		6	18		
	Surface permeability	2	•	16	24		
	Rainfell intensity		8	66	108		
	•		Subtotals		61		
	Subscere (100 X &	actor score subtota	l/meximum score				
	2. Flooding	0	11	0	0		
Subscore (190 x Eactor score/3)							
	3. Ground-water migration	•		,			
	Depth to ground water	2		16	24		
	Net precipitation	22	6	12	18		
	Soil permeability	2		16	24		
	Subsurface flows	1		8	24		
	Direct access to ground vater	3		24	24		
			Subtotals	76	114		
_		actor ecore subtota	i/maximum score	subtotal)	67		
c.	• •						
	Enter the highest subscore value from A, B-1,	3-2 or 3-3 above.			67		
			Pethvey	s Subscore	<del>67</del>		
īV.	. WASTE MANAGEMENT PRACTICES	<del> </del>	<del></del>	<del>-</del>			
A.	Average the three subscores for receptors, was	te characteristics,	and pathways.				
Receptors Waste Characteristics Pathways							
		172	divided by 3	e Gros	57 Total Score		
3.	Apply factor for waste containment from waste	management practice	•				
	Gross Total Score I Weste Management Practices	Pactor - Pinel Sco	ge .				
		54	x 1.0		57		




APPENDIX F

**PHOTOGRAPHS** 

## WESTEN!

#### SITE NO. 1 - POL AREA



POL AREA, AERIAL VIEW FROM WEST




POL AREA, AERIAL VIEW FROM SOUTH SHOWING PROXIMITY TO PONDING BASIN

SITE NO. 2 - OPEN STORAGE AREA #42




VIEW FROM WEST SIDE



DRUMS OF WASTE ENGINE OIL AND HYDRAULIC OIL




## SITE NO. 2 - OPEN STORAGE AREA #42 (CONTINUED)



AERIAL VIEW FROM SOUTH



#### SITE NO. 3 - PONDING BASIN




AERIAL VIEW FROM NORTH

W. STEEN

#### SITE NO. 4 - WASHRACK AREA



WASHRACK AREA TREATMENT SYSTEM, VIEWED FROM NORTH




WASHRACK AREA, SOUTH SIDE OF BUILDING # 215

estica (Proceedings) enveloped de la coció




#### SITE NO. 5 - BUILDING #330



WASTE OIL STORAGE AREA SOUTH OF BUILDING #330



## SITE NO. 5 - BUILDING #330 (CONTINUED)



WASTE OIL STORAGE AREA SOUTH OF BUILDING #330 GROUND DISCOLORATION



#### SITE NO. 6 - HEATING PLANT



NO. 6 FUEL OIL SPILL BENEATH TANK #221



#### SITE NO. 6 - HEATING PLANT


(CONTINUED)



CHEMICAL STORAGE OUTSIDE OF BUILDING #212



#### SITE NO. 7 - OLD WELL HOUSE



AERIAL VIEW FROM NORTH



#### APPENDIX G

GLOSSARY OF TERMS AND ABBREVIATIONS



#### APPENDIX G

#### GLOSSARY OF TERMS AND ABBREVIATIONS

ACCUMULATION POINT A designated location for the accumula-

tion of wastes prior to removal from the

installation.

ACFT MAINT Aircraft Maintenance

AF Air Force

AFB Air Force Base

AFESC Air Force Engineering and Services

Center

AFFF Aqueous Film Forming Foam (a fire extin-

quishing agent).

AFR Air Force Regulation

AFRES Air Force Reserve Command

Ag Chemical symbol for silver.

AGE Aerospace Ground Equipment

Al Chemical symbol for aluminum.

ALLUVIUM Materials eroded, transported, and de-

posited by surface water.

ANG Air National Guard

ARTESIAN Groundwater contained under hydrostatic

pressure.

AQUIFER A geologic formation, group of forma-

tions, or part of a formation that is capable of yielding water to a well or

spring.

AROMATIC Organic chemial compounds in which the carbon atoms are arranged into a ring

with special electron stability associated. Aromatic compounds are often

more reactive than nonaromatics.

AVGAS Aviation Gasoline (contains lead).

Ba Chemical symbol for barium.

BIOACCUMULATE Tendency of elements or compounds to ac-

cummulate or buildup in the tissues of living organisms when they are exposed to elements in their environments, e.g.,

heavy metals.

BIODEGRADABLE The characteris ic of a substance to be

broken down from complex to simple com-

pounds by microorganisms.

BOWSER A mobile tank, usually 1,000 gallons or

less in capacity.

BX Base Exchange

CaCO<sub>3</sub> Chemical symbol for calcium carbonate.

Cd Chemical symbol for cadmium.

CE Civil Engineering

CERCLA Comprehensive Environmental Response,

Compensation, and Liability Act

CIRCA About, used to indicate an approximate

date.

CN Chemical symbol for cyanide.

COD Chemical Oxygen Demand, a measure of the

amount of oxygen required to oxidize organic and oxidizable inorganic compounds

in water.

COE Corps of Engineers

## WAS SUBJECT OF THE STATE OF THE

CONFINED AQUIFER An aquifer bounded above and below by

geologic units of distinctly lower permeability than that of the aquifer it-

self.

CONFINING UNIT A geologic unit with low permeability

which restricts the vertical movement

of groundwater.

Cr Chemical symbol for chromium.

Cu Chemical symbol for copper.

2,4-D Abbreviation for 2,4-dichlorophenoxy-

acetic acid, a common weed killer and

defoliant.

DEQPPM Defense Environmental Quality Program

Policy Memorandum

DIP The angle at which a geologic structural

surface is inclined from the horizontal.

DOD Department of Defense

DOT Department of Transportation

DOWNGRADIENT In the direction of decreasing hydraulic

static head; the direction in which

groundwater flows.

DPDO Defense Property Disposal Office

DUMP An uncontrolled land disposal site where

solid and/or liquid wastes are

deposited.

EFFLUENT A liquid waste, untreated or treated,


that discharges into the environment.

EP Extraction Procedure - the EPA standard

laboratory procedure for simulation of

leachate generation.

EPA U.S. Environmental Protection Agency





MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS - 1963 - A

EROSION The wearing away of land surface by

wind, water, or chemical processes.

FAA Federal Aviation Administration

FAULT A fracture in rock along the adjacent

rock surfaces which are differentially

displaced.

Fe. Chemical symbol for iron.

FLOOD PLAIN The low land and relatively flat areas

adjoining inland and coastal areas of the mainland and off-shore islands, including, at a minimum, areas subject to 1 percent or greater chance of flooding

in any given year.

FLOW PATH The direction of movement of groundwater

as governed principally by the hydraulic

gradient.

FMS Field Maintenance Squadron

FPTA Fire Protection Training Area

FY Fiscal Year

GC/MS Gas chromatograph/mass spectrophotom-

eter, an analytical instrument for qualitative and quantitative measurement of organic compounds having a maximum mol-

ecular weight of 800.

GROUNDWATER Water beneath the land surface in the

saturated zone that is under atmospheric

or artesian pressure.

GROUNDWATER RESERVOIR The earth materials and the intervening

open spaces that contain groundwater.

HALON A fluorocarbon fire extinguishing com-

pound.

HALOGEN The class of chemical elements includ-

ing fluorine, chlorine, bromine, and

iodine.

## WESTERN .

HARM

Hazard Assessment Rating Methodology

HAZARDOUS SUBSTANCE

Under CERCLA, the definition of hazardous substance includes:

- All substances regulated under Paragraphs 311 and 307 of the Clean Water Act (except oil).
- All substances regulated under Paragraph 3001 of the Solid Waste Disposal Act.
- All substances regulated under Paragraph 112 of the Clean Air Act.
- All substances which the Administrator of EPA has acted against under Paragraph 7 of the Toxic Substance Control Act.
- Additional substances designated under Paragraph 102 of the Superfund Bill.

HAZARDOUS WASTE

As defined in RCRA, a solid waste, or combination of solid wastes, which because of its quantity, concentration, or physical/chemical, or infectious characteristics may cause or significantly contribute to an increase in mortality or an increase in serious, irreversible, or incapacitating reversible illness; or pose a substantial present or potential hazard to human health or the environment when improperly treated, stored, transported, or disposed of, or otherwise managed.

HAZARDOUS WASTE GENERATION

The act or process of producing a hazardous waste.

**HEAVY METALS** 

Metallic elements, including the transition series, which include many elements required for plant and animal nutrition in trace concentrations but which become toxic at higher concentrations.

Hg Chemical symbol for mercury

HQ Headquarters

**HYDROCARBONS** Organic chemical compounds composed of

hydrogen and carbon atoms chemically bonded. Hydrocarbons may be straight chain, cylic, branched chain, aromatic, or polycyclic, depending upon arrangement of carbon atoms. Halogenated hydrocarbons are hydrocarbons in which one or more hydrogen atoms has been replaced by

a halogen atom.

INFILTRATION The movement of water across the atmos-

phere-soil interface.

IRP Installation Restoration Program

**ISOPACH** Graphic presentation of geologic data,

including lines of equal unit thickness that may be based on confirmed (drill hole) data or indirect geophysical meas-

urement.

JP-4 Jet Propulsion Fuel (unleaded) No.

military jet fuel.

LEACHATE A solution resulting from the separation

> or dissolving of soluble or particulate constituents from solid waste or other man-placed medium by percolation of

water.

LITHOLOGY The description of the physical charac-

ter of a rock.

LOESS An essentially unconsolidated unstrati-

fied calcareous silt; commonly homogeneous, permeable, and buff to gray in color.

LYSIMETER A vacuum operated sampling device used

for extracting pore waters at various

depths within the unsaturated zone.

#### WESTERN .

MEK. Methyl Ethyl Ketone

METALS See "Heavy Metals".

MGD Million gallons per day.

MOA Military Operating Area

MIK Methyl Isobutyl Ketone

MOGAS Motor Gasoline

Mn Chemical symbol for manganese.

MONITORING WELL A well used to obtain groundwater sam-

ples and to measure groundwater eleva-

tion

MSL Mean Sea Level

NDI Nondestructive inspection.

NET PRECIPITATION The amount of annual precipitation minus

annual evaporation.

Ni Chemical symbol for nickel.

NOAA National Oceanic and Atmospheric Admin-

istration

NPDES National Pollutant Discharge Elimination

System

OEHL Occupational and Environmental Health

Laboratory

OIC Officer-In-Charge

ORGANIC Being, containing, or relating to carbon

compounds, especially in which hydrocar-

bon is attached to carbon.

OSI Office of Special Investigations

O&G Symbols for oil and grease.

Pb Chemical symbol for lead.

PCB Polychlorinated Biphenyl - liquids used

as a dielectrics in electrical equip-

ment.

PCE Tetrachloroethylene

PERCOLATION Movement of moisture by gravity or

hydrostatic pressure through inter-

stices of unsaturated rock or soil.

PERMEABILITY The capacity of a porous rock, soil, or

sediment for transmitting a fluid.

PERSISTENCE As applied to chemicals, those which are

very stable and remain in the environment in their original form for an ex-

tended period of time.

PD-680 Kerosene-based cleaning solvent

pH Negative logarithm of hydrogen ion con-

centration.

PL Public Law

POL Petroleum, Oils, and Lubricants

POLLUTANT Any introduced gas, liquid, or solid

that makes a resource unit for a specif-

ic purpose.

POLYCYCLIC COMPOUND All compounds in which carbon atoms are

arranged into two or more rings, usually

in nature.

POTENTIOMETRIC SURFACE The surface to which water in an aquifer

would rise in tightly cased wells open

to the aquifer.

PPB Parts per billion by weight.

PPM Parts per million by weight.

PRECIPITATION Rainfall.

QUATERNARY MATERIALS The second period of the Cenozoic

geologic era, following the Tertiary, and including the last 2 to 3 million

years.

RCRA Resource Conservation and Recovery Act

of 1976

RECEPTORS The potential impact group or resource

for a waste contamination source.

RECHARGE AREA A surface area in which surface water

or precipitation percolates through the unsaturated zone and eventually reaches

the zone of saturation.

RECHARGE The addition of water to the groundwater

system by natural or artificial process-

es.

RIPARIAN Living or located on a riverbank.

SANITARY LANDFILL A site using an engineered method of

disposing solid wastes on land.

SATURATED ZONE Soil or geologic materials in which all

voids are filled with water.

SAX's TOXICITY A rating method for evaluating the tox-

icity of chemical materials.

SCS U.S. Department of Agriculture Soil Con-

servation Service

SOLID WASTE Any garbage, refuse, or sludge from a

waste treatment plant, water supply treatment, or air pollution control facility, and other discarded material, including solid, liquid, semi-solid, or contained gaseous material resulting from industrial, commercial, mining, or agricultural operations and from community activities, but does not include solid or dissolved materials in domestic

sewage; solid or dissolved materials in irrigation return flows; industrial discharges which are point source subject to permits under Section 402 of the Federal Water Pollution control Act, as amended (86 USC 880); or source, special nuclear, or by-product material as defined by the Atomic Energy Act of 1954 (68 USC 923).

SPILL Any unplanned release or discharge of a

material onto or into the air, land, or

water.

STORAGE OF HAZARDOUS

WASTE

スの表記できるからで、<br />
■ななののない<br />
■ななののない<br />
■ななるのでは<br />
■なるのでは<br />
■

Containment, either on a temporary basis or for a longer period, in such manner as not to constitute permanent disposal

of such hazardous waste.

STP Sewage Treatment Plant

2,4,5-T . Abbreviation for 2,4,5-trichlorophen-

oxyacetic acid, a common herbicide.

TAG Tactical Airlift Group

TCE Trichloroethylene

TDS Total Dissolved Solids

TOC Total Organic Carbon

TOXICITY The ability of a material to produce in-

jury or disease upon exposure, ingestion, inhalation, or assimilation by a

living organism.

TRANSMISSIVITY The rate at which water is transmitted

through a unit width of aquifer under a

hydraulic gradient.

## WESTERN .

TREATMENT OF HAZARDOUS

WASTE

Any method, technique, or process including neutralization designed to change the phsyical, chemical, or biological character or composition of any hazardous waste so as to neutralize the waste or so as to render the waste nonhazardous.

TSD

Treatment, storage, or disposal.

TSDF

Treatment, storage, or disposal facil-

ity.

UPGRADIENT

In the direction of increasing hydraulic static head; the direction from which

groundwater flows.

USAF .

United States Air Force

USDA

United States Department of Agriculture

USFWS

United States Fish and Wildlife Service

USGS

United States Geological Survey

WANG

Wisconsin Air National Guard

WATER TABLE

Surface of a body of unconfined groundwater at which the pressure is equal to

that of the atmosphere.

WWTP

Wastewater Treatment Plant

zn

Chemical symbol for zinc



APPENDIX H

REFERENCES



#### **BIBLIOGRAPY**

- Council on Environmental Quality, 1981, Contamination of Groundwater by Toxic Organic Chemicals. U.S. Government Printing Office, Washington, DC, 84 p.
- National Oceanic and Atmospheric Administration, U.S. Department of Commerce, 1974, Climates of the States, Volume I Eastern States Plus Puerto Rico and the U.S. Virgin Islands. Water Information Center, Inc., Port Washington, New York.
- Newport, T.G., 1971, <u>Groundwater Resources of Montgomery County</u>, <u>Pennsylvania</u>. Pennsylvania Geological Survey, 4th Sec., Water Resources Report 29, 83 p.
- Pennsylvania Department of Environmental Resources, 1980, <u>Title 25</u>
  Rules and Regulations, Part I Department of Environmental
  Resources. Pennsylvania Department of Environmental
  Resources, Harrisburg, Pennsylvania.
- REWAI (R. E. Wright Associates, Inc.), 1982, <u>Special Groundwater</u>
  <u>Study of the Middle Delaware River Basin, Study Area II.</u>
  <u>Delaware River Basin Commission Report, 4 Volumes.</u>
- Rima, Donald R., Harold Meisler and Stanley Longwell, 1962, <u>Geology and Hydrology of the Stockton Formation in</u> <u>Southeastern Pennsylvania</u>. Pennsylvania Geological Survey Bulletin W14, 46 p.
- Ruffner, James A., and Frank E. Bair, 1977, The Weather Almanac.
  Avon Books, New York, New York.
- Sloto, Ronald A., and Drew K. Davis, 1983, Effect of Urbanization on the Water Resources of Warminster Township, Bucks County, Pennsylvania. U.S. Geological Survey Water Resources Investigations, 82-4020, 72 p.
- U.S. Department of Agriculture, Soil Conservation Service, 1967, Soil Survey Montgomery County, Pennsylvania. U.S. Government Printing Office, Washington, DC.
- U.S. Department of Housing and Urban Development, Federal Insurance Administration, 1977, Flood Insurance Study, Township of Horsham, Pennsylvania. U.S. Department of Housing and Urban Development, 21 p.

# END

## FILMED

1-85

DTIC